

Submit 1 Copy To Appropriate District Office
 District I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 1301 W. Grand Ave., Artesia, NM 88210
 District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

RECEIVED
 FEB 22 2010
HOBSOCD

State of New Mexico
 Energy, Minerals and Natural Resources
OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

Form C-103
 October 13, 2009

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-005-20953 ✓
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input checked="" type="checkbox"/>
2. Name of Operator CFM Oil		6. State Oil & Gas Lease No.
3. Address of Operator P.O. Box 1176 Artesia, NM 88211		7. Lease Name or Unit Agreement Name Gulf Kimmons ✓
4. Well Location Unit Letter A : 660 feet from the N line and 660 feet from the E line Section 19 Township 8S Range 31E NMPM County Chaves ✓		8. Well Number #2 ✓ 9. OGRID Number 3322 ✓
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		10. Pool name or Wildcat San Andres

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPL <input type="checkbox"/> DOWNHOLE COMMINGLE <input type="checkbox"/>		SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> P AND A <input checked="" type="checkbox"/> CASING/CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

See attached

Approved for plugging of well bore only.
 Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmnr.state.nm.us/oed.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Leslie Falton TITLE owner DATE _____
 Type or print name Leslie Falton E-mail address: lesliefalton@msn.com PHONE: 575-746-3099
For State Use Only

APPROVED BY [Signature] TITLE REPRESENTATIVE/STAFF MANAGER DATE 2-23-10
 Conditions of Approval (if any): _____

Company: CFM OIL COMPANY
Lease: KIMMOMS #2
Project: P & A
ATTN: LOUIS FULTON

FAX:
E-mail:
PUSHER -
BID =
INV # 09-6060-5

11/6/2009 13 HRS
SAFETY MEETING - MOVE IN RIG UP - POH WITH RODS - SDFD

11/7/2009 12 HRS
SAFETY MEETING - ND WELLHEAD - NU BOP - POH WITH TUBING - SDFD

11/9/2009 12 HRS
SAFETY MEETING - RIH WITH CIBP SET DOWN @ 808' - POH - RIH WITH NOTCHED COLLAR - DRILL
DOWN TO 3350' - POH - RIH AND SET CIBP @ 3350' - POH - RIH WITH TUBING AND CIRCULATE
PLUGGING MUD - SDFD

8	Double derrick rig with 4 man work crew/hr	\$250.00	\$2,000.00
1	NOTCHED COLLAR	\$45.00	N/C

11/10/2009 13 HRS
SAFETY MEETING - SPOT 25 SACKS ON TOP OF CIBP - POH - ND WELL HEAD - PULL STRETCH ON
CASING - RIH AND CUT CASING @ 1550' - POH WITH CASING - RIH WITH TUBING - SDFD

11/11/2009 0 HRS
SAFETY MEETING - SPOT 35 SACKS @ 1612' - POH - WOC - RIH AND TAG @ 1438' - POH - RIH AND SPOT
45 SACKS WITH 2% CACL2 @ 1271' - POH - WOC - RIH AND TAG @ 1257' - RE-SPOT 45 SACKS - POH -
WOC - SDFD

4	Double derrick rig with 4 man work crew/hr	\$250.00	\$1,000.00
45	Cement per sack (CLASS C)	\$14.75	\$663.75

11/12/2009

12 HRS

SAFETY MEETING - RIH AND TAG @ 1108' - POH - SPOT 35 SACKS @ 900' - POH - SPOT 15 SACKS FROM
80' TO SURFACE - CUT OFF WELL HEAD - INSTALL PA MARKER - LEVEL LOCATION - MOVE OUT