

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-8447	
7. Unit Agreement Name	
8. Farm or Lease Name Gulf State	
9. Well No. 1	
10. Field and Pool, or Wildcat Inbe Permo Penn	
12. County Lea	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL GAS WELL OTHER

2. Name of Operator
A. F. Roberts, Jr.

3. Address of Operator
c/o Oil Reports & Gas Services, Inc., Box 763, Hobbs, New Mexico

4. Location of Well
UNIT LETTER **A** **660** FEET FROM THE **North** LINE AND **660** FEET FROM
THE **East** LINE, SECTION **18** TOWNSHIP **11 S** RANGE **34 E** N.M.P.M.

15. Elevation (Show whether DF, RT, GR, etc.)
4205

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is proposed to plug and abandonment as follows:
Set cast iron bridge plug @ 9700 & cap with 35' cement
Cut & pull 4 1/2" casing from approximately 8000
100' plug across 4 1/2" casing stub
100' plug at top of Abo at 7687
100' plug at top of Glorieta at 5412
100' plug across 8 5/8" casing shoe at 4021
Cut & pull 8 5/8" casing from approximately 1500'
(Note: top of Salt at 2085, base of Salt at 2440; if 8 5/8 casing
pulled from below these points a 100' plug at top of Salt and a
100' plug at base of Salt)
100' plug across 8 5/8" casing stub
100' plug across 13 3/8" casing shoe at 415'
10 sack plug at surface with regulation marker
9.5# mud between all plugs

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Walter Haller TITLE Agent DATE 1/19/73

APPROVED BY Joe D. Ramey TITLE Dist. L. Supy. DATE JAN 20 1973

CONDITIONS OF APPROVAL: