

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State  Fee   
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>TEXAS PACIFIC OIL CO., INC.</b>	8. Farm or Lease Name <b>STATE "AC"</b>
3. Address of Operator <b>P. O. Box 1069 - Hobbs, New Mexico 88240</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>N</b> , <b>660</b> FEET FROM THE <b>South</b> LINE AND <b>1980</b> FEET FROM THE <b>West</b> LINE, SECTION <b>15</b> TOWNSHIP <b>10-S</b> RANGE <b>36-E</b> NMPM.	10. Field and Pool, or Wildcat <b>So. Crossroads Devonian</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4018.30' GR</b>	12. County <b>Lea</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Rigged up, pulled tubing, pump and packer.
- Ran CIBP @ 12,000'. Dumped 35' cement plug on top.
- Displaced well fluids w/mud laden 10# brine. Pulled tubing.
- Shot off 7" casing @ 4475'. Spot 50 sk plug @ 4513', and 4321'.
- Shot off 9-5/8" casing @ 985'. Spot 70 sk plug @ 1021', and 392'.
- Spot 10 sk cement plug at surface and installed dry hole marker.
- Cleaned location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Original Signed by L.A. Wright TITLE Area Superintendent DATE 8-17-73

APPROVED BY John W. Remyan TITLE Geologist DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: