

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Department of Minerals and Natural Resources

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-025-22272

5. Indicate Type of Lease
STATE FEE

6. State Oil & Gas Lease No.
K 4280

7. Lease Name or Unit Agreement Name

Warren 27 State

8. Well No.
1

9. Pool name or Wildcat Permian
Bagley N. (Wolfcamp)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL GAS WELL OTHER

2. Name of Operator
Tom Brown, Inc.

3. Address of Operator
P. O. Box 2608, Midland, Texas 79702

4. Well Location
Unit Letter L : 1980 Feet From The south Line and 510 Feet From The west Line
Section 27 Township 11 S Range 33 E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
4249' GR 4259' DF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

09/27/89 MIRU PU. TOH with rods & pump. RU WL TIH & set CIBP at 8340'. Capped with 10 sx cmt. Shot 5 1/2" csg at 5200', 4793', 4587'. TOH with 5 1/2" csg. TIH with tbg & spotted 25 sx cmt at 5250'. Pulled up and spotted 40 sx cmt at 4640'. Tagged TOC at 4480'. Pulled up and spotted 40 sx cmt at 3810'. Tagged TOC at 3696'. TIH & shot csg at 794'. TOH & laid down 8 5/8" csg. TIH & spotted 65 sx cmt at 844'. Tagged TOC at 730'. Pulled up tbg and spotted 65 sx cmt at 400'. Tagged TOC at 338'. Spotted second 50 sx plug. Tagged TOC at 233'. Pulled up tbg & spotted 10 sx cmt at surface.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.
SIGNATURE Steve L. Thomas TITLE Vice President Operations DATE 10/24/89
TYPE OR PRINT NAME _____ TELEPHONE NO. _____

(This space for State Use)
APPROVED BY Jack Griffin TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

OIL & GAS INSPECTOR
NOV 16 1989

RECEIVED

OCT 27 1989

OCD
HOBBS OFFICE