

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

HOBBS OFFICE O. C. C.  
 NEW MEXICO OIL CONSERVATION COMMISSION  
 MAR 22 1 13 PM '66

Form C-103  
 Supersedes Old  
 C-102 and C-103  
 Effective 1-1-65

5a. Indicate Type of Lease  
 State  Fee   
 5. State Oil & Gas Lease No.  
**E-10047**

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>Sunray Oil Company</b>	8. Farm or Lease Name <b>N. M. State "AY"</b>
3. Address of Operator <b>P. O. Box 1116 - Roswell, New Mexico</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>B</b> , <b>990</b> FEET FROM THE <b>N</b> LINE AND <b>2310</b> FEET FROM THE <b>E</b> LINE, SECTION <b>36</b> TOWNSHIP <b>7S</b> RANGE <b>35E</b> NMPM.	10. Field and Pool, or Wildcat <b>Todd San Andres</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4169 DF</b>	12. County <b>Roosevelt</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
 NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <b>Frac</b> <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER _____ <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Pull rods and tubing.
2. Frac down csg. w/20,000 gal. refined oil & 20,000 lb. sand.
3. Run tubing and rods, recover frac oil and take production test.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED  **B. F. Brawley** TITLE **District Engineer** DATE **3-21-66**

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: