

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>	
5. State Oil & Gas Lease No. K-6795	
7. Unit Agreement Name None	
8. Farm or Lease Name Tidewater-State	
9. Well No. 1	
10. Field and Pool, or Wildcat Tobac (Penn)	
12. County Chaves	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL GAS WELL OTHER- **Temp. Abandoned**

2. Name of Operator
ROGER C. HANKS

3. Address of Operator
1112 Oil & Gas Building, Wichita Falls, Texas 76301

4. Location of Well
UNIT LETTER **H**, **1980** FEET FROM THE **North** LINE AND **660** FEET FROM
THE **East** LINE, SECTION **31** TOWNSHIP **8S** RANGE **33E** NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK

TEMPORARILY ABANDON

PULL OR ALTER CASING

OTHER

PLUG AND ABANDON

CHANGE PLANS

SUBSEQUENT REPORT OF:

REMEDIAL WORK

COMMENCE DRILLING OPNS.

CASING TEST AND CEMENT JOB

OTHER

ALTERING CASING

PLUG AND ABANDONMENT

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Roger C. Hanks - Operator - plans to plug and abandon the above well on or about February 19, 1969, by the following method:

Placing a 25 sx plug over perforations at approximately 9100'; will rig up dialog and run free point and chemically cut off 4 1/2" casing, place a 25 sx plug over stub of 4 1/2" casing; set 25 sx plug over Glorietta formation at approximately 5100'; will rig up dialog and run free point on intermediate 8 5/8" casing, chemically cut same and set 25 sx plug in and out of base of intermediate. Space between plugs will be filled with 10# drilling mud and location will be marked permanently with steel marker according to Commission rules with 10 sx plug at surface.

The following additional plugs will be necessary:
 25 sx plug at base of 5 1/2" } if not behind 8 5/8"
 25 sx plug at top of 5 1/2"
 25 sx plug at base of 13 7/8" @ 423'
 25 sx plug at top of 5 1/2" and 13 7/8"

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Roger C. Hanks by [Signature] TITLE Operator DATE 2-17-69

APPROVED BY John W. Runyan TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:
NOTE ABOVE