N.	M.	PH	38.7	300ming181
P.	0.	ŀ.	1,330	20.51111.03.04

orm 9–331	P. O. L., 1300	et Bureau No. 42-R1424	
Dec. 1973	UNITED SPATES NEW MEXICO 8824	5. LEASE NM 046153-A	
DE	PARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
SUNDRY N	NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME	
eservoir, Use Form 9	t for proposals to drill or to deepen or plug back to a differen —331—C for such proposals.)		
1. oil (gas	Miller Federal 9. WELL NO.	
	well uther	- S. WELL NO.	
2. NAME OF OF Hase	loff Corporation	10. FIFLD OR WILDCAT NAME	
3. ADDRESS OF	OPERATOR Box 249, Lovington, NM 8826	11. SEC., T., R., M., OR BLK. AND SURVEY OR	
	F WELL (REPORT LOCATION CLEARLY. See space 1	NWSE Sec. 34: T7S, R31E	
AT SURFACE AT TOP PRO	D. INTERVAL:	12. COUNTY OR PARISH 13. STATE Chaves New Mexico	
AT TOTAL DE		14. API NO.	
	ROPRIATE BOX TO INDICATE NATURE OF NOTICE OTHER DATA	15. ELEVATIONS (\$HOW DF, KD8, AND WD) 4326' RDB	
REQUEST FOR A TEST WATER SH FRACTURE TREA SHOOT OR ACID REPAIR WELL PULL OR ALTER MULTIPLE COMP	IUT-OFF	(NOTE: Report results of multiple completion or zone change on Form 9–330.)	
CHANGE ZONES ABANDON® (other)		;	
inalitat act	PROPOSED OR COMPLETED OPERATIONS (Clearly stimated date of starting any proposed work. If well indicated true vertical depths for all markers and zones pertical	2 fill SCHOHAITA GILLISO, Black adaptations	
01-2	2-86 1) Set cement plug acros top of plug at 3850'.	s perf's 3900' to 3980'	
	2) Set 100' cement plug 2100'' back to 2000'.	across Yates Formation from	
	back to 295. Plug se casing.	s shoe 50' in 50' out, 395' it in and behind the 4 1/2"	
	4) Set 50' cement plug a 5) Installed P & A marke		
		;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;	
Subsurface Safe	ty Valve: Manu. and Type	Set @ F	
18. I hereby cer	tify that the foregoing is true and correct		
SIGNED	W (The TITLE office My	MAGE DATE 1- 28-16	
	(This space for Federal or Sta		
	1	DATE	
APPROVED BY _ CONDITIONS OF	APPROVAL, IF ANY:		

S