

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-101
Revised 10-1-

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

50. Indicate Type of Lease
State Fee
51. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR RELOCATE A WELL OR TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL GAS WELL OTHER

7. Unit Agreement Name

8. Form or Lease Name
Paul "LR"

9. Well No.
8

10. Field and Pool, or Whident
Tom Tom SA

11. Location of Well
UNIT LETTER G 1980 FEET FROM THE North LINE AND 1980 FEET FROM
THE East LINE, SECTION 25 TOWNSHIP 7S RANGE 31E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
4389.5' GR

12. County
Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING
 TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT
 PULL OR ALTER CASING OTHER CASING TEST AND CEMENT JOB OTHER Perforate, Treat, Acidize

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 4200'. Ran 103 joints of 4-1/2" 9.5# casing set at 4200'. Float collar set at 4159'. Cemented w/350 sacks Class "C" 3% salt. PD 1:15 PM 9-17-81. Bumped plug to 1000 psi, released pressure & float held okay. WOC. WIH w/casing gun on wireline & perforated 4141-4155' w/8 .41" holes as follows: 4141, 43, 45, 47, 49, 51, 53, & 55'. WIH w/4-1/2" RTTS. Set at 4140'. Acidized perfs w/1000 gallons 20% NEFE acid & 15 ball sealers. Swabbed back load. TOOH & picked up RBP. TIH & set RBP at 4130'. Tested RBP to 2500#. OK. Spotted 1 bbl of acid. TOOH. WIH w/casing gun on wireline & perforated 4099-4122' w/10 .41" holes as follows: 4099, 4101, 04, 07, 09-1/2, 11, 14, 17, 19-1/2 & 22'. Acidized perfs w/1500 gallons 15% NEFE acid. Swabbed back load. WBIH w/Selectfire guns on wireline and perforated 4015-85' w/16 .41" holes as follows: 4015, 19, 22, 36, 38, 48, 52, 55, 58, 61, 64, 67, 74, 78, 83, & 85'. Acidized perforations w/3500 gallons 20% NEFE acid and 30 ball sealers. Swabbed back load. Tripped out of hole w/packer & RBP. Ran rods & pump. to begin pumping back load.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Juanita Goddard TITLE Engineering Secretary DATE 10-6-81

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: