

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State Fee
5. State Oil & Gas Lease No.
L-963

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL GAS WELL OTHER- **Re-entry**

2. Name of Operator
Sage Oil Company

3. Address of Operator
c/o Box 763, Hobbs, New Mexico 88240

4. Location of Well
UNIT LETTER **B** **660** FEET FROM THE **North** LINE AND **1980** FEET FROM
THE **East** LINE, SECTION **35** TOWNSHIP **14S** RANGE **33E** N.M.P.M.

7. Unit Agreement Name
8. Farm or Lease Name
State "SA"

9. Well No.
1

10. Field and Pool, or Wildcat
Undes Saunders Permo-Penn

15. Elevation (Show whether DF, RT, GR, etc.)
4190 DF

12. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK

TEMPORARILY ABANDON

PULL OR ALTER CASING

OTHER _____

PLUG AND ABANDON

CHANGE PLANS

SUBSEQUENT REPORT OF:

REMEDIAL WORK

COMMENCE DRILLING OPNS.

CASING TEST AND CEMENT JOB

OTHER **Progress report**

ALTERING CASING

PLUG AND ABANDONMENT

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 6/14/78 Rigged up reverse circulation unit. Drilled plug to 20'.
- 6/15/78 Circulated heavy mud to 340'.
- 6/16/78 Hole caving, circulatedavings @ 340'.
- 6/17/78 Mixed mud, tagged top 8 5/8" casing stub @ 468'.
- 6/18/78 Shut down for Sunday.
- 6/19/78 Picked up bit, circulated hole clean to 930'. Pulled tubing, ran impression block, failed to get impression.
- 6/20/78 Ran tubing with bit, clean out to 1020'.
- 6/21/78 Pulled bit, picked up cut-rite shoe, 1 joint washover pipe, failed to find top 8 5/8" stub. Pulled shoe & washover pipe.
- 6/22/78 Picked up skirted mill, tagged top stub, failed to get over stub, pulled mill. Repaired & rerun mill, unable to get over stub, pulled mill.
- 6/23/78 Ran 4" mill on bottom of crooked joint of tubing & flat bottom mill on top of joint. Tagged top of 8 5/8" stub, milled off 16", pulled mill.
- 6/24/78 Ran 10 3/4" skirt and 8 joints 8 5/8" casing.
- 6/25/78 Shut down for Sunday.
- 6/26/78 Finished running 8 5/8" casing, set over stub. Ran Tubing with bit, drilled cement plug 490 to 520'.

Continued on attachment

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *H. E. ...* TITLE Agent DATE 7/21/78

APPROVED BY Orig. Signed by Jerry Weston Dist. L. Supv. TITLE _____ DATE JUL 24 1978

CONDITIONS OF APPROVAL, IF ANY: