

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State  Fee

5. State Oil & Gas Lease No.

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>Dryhole</u>	7. Unit Agreement Name
2. Name of Operator <u>Ralph E. Williamson (Advance Oil &amp; Gas Co., Inc.)</u>	8. Farm or Lease Name <u>Coll</u>
3. Address of Operator <u>1385 Midland National Bank Tower, Midland, TX 79701</u>	9. Well No. <u>1</u>
4. Location of Well UNIT LETTER <u>J</u> , <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>15</u> TOWNSHIP <u>13-S</u> RANGE <u>38-E</u> NMPM.	10. Field and Pool, or Wildcat <u>Wildcat</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>3810' GR</u>	12. County <u>Lea</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <u>Pull 8 5/8" casing Replug</u> <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2/25/80 Rig up, go in hole with wireline to 1200' to pull 8 5/8", 32# casing.  
 Set 150' plug on stub, shut in, WOC.  
 Set 100' plug @ 425'/bottom of surface, shut in, WOC.  
 Set 10 sx. plug @ surface and set dryhole marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Linda Walker TITLE Agent DATE 4/29/80

APPROVED BY Jerry Sexton TITLE \_\_\_\_\_ DATE MAY 8 1980  
 CONDITIONS OF APPROVAL Dist. & SUPPLY