

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

HUBBS OFFICE
MAY 31 8 12 AM '68
Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

4. Well Type of Lease
State Fee

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- WIW	7. Unit Agreement Name
2. Name of Operator Ryder Scott Management Company	8. Farm or Lease Name Cockburn Trinitite
3. Address of Operator 922 - 8th Street, Wichita Falls, Texas 76301	9. Well No. 2
4. Location of Well UNIT LETTER <u>H</u> , <u>2100</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>11</u> TOWNSHIP <u>17</u> RANGE <u>32</u> NMPM.	10. Field and Pool, or Wildcat Maljamar
15. Elevation (Show whether DF, RT, GR, etc.) no record	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-9-68 Pulled 1753' casing.
Set cast iron bridge plug at 3755', capped w/1 sack cement (7' fill up).
Set 25 sx cement at casing stub @ 1750'.
Set 25 sx cement @ base of surface pipe.
Set 10 sx cement @ top of surface.
Set metal marker at well site.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jean Halsey TITLE Agent DATE May 29, 1968

APPROVED BY John W. Runyan TITLE Geologist DATE 5/29/68

CONDITIONS OF APPROVAL, IF ANY: