

Submit 3 Copies To Appropriate District Office
 District I
 1625 N. French Dr., Hobbs, NM 87240
 District II
 811 South First, Artesia, NM 87210
 District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV
 2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 Revised March 25, 1999

OIL CONSERVATION DIVISION
 2040 South Pacheco
 Santa Fe, NM 87505

WELL API NO.
 30-025-05148

5. Indicate Type of Lease
 STATE FEE

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name:
 Denton North Wolfcamp Unit
 Tract 6

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)
 1. Type of Well:
 Oil Well Gas Well Other

2. Name of Operator
 Stephens & Johnson Operating Co.

8. Well No.
 15

3. Address of Operator
 P O Box 2249, Wichita Falls, TX 76307-2249

9. Pool name or Wildcat
 Denton Wolfcamp

4. Well Location
 Unit Letter J : 1980 feet from the South line and 2180 feet from the East line
 Section 26 (NW SE) Township 14S Range 37E NMPM County Lea

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
 3824 DF

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:
 PERFORM REMEDIAL WORK PLUG AND ABANDON
 TEMPORARILY ABANDON CHANGE PLANS
 PULL OR ALTER CASING MULTIPLE COMPLETION
 OTHER:

SUBSEQUENT REPORT OF:
 REMEDIAL WORK ALTERING CASING
 COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT
 CASING TEST AND CEMENT JOB
 OTHER:

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Well has been temporarily abandoned since 1-1-93. Will plug and abandon.
 See attached plugging procedure.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE _____ TITLE Manager of Operations DATE 6-25-02

Type or print name Peyton S. Carnes, Jr. Telephone No. 940-723-2166
 (This space for State use)

APPROVED BY _____ DATE JUL 30 2002
 Conditions of approval, if any:


ORIGINAL SIGNED BY
 GARY W. WINK
 OC FIELD REPRESENTATIVE
 DATE

DENTON NORTH WOLFCAMP UNIT WELL NO. 6-15

Plugging Procedure:

- 1) Set 5 1/2" CIBP @ 9120' with 35' cement on plug.
- 2) Run tubing to 9085', tag plug and load hole with 9.5# mud laden salt water.
- 3) Spot 25 sack plug @ 6300' in 5 1/2" casing.
- 4) Spot 30 sack plug 50' inside of 5 1/2" liner (4569') to 4417' inside of 7 5/8" casing. Tag plug.
- 5) Spot 25 sack plug at 3150' in 7 5/8" casing.
- 6) Spot 25 sack plug at 2200' in 7 5/8" casing.
- 7) Spot 125 sack plug 50' below surface casing to surface in 7 5/8" casing.
- 8) Cut off casing 3' below ground and install permanent marker.

Denton North Wolfcamp Unit Well 10.6-15
Denton N. (Wolfcamp) Field
Lea County, New Mexico



5-24-78
1EW