

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease  
 State  Fee

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO RE-OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
 USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1.  OIL WELL  GAS WELL  OTHER: **Water Injection Well**

7. Unit Agreement Name **Denton North Wolfcamp Ut. Tr. 8**

2. Name of Operator  
**Mobil Producing TX. & N.M. Inc.**

8. Farm or Lease Name

3. Address of Operator  
**Nine Greenway Plaza, Suite 2700, Houston, Texas 77046**

9. Well No.  
**3**

4. Location of Well  
 UNIT LETTER **G** **1980** FEET FROM THE **North** LINE AND **2310** FEET FROM  
**East** THE **36** LINE, SECTION **14S** TOWNSHIP **37E** RANGE **37E** N.M.P.M.

10. Field and Pool, or Wildcat  
**Denton Wolfcamp**

15. Elevation (Show whether DF, RT, GR, etc.)  
**3801' (GR)**

12. County  
**Lea**

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
 NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK   
 TEMPORARILY ABANDON   
 PULL OR ALTER CASING   
 OTHER

PLUG AND ABANDON   
 CHANGE PLANS

REMEDIAL WORK   
 COMMENCE DRILLING OPNS.   
 CASING TEST AND CEMENT JOBS   
 OTHER

ALTERING CASING   
 PLUG AND ABANDONMENT

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 10/04/82 MI Baber P&A Ut, notified NM OCD, got vbl OK to P&A, unload & rack 2-3/8 work tbg, NU BOP, WIH w/ 2-3/8 OE tbg to 2200.
- 10/05/82 Fin GIH w/ 2-3/8 OE tbg, stopped @ 6040, could not work deeper, POH, WIH w/ 5-5/8 tooth type bit, work thru short bridges to 6160 & stopped going, POH w/ bit, bit teeth packed w/ cmt & iron sulfide.
- 10/06/82 WIH w/ 6" tooth type bit, 2 - 4-3/4 cols on 2-3/8 tbg, DO iron sulfide 6040-6110 & fell thru, circ hole clean, ran bit & CO 9119 to D pkr @ 9252, circ hole clean, pulled 44 jts tbg.
- 10/07/82 Fin POH w/ tbg, DC & bit, RIH w/ 2-3/8 tbg OE to Baker Model D pkr w/ DR plug @ 9252, circ hole to 10# br mud, Baber spotted 30x Class H cmt on top of pkr 9252 to calc top @ 9100, job procedure was ok'd by Ed Sid w/ NM OCD, POH w/ 2-3/8 tbg to 3200.
- 10/08/82 Fin LD extra tbg, rem BOP, DO csg head, welded on lift sub, instl csg jacks, PU 250,000# rem slips-freept indicated stuck @ 4800, trying to work free pt deeper.
- 10/09-10/82 Ran free pt on 7" csg, free to 5200, Baber cut csg @ 5205, worked 7" csg 1 hr pipe stuck, broke off lift sub, SDFN & Sunday, prep to pickup w/ csg spear.
- 10/11/82 Latch into 7-5/8 csg w/ csg spear, could not move csg after jarring 1-1/2 hr, (SEE REVERSE)

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Paula A. Collins TITLE Authorized Agent DATE 10/22/82

APPROVED BY Ra Sudder TITLE OIL & GAS INSPECTOR DATE NOV 10 1988

CONDITIONS OF APPROVAL, IF ANY:

CONTINUED FROM FRONT

- 10/11/82 (Cont.) notified Jerry Sexton w/ NM OCD & obtained permission to cut 7-5/8 csg @ 4820, cut csg & could not pull csg, rewelded lift sub.
- 10/12/82 Work 7" csg free 4 hrs, LD 70 jts 7" csg = 2292'.
- 10/13/82 LD addl 82 jts & 5' piece of 7" csg, total csg rec 152 jts 7" 4873' of good csg, start in hole w/ OE 2-3/8 tbg.
- 10/14/82 Fin GIH w/ 2-3/8 OE tbg to 6114, Baber WS spotted 50x Class C cmt across csg holes 6049, pulled up clear, WOC 4 hrs, ran back & tag cmt @ 5904, pulled OE tbg up to 5260, spotted 30x Class C cmt across 7" csg, cut @ 5205, est T/cmt @ 5160, pulled OE tbg up to 4870, spotted 75x Class C cmt across 7" csg, cut off stub @ 4820, est T/cmt 4600, pulled up clear.
- 10/15/82 Ran tbg, tag cmt @ 4630, pull OE 2093, spotted 60x Class C, est top @ 1900, pulled OE tbg 372, spotted 40x Class C, est T/cmt 250, set 30' cmt plug in top of csg, cut off wellhead, weld 13-3/8 steel plate w/ P&A marker, rel Baber P&A Sv Ut @ 3 pm 10/15/82.

FINAL REPORT.

RECEIVED

OCT 25 1982

10/25/82