

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SAINTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
 State Fee
 5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO RE-ENTER OR RE-DRILL BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" FORM C-101 FOR SUCH PROPOSALS.

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER - WIW	7. Unit Agreement Name Denton North Wolfcamp Ut. Tr.8
2. Name of Operator Mobil Producing TX. & N.M. Inc.	8. Farm or Lease Name
3. Address of Operator Nine Greenway Plaza, Suite 2700, Houston, TX 77046	9. Well No. 3
4. Location of Well UNIT LETTER <u>G</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>2310</u> FEET FROM <u>East</u> LINE, SECTION <u>36</u> TOWNSHIP <u>14S</u> RANGE <u>37E</u> N.M.P.M.	10. Field and Pool, or Wildcat Denton Wolfcamp
15. Elevation (Show whether DF, RT, GR, etc.) 3801' (GR)	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

- (1) GIH w/7" cement retainer on 2-7/8" work string. Set retainer at 9250'.
- (2) Squeeze Wolfcamp Perfs (9284-9436) w/88x cement. Pull out of retainer. Spot 10x cement on top of retainer.
- (3) Circulate 9.5#/Gal. mud from 9200' to surface (340 bbls.).
- (4) Determine free point of 7" casing. GIH w/casing cutter. Cut and pull all free 7" casing.
- (5) GIH w/ 2-7/8" work string. Spot 65x cement from 75' below casing stub to 75' above casing stub.
- (6) Pull up hole to 4840'. Spot 65x cement across 9-5/8" casing shoe from 4690-4840'.
- (7) Pull up hole to 2100'. Spot 60x cement over salt zone from 2000-2100'. Pull up hole to 25' from surface.
- (8) Spot 10x cement at surface. Erect P&A Monument.
- (9) Clear location.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

NOTE: Use only "Neat" cement.
 Procedure discussed w/ Jerry Sexton of NM OCD in Hobbs, NM.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Paula A. Collins TITLE Authorized Agent DATE 8/13/82

ORIGINAL SIGNED BY
 JERRY SEXTON

APPROVED BY _____ TITLE _____ DATE AUG 17 1982

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
AUG 18 1982
D.C.D.
HOBBS OFFICE