

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

MAR 17 1 23 PM '67

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER - Temporarily Abandoned	7. Unit Agreement Name
2. Name of Operator Atlantic Richfield Company	8. Farm or Lease Name B.C. Dickinson "B"
3. Address of Operator P. O. Box 1978, Roswell, New Mexico	9. Well No. 3
4. Location of Well UNIT LETTER M 660 FEET FROM THE South LINE AND 330 FEET FROM THE West LINE, SECTION 12 TOWNSHIP 15-S RANGE 37-E NMPM.	10. Field and Pool, or Wildcat Denton-Devonian
15. Elevation (Show whether DF, RT, GR, etc.) 3794' DF	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input checked="" type="checkbox"/>	OTHER Recomplete in San Andres <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well was temporarily abandoned in December, 1961 by cementing off Mississippian perforations 11002 to 11046 w/25 sx Sloset. We now propose to pull 7" from approximately 6200', condition open hole & run open hole logs of the San Andres zone. If logs warrant a completion attempt, a 35 sk cement plug will be set at the 7" stub and 4-1/2" casing will be set at 6200' and cemented w/300 sx of Incor. San Andres will be selectively jet perforated and stimulated. If logs show San Andres unproductive, well will be plugged and abandoned w/50 sx cement in bottom of 9-5/8" casing @ 4751' and 10 sx in top of well.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Original Signed O. D. Bretcha TITLE Dist. Drlg. Supervisor DATE 3-16-67

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: