

NO. OF COPIES RECEIVED	
DISTRIBUTION:	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION
3-NMOCC
1-Midland
1-File
2-Atlantic Richfield

Form C-103
 Supersedes Old
 C-102 and C-103
 Effective 1-1-65

5a. Indicate Type of Lease
 State Fee
 5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO CELEBRATE OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - M (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Unit Agreement Name
2. Name of Operator GETTY OIL COMPANY	8. Firm or Lease Name STATE "P"
3. Address of Operator P. O. BOX 249, HOBBS, NEW MEXICO 88240	9. Well No. 51
4. Location of Well UNIT LETTER M 330 FEET FROM THE SOUTH LINE AND 330 FEET FROM THE WEST LINE, SECTION 32 TOWNSHIP 16-S RANGE 37-E NMPM.	10. Field and Pool, or Wildcat LOVINGTON - Padlock
15. Elevation (Show whether DF, RT, GR, etc.) 3803' GR	12. County LEA

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

Moved in casing pulling rig 7-7-76. Set CIBP @ 6100'. Dumped 35 feet cement on top of plug. PBD 6065'. Mixed 37 sacks salt gel in 150 bbls. brine. Circulated hole. Shot 5-1/2" casing @ 3417'. Could not pull. Shot 5-1/2" @ 3115' and pulled. Mixed 45 sacks salt gel in 185 bbls. brine and circulated hole. Mixed 45 sacks cement and spotted plug from 3172 to 2960'. Mixed 27 sacks cement and spotted plug from 2143' to 2043' (100'). Layed 10 sacks cement plug in top of 8-5/8". Cut off 8-5/8" casing head and cemented in "DRY HOLE" Marker. Cut off guy line anchors and cleaned up location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.
 ORIGINAL SIGNED BY:
 C.L. Wade: C. L. Wade TITLE AREA SUPERINTENDENT DATE 7-26-76

APPROVED BY John Ryan TITLE _____ DATE 7-5-1976
 CONDITIONS OF APPROVAL, IF ANY:

WLG/bh

RECEIVED

JUL 27 1976

C. L. CONNOR & COMPANY
LEEDS, N. C.