

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1940, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

Santa Fe, New Mexico 87504-2088

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.
30-025-09867

5. Indicate Type of Lease
STATE FEE

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)



7. Lease Name or Unit Agreement Name

Priest

1. Type of Well:
OIL WELL GAS WELL OTHER

2. Name of Operator
Paladin Energy Corporation

8. Well No.
6

3. Address of Operator
10290 Monroe Dr., Ste. 301, Dallas, TX 75229

9. Pool name or Wildcat
Denton Field

4. Well Location
Unit Letter E : 330 Feet From The West Line and 1651 Feet From The North Line
Section 1 Township 15S Range 37E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3794

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 7-17-00 1) Notify NMOCD, Billy P.
- 7-18-00 2) Set 5-1/2" CIBP @ 12,427' w/ 4 sx cmt.dumpbailed on top,TOC @12,387' calc.
- 3) Circulated hole w/ 10# MLF.
- 4) Spot 25 sx cmt. 8128-7876'.
- 7-20-00 5) Cut & Pull 5-1/2" csg. from 5900'.
- 6) Spot 30 sx cmt. w/ 2% CaCl @ 5950'.WOC & tag TOC @ 5815'.
- 7) Spot 40 sx cmt. @ 4800'.
- 7-21-00 8) Tag TOC @ 4627'.
- 9) Spot 30 sx cmt. 2200-2090'.
- 10) Spot 35 sx cmt. w/ 2% CaCl @ 427',WOC & Tag TOC @ 315'.
- 11) Cone 20 sx cmt. 60' - Surface.
- 12) Back fill cellar & pit, cut deadmen, install dry hole marker.ASAP.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Roger Massey TITLE Agent DATE 7-28-00

TYPE OR PRINT NAME Roger Massey TELEPHONE NO. 915-570-7087

(This space for State Use)

APPROVED BY Billy E. Prubie TITLE _____ DATE _____

GWW