

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. 1065
7. Unit Agreement Name
8. Farm or Lease Name E. K. Queen Unit Tr. 9
9. Well No. 4
10. Field and Pool, or Wildcat E. K. Yates 7/River Q.
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Mobil Oil Corporation
3. Address of Operator Three Greenway Plaza East, Suite 800, Houston, Texas 77046
4. Location of Well UNIT LETTER <u>0</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>18</u> TOWNSHIP <u>18-S</u> RANGE <u>34-E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 4073 GR

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- MIRU; POH w/inj. equip.
- GIH w/cmt retainer & set @ -4400'. Sqz Queen perfs
- PU & spot 5 sx on retainer.
- Circ hole w/9.5# mud laden fluid.
- Run "free-point", shoot off, POH and lay down 5 1/2" casing (top of cmt -3135').
- Spot 50 sx cmt plug across csg cut & bottom of salt.
- PU & spot 50 sx -1875-1975 across salt top.
- PU & spot 65 sx -290'-400' across surf csg shoe.
- PU & spot 10 sx - 0'-21'.
- Erect monument & clear location.

Notify NMOCC 24 hrs prior to starting P&A.

File NMOCC Forms C-103 & C-105.

Procedure approved by NMOCC.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Authorized Agent DATE 1-3-77

APPROVED BY [Signature] TITLE \_\_\_\_\_ DATE 1977

CONDITIONS OF APPROVAL, IF ANY \_\_\_\_\_