

| | |
|------------------------|--|
| NO. OF COPIES RECEIVED | |
| DISTRIBUTION | |
| SANTA FE | |
| FILE | |
| U.S.G.S. | |
| LAND OFFICE | |
| OPERATOR | |

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State Fee
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

| | |
|---|--|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> | 7. Unit Agreement Name |
| 2. Name of Operator JAKE L. HAMON | 8. Farm or Lease Name Texas Gulf |
| 3. Address of Operator 908 VAUGHN BUILDING, MIDLAND, TEXAS & 79701 | 9. Well No. 1 |
| 4. Location of Well UNIT LETTER K 2310 FEET FROM THE South LINE AND 2310 FEET FROM THE West LINE, SECTION 27 TOWNSHIP 18 RANGE 35 NMPM. Buckeye | 10. Field and Pool, or Wildcat |
| 15. Elevation (Show whether DF, RT, GR, etc.) UK | 12. County Lea |

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

| NOTICE OF INTENTION TO: | | SUBSEQUENT REPORT OF: | |
|--|--|---|---|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input checked="" type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | OTHER <input type="checkbox"/> | CASING TEST AND CEMENT JOB <input type="checkbox"/> | |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- (1) Spot a 20' plug on top of the Model D Packer at 10,700'.
- (2) Spot a 100' plug across perforations at 9,080'.
- (3) Spot a 100' plug at stub of 5-1/2" casing, approx. 6,000'.
- (4) Spot a 100' plug in and out of the 9-5/8" shoe at 3,775'.
- (5) Spot a 20 sx plug in the top of hole and set a regulation marker.
- (6) Hole will be loaded with mud-laden fluids.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *J. D. Duffin* TITLE AGENT DATE 12/28/72

APPROVED BY _____ TITLE SUPERVISOR DISTRICT I DATE JAN 2 1973

CONDITIONS OF APPROVAL, IF ANY: