

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State Fee
5. State Oil & Gas Lease No.
B-2656

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL GAS WELL OTHER
2. Name of Operator
Conoco Inc.
3. Address of Operator
P.O. Box 460 - Hobbs, New Mexico 88240
4. Location of Well
UNIT LETTER G 2310 FEET FROM THE north LINE AND 2310 FEET FROM
THE east LINE, SECTION 33 TOWNSHIP 18S RANGE 38E NMPM.
15. Elevation (Show whether DF, RT, CR, etc.)

7. Unit Agreement Name
8. Farm or Lease Name
State A-33
9. Well No.
11
10. Field and Pool, or Wildcat
Bowers Seven Rivers
12. County
Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1503.

Work started 3/17/87. MIRU. POOH w/ Hg. C-1H w/ Hg. to 3100'. Circulate wellbore w/ 80 bbls mud. Spot 35 sxs class "c" cement w/ 4% CaCl₂ from 2850'-2500'. Wait on cement 3 1/2 hrs. Tag cement at 2600'. Spot 20 sxs class "c" neat cement from 1620'-1370'. POOH w/ Hg. Spot 20 sxs class "c" w/ 4% CaCl₂ from 470'-270'. POOH. Tag top of cement at 290'. Circulate 20 sxs class "c" neat from 100' to surface. Rig down. Install P&A marker. Work completed on 3/18/87

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] LF FINNEY TITLE Administrative Supervisor DATE August 18, 1987

APPROVED BY [Signature] TITLE OIL & GAS INSPECTOR DATE SEP 10 1987

CONDITIONS OF APPROVAL, IF ANY:
none