

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State Fee
5. State Oil & Gas Lease No.
B-10784

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL GAS WELL OTHER

2. Name of Operator
AMOCO PRODUCTION COMPANY

3. Address of Operator
P. O. BOX 68 HOBBS, NEW MEXICO 88240

4. Location of Well
UNIT LETTER L 1980 FEET FROM THE South LINE AND 660 FEET FROM
THE West LINE, SECTION 9 TOWNSHIP 18-S RANGE 34-E NMPM.
10. Field and Pool, or Wildcat
W. Vacuum Bone Springs

15. Elevation (Show whether DF, RT, GR, etc.)
4046.0' GR

12. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK
TEMPORARILY ABANDON
PULL OR ALTER CASING
OTHER

PLUG AND ABANDON
CHANGE PLANS
OTHER

SUBSEQUENT REPORT OF:

REMEDIAL WORK
COMMENCE DRILLING OPNS.
CASING TEST AND CEMENT JOB
OTHER

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to PxA as follows:

MISU and POH rods, pump, and tubing. RIHW/ CIBP and set at 8175'. Cap w/ 35' of Class H neat cement. Spot 58 Bbls of 10# brine with 25# gel per bbl. Pull up to 5730' and spot a 25 SX Class H neat cement plug from 5703'-5530' (Top of Delaware 5630'). Spot 26 Bbls brine gel. Pull up to 4450' and spot a 25 SX Class H neat cement plug from 4450'-4250' (Top of Queen 4354'). Spot 13 Bbls brine gel. Pull up to 3700' and spot a 25 SX class H neat cement plug from 3700'-3500' (8 7/8" casing shoe set at 3600'). Spot 36 Bbls brine gel. Pull up to 2000' and spot a 25 SX class H neat cement plug from 2000'-1800' (Top of Salt 1900'). Spot 29 bbls brine gel. Pull up to 600' and spot a 25 SX class H neat plug from 600'-400' (13 3/8" casing shoe at 516'). Spot 8 bbls brine gel. Pull up to 80' and spot a 10 SX Class H neat cement plug from 80'-60' (10 1/2" casing shoe at 60').
O+5 NMOCD-H 1-JRB 1-FJN 1-CMH 1-Chevron, H.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Charles M. Herring TITLE ADMINISTRATIVE ANALYST (SG) DATE 1-16-86

ORIGINAL SIGNED BY JERRY BEXTON
DISTRICT I SUPERVISOR

JAN 17 1986

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

Heat cement plug from 80' to surface. Cap well and erect abandonment marker. MOSU.

RECEIVED
JAN 14 1988
O. C. H.
HARRIS CENTER