Form 3160-5 (August 1999)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

N.M. Oil C s. Division
1625 N. French Dr.
Hobbs, NM 88240
Expire
Lease Serial No.

FORM APPROVED OMB No. 1004-0135 Expires November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an 6. If Indian, Allottee or Tribe Name abandoned well. Use Form 3160-3 (APD) for such proposals. If Unit or CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on reverse side NMNM84603X Type of Well ☐ Oil Well ☐ Gas Well ☒ Other Well Name and No. Name of Operator Central Corbin Queen Unit #104 Saga Petroleum LLC API Well No. 3a. Address 30-025-29740 3b. Phone No. (include area code) 415 W Wall, Suite 1900, Midland, TX 79701 (915)684-4293 10. Field and Pool, or Exploratory Area 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 660' FNL & 790' FEL CORBIN QUEEN CENTRAL 11. County or Parish, State SEC9 (A), T18S, R33E LEA NM 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Acidize Deepen Production (Start/ Resume) ☐ Water Shut-Off Notice of Intent Alter Casing Fracture Treat Reclamation Well Integrity Subsequent Report Casing Repair Othe: Add perfs New Construction Recomplete Change Plans Plug and Abandon inc inj rate Temporarily Abandon Final Abandonment Notice Convert to Injection Plug Back Water Disposal reduce inj pres 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) TD 4325' PBTD 4312' Perf 4213'-4242' RIH w/gauge ring to TD - If unable to reach 4275', POOH, PU GR-CCL logging tool & RIH & set on depth w/GR-DEN-Neutron log, obtain GR-CCL log over Queen interval & POOH Perf 4244'-4246' & 4249'-4254' w/1 jspf (decentralized strip gun) Acidize new & old perfs using 4000 gals 15% NEFE HCL in 2 stages. Pump 2500 gal acid, followed w/200# Rock Salt block & then pump remaining 1500 gal 15% NEFE HCL acid. Monitor treating pressure, not to exceed 4500# surface pressure. SI for 30 mins, flow well back w/at lease twice the volume from btm perf to surface. Put well back on injection & obtain inj rate & surface pressures until well stabilizes. Obtain step rate test. 14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Bonnie Husband **Production Analyst** Date 08/13/2001 THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by Title Conditions of approval, if any, are attached. Approval of this notice does not warrant or Office certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or

fraudulent statements or representations as to any matter within its jurisdiction.