

Submit 3 Copies To Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 87240  
District II  
811 South First, Artesia, NM 87210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised March 25, 1999

OIL CONSERVATION DIVISION  
2040 South Pacheco  
Santa Fe, NM 87505

WELL API NO. 30-025-20235
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-270

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other	7. Lease Name or Unit Agreement Name: Vacuum Glorieta West Unit
2. Name of Operator Texaco Exploration & Production	8. Well No. 33
3. Address of Operator 500 N. Lorraine Midland, Texas 79702	9. Pool name or Wildcat Vacuum Glorieta
4. Well Location Unit Letter <u>L</u> : <u>1650</u> feet from the <u>South</u> line and <u>660</u> feet from the <u>West</u> line Section <u>25</u> Township <u>17S</u> Range <u>34E</u> NMPM County <u>Lea</u>	
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 4019' DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐

OTHER: ☐ Request TA status

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

01-23-01 MIRU Key, Weatherford, SDON, Prep to pull sub eqp.  
01-24-01 Open well, bled down, kill w/10# brine. RU and pull sub eqp. RD esp. TIH w/5-1/2" CIBP and pkr on 2-7/8" work string; set CIBP @ 5814'; test CIBP to 1000 psi, OK. Prep to test csg.  
01-25-01 RU reverse unit, circ w/10# brine, start looking for csg leak. 2452' to surface good. 5086' to 5814' test good; SDON; prep to circ treated wtr and chart csg.  
01-26-01 TIH to 5805', circ w/treated wtr, test and chart csg to 340 psi for 30 minutes; TOH laying down 2-7/8" work string; prep to continue laying down work string and RD.  
01-29-01 SD due to ice/snow.  
01-30-01 Finish laying down 2-7/8" tbq, load csg w/treated wtr. NDBOP, NOWH, well test; RD Key.

Well is temporarily abandoned.

04-05-02 Retested and chart csg to 500 psi for 30 minutes.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Laura Skinner TITLE Regulatory Specialist DATE 04-19-02

Type or print name Laura Skinner Telephone No. 915-687-7355

(This space for State use)

ORIGINAL SIGNED BY

GARY W. WINK

OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE

APPROVED BY  
Conditions of approval, if any:

This Approval of Temporary  
Abandonment Expires

5/6/07

MAY 06 2002

