

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I
P.O. Box 1980, Hobbs NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-20582

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
Phillips Petroleum Company

3. Address of Operator
4001 Penbrook Street, Odessa, TX 79762

4. Well Location
Unit Letter M : 330 Feet From The SOUTH Line and 660 Feet From The WEST Line

Section 27 Township 17-S Range 35-E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

7. Lease Name or Unit Agreement Name
VACUUM GLORIETA EAST UNIT
TRACT 12

8. Well No.
2

9. Pool name or Wildcat
VACUUM GLORIETA

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: SQZ. T/REPAIR CASING ANNULUS LEAK ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

04/19/96 MIRU LUCKY #21 DDU; COOH W/ RODS & PMP.
NU BOP, ND WELLHEAD; COOH W/TBG, LAYING DOWN
ON PIPE RACKS; GIH W/RBP T/2400' TST PLUG, PUT
2 SXS SAND ON RBP, TOP OFF CASING W/FR WATER, SD
04/22/96 RU HALLIBURTON, GIH W/4" PERF GUNS T/1630', SHOOT 4
HOLES COOH W/GUNS; GO IN HOLE W/PKR ON TBG T/1635',
SET PKR; RU & SWAB, 1ST FL 700' F/SURFACE, ENDING
LEVEL 1600', REC 40 BBL WTR, SD.
04/23/96 SWAB, FL @ 700', SWAB DOWN T/1630', SEAT NIPPLE, COOH
W/PKR & TBG, OBSERVE, PULL BOP, PART WELLHEAD FLANGES,
RELEASE SMALL AMT OF GAS, REPAIR WELLHEAD PACK OFF RUBBER,
(CONTINUED ON BACK)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Larry M. Sanders TITLE Senior Regulation Analyst DATE 05/06/96

TYPE OR PRINT NAME Larry M. Sanders

TELEPHONE NO. (915)368-1488

(This space for State Use)

APPROVED BY LARRY SEXTON
SUPERVISOR

TITLE _____ DATE MAY 10 1996

CONDITIONS OF APPROVAL, IF ANY:

RE-PIPE SURFACE PIPE RISERS, SET WELLHEAD BACK ON & FLANGE UP, NU BOP, PUMP DOWN 4-1/2", 140 BBL T/CLEAN UP BACK SIDE. SD.

04/24/96 CIRC FRESH WATER TO SURFACE, 2 BPM @ 150 PSI, GO IN W/CMT RETAINER TO 1545' LEFT SWINGING, SD.

04/25/96 RU ON TBG, SET/TEST RETAINER, BREAK CIRC. T/SURFACE, 5 BBL T/CIRC, RU HALLIBURTON, PMP 446 SXS CLASS C CMT IN 4 HOLES @ 1630', MAX RATE 2.5 BPM, MIN RATE .70 BPM, MAX PRESS 1000 PSI SI PRESS 1000 PSI, REV OUT T/CLEAN UP, RD HALLIBURTON, COOH W/TBG, SI.

04/26/96 PU BIT, 6 DRL COLLARS, 1000' TBG, RU F/DRILL OUT, SD F/CMT TO SET UP.

04/27/96 TAG TOP CMT @ 1536', DRL DOWN T/1542', STILL DRILLING RETAINER, SD.

04/30/96 DRILL OUT CMT, CIRC WELLBORE CLEAN OF CMT, TAG SAND, CIRC SAND OFF RBP, COOH W/COLLARS, TRIP CASING SCRAPER, GIH W/ON-OFF TOOL, (SAND STILL IN PLUG), PU TUBING, SD.

05/01/96 GIH W/ON-OFF TOOL, SAND ON PLUG, RU T/CIRC, CLEAN UP SAND, CATCH RBP, COOH W/TOOLS, SOME OF RETAINER PUSHED UP INTO ON-OFF TOOL, GOT RBP T/SURFACE, GIH W/PROD TBG, TSTG TBG, ND BOP, CHANGE WELLHEADS, SI.

05/02/96 RUN ROD STRING, HANG WELL ON, RD LUCKY, DROP FROM REPORT.