Form 3160-3 (June 1990)

UNITLD STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

N.M. Oil CC . Division FORM APPROVED P.O. Box 1980 Hobbs, NM 88241

Budget Bureau No. 1004-0135 Expires: March 31, 1993


5. Lease Designation and Serial No.

NMNM-77074 **SUNDRY NOTICES AND REPORTS ON WELLS** 6. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals 7. If Unit or CA, Agreement Designation SUBMIT IN TRIPLICATE 1. Type of Well Oil Well 8. Well Name and No. \boxtimes Other Tomahawk 34 Federal #1 2. Name of Operator **Nearburg Producing Company** 9. API Well No. 30-025-34302 3. Address and Telephone No. 10. Field and Pool, or Exploratory Area 3300 N A St., Bldg 2, Suite 120, Midland, TX 79705 915/686-8235 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Wildcat - Yates 11. County or Parish, State 660' FNL and 1,650' FWL, Section 34, T20S, R33E Lea County, New Mexico CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 12. TYPE OF ACTION TYPE OF SUBMISSION Change of Plans Abandonment Notice of Intent **New Construction** Recompletion X Subsequent Report Plugging Back Non-Routine Fracturing Casing Repair Water Shut-Off Final Abandonment Notice Altering Casing Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 13. Describe Proposed or Completed Operations (Clearly state all pertinet details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markders and zones pertinent to this work.)* 1). MIRU well service unit. 2). Set CIBP at 13,575' w/35' cement on top to abandon the Morrow formation. 3.) Circulate well with 9.9 ppg mud. 4.) Set 25 sx cmt plug 10,880' - 10,680'. PUH 8,002' & set 25 sx cmt plug 8,002' - 7,802'. Cut and pulled 5-1/2" csg from 6,615'. PUH to 6,663' & set 50 sx cmt plug 6,663' - 6,463' (100' in & out of csg stub). WOC & tag plug at 6,617'. PUH to 6,411' & set 45 sx cmt plug 6,411 -6,261'. PUH to 5,311' & set 80 sx cmt plug 5,311' - 5,011'. WOC. Tag cmt plug at 5,104'.

5). Perforate 7 Rivers Formation 3,467' - 3,494' at 4 JSPF.

6). Swab well.

7). RDMO well service unit.



14. I hereby certify that the foregoing is true and correct		1/2/00
Signed Signed	Title Manager of Drilling and Production	Date
(This space for Federal or State office use)		
Approved byConditions of approval, if any:	Title	Date

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

