

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

**OIL CONSERVATION DIVISION**

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

DISTRICT I  
P.O. Box 1980, Hobbs NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.  
**30-025-06368**

5. Indicate Type of Lease  
STATE  FEE

6. State Oil & Gas Lease No.

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)



7. Lease Name or Unit Agreement Name  
**NORTHEAST DRINKARD UNIT**

1. Type of Well:  
OIL WELL  GAS WELL  OTHER

8. Well No.  
**213**

2. Name of Operator  
**Shell Western E&P Inc.**

9. Pool name or Wildcat  
**N. EUNICE BLINEBRY-TUBB-DRINKARD**

3. Address of Operator  
**P.O. Box 576, Houston, TX 77001** (WCK 5237)

4. Well Location  
Unit Letter **L** : **4620** Feet From The **SOUTH** Line and **660** Feet From The **WEST** Line  
Section **2** Township **21S** Range **37E** NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
**3491' DF**



11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

<b>NOTICE OF INTENTION TO:</b>		<b>SUBSEQUENT REPORT OF:</b>	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <b>OAP &amp; AT</b> <input checked="" type="checkbox"/>		OTHER: _____ <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- POH W/PROD EQMT.
- TAG BTM.
- PERF BLINEBRY 5827' - 5922' (1 SPF).
- AT DRINKARD OH W/750 GAL 15% NEFE HCL + 600# ROCK SALT.
- SET RBP @ +/-6642'. AT DRINKARD PERFS 6584' - 6639' W/1500 GAL 15% NEFE HCL + 1200# ROCK SALT.
- RESET RBP @ 6010'. AT BLINEBRY PERFS 5936-77' W/1500 GAL 15% NEFE HCL + 1200# ROCK SALT.
- RESET RBP @ 5929'. AT BLINEBRY PERFS 5896' - 5922' W/1500 GAL 15% NEFE HCL.
- RESET RBP @ 5887'. AT BLINEBRY PERFS 5827-78' W/2500 GAL 15% NEFE HCL.
- INST PROD EQMT & RTP.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *G. S. Nady* TITLE **MGR - ASSET ADMIN.** DATE **10/18/94**

TYPE OR PRINT NAME **G. S. NADY** TELEPHONE NO. **713/544-3797**

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE **OCT 25 1994**

CONDITIONS OF APPROVAL, IF ANY:

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-77

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease  
State  Fee   
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1.  OIL WELL  GAS WELL  OTHER

2. Name of Operator  
SHELL WESTERN E&P INC.

3. Address of Operator  
P. O. BOX 576, HOUSTON, TX 77001 (WCK 4435)

4. Location of Well  
UNIT LETTER L 4620 FEET FROM THE SOUTH LINE AND 660 FEET FROM  
THE WEST LINE, SECTION 2 TOWNSHIP 21-S RANGE 37-E N.M.P.M.

7. Unit Agreement Name  
NORTHEAST DRINKARD UNIT

8. Farm or Lease Name  
NORTHEAST DRINKARD UNIT

9. Well No.  
213

10. Field and Pool, or Wildcat  
NORTH EUNICE BLINEBRY-TUBB-DRINKARD OIL & GAS

11. Elevation (Show whether DF, RT, GR, etc.)  
3491' DF

12. County  
LEA

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK  PLUG AND ABANDON  REMEDIAL WORK  ALTERING CASING

TEMPORARILY ABANDON  CHANGE PLANE  COMMENCE DRILLING OPNS.  PLUG AND ABANDONMENT

PULL OR ALTER CASING  OTHER  CASING TEST AND CEMENT JOBS

OTHER OAP, ACD & SAND FRAC'D

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. (See C-103 Intent for former well name, State Sec. 2 #2)

12-15 to 12-29-87:  
POH w/prod equip. Set RBP @ 6550'. Spotted 500 gals 15% HCl-NEA from 6440' to 5940'. Perf'd Blinebry/Tubb 6048' - 6438' (1 JSPF). Acid perms 6048' - 6438' w/ 1092 gals 15% HCl-NEA (perms 6048' - 6297' communicated). Acid perms 6048' - 6438' w/ 2000 gals 15% HCl-NEA. Sand frac'd perms 6048' - 6438' w/ 42,000 gals x-linked 40# gel + 144,500# 20/40 sd. SI overnite. Flowed back until well died. Tagged top of sd @ 6430'. Circ'd out sd to 6550'. Rel RBP & reset @ 6570'. Ran GR/temp log. Perf'd Blinebry/Tubb 5896' - 6560' (1 JSPF). Spotted 500 gals 15% HCl-NEA from 6550' to 6050'. Pmp'd 1000 gals 15% HCl-NEA into Tubb perms 6538' - 60' & communicated. Acid perms 5936' - 6560' w/ 2000 gals 15% HCl-NEA + 500# rock salt. Reset RBP @ 5915'. Acid perms 5896' - 5901' w/ 500 gals 15% HCl-NEA. POH w/RBP. Installed prod equip & returned well to prod.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE 6-9-88

ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_