

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

# OIL CONSERVATION DIVISION

**DISTRICT I**  
P.O. Box 1980, Hobbs NM 88241-1980

2040 Pacheco St.  
Santa Fe, NM 87505

**DISTRICT II**  
P.O. Drawer DD, Artesia, NM 88210

**DISTRICT III**  
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-025-20175
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-1732
7. Lease Name or Unit Agreement Name HEASLEY STATE
8. Well No. 8
9. Pool name or Wildcat EUMONT;YATES-7 RVRS-QUEEN (PRO GAS)
10. Elevation (Show whether DF, RKB, RT, GR, etc.)

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL  GAS WELL  OTHER

2. Name of Operator  
Chevron U.S.A. Inc.

3. Address of Operator  
P.O. Box 1150, Midland, TX 79702

4. Well Location  
Unit Letter A : 660 Feet From The NORTH Line and 500 Feet From The EAST Line

Section 5 Township 21S Range 36E NMPM LEA County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: <u>CO:ACZD</u> <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

POH W/TBG. CLEANED OUT SAND 3093' TO RBP @ 3200'. CIRC HOLE CLEAN. TAGGED FILL @ 3337'. CLEANED OUT TO 3579'. CIRC HOLE CLEAN. ACZD W/3000 GALS 15%. SWABBED. RIH W/PROD TBG TO 3470'. RETURNED WELL TO PRODUCTION.

WORK PERFORMED 9/26/97 - 10/1/97

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. K. Ripley TITLE TECHNICAL ASSISTANT DATE 5/7/98

TYPE OR PRINT NAME J. K. RIPLEY TELEPHONE NO. (915)687-7148

(This space for State Use)

ORIGINAL SIGNED BY GARY WINK TITLE FIELD REP. II DATE MAY 19 1998

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: \_\_\_\_\_