

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

AUG 15 3 35 PM '66

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Gulf Oil Corporation	8. Farm or Lease Name A.L. Christmas (NCT-A)
3. Address of Operator P. O. Box 670, Hobbs, N.M. 88240	9. Well No. 4
4. Location of Well UNIT LETTER G 1980 FEET FROM THE north LINE AND 1980 FEET FROM THE east LINE, SECTION 27 TOWNSHIP 22S RANGE 36E NMPM.	10. Field and Pool, or Wildcat South Emice
15. Elevation (Show whether DF, RT, GR, etc.) 3511' DF	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Rigged up pulling unit. Pulled rods and pump. Installed BOP. Pulled tubing. Ran 5 1/2" Baker CI BP on 2-3/8" tubing and set at 3670'. Loaded hole with mud. Spotted 10 sacks cement on top of BP. Tested 5 1/2" casing and BP with 500# for 30 minutes, no drop in pressure. Pulled tubing and spotted 10 sacks cement 80' to surface. Set dry hole marker and cleaned location. Plugged and abandoned 7-13-66.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED C. D. BORLAND ORIGINAL SIGNED BY C. D. BORLAND TITLE Area Production Manager DATE 7-15-66

APPROVED BY Leslie A. Clemens TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: