

N.M. OIL CONS. COMMISSION

P. BOX 1090

UNITED STATES DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

Form 3160-5  
November 1983  
Formerly 9-331)

Form approved  
Budget Bureau No. 1004-3135  
Expires August 31, 1985

PERMIT IN TRIPPLICATE  
(Send instructions on reverse side)

5. LEASE DESIGNATION AND SERIAL NO.

NM-18631

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

---

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Jackson Federal

9. WELL NO.

4

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., W., OR ALK. AND CORNER OR AREA

Sec. 35, T24S, R32E

SUNDRY NOTICES AND REPORTS ON WELLS  
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL  GAS WELL  OTHER  Dry

2. NAME OF OPERATOR  
Exxon Corporation Attn: Melba Knippling

3. ADDRESS OF OPERATOR  
P. O. Box 1600, Midland, Texas 79702

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)  
At surface

660' FNL and 1980' FWL of Sec. (NE NW)

14. PERMIT NO.  
30-025-29212

15. ELEVATIONS (Show whether of, to, or, etc.)  
GR

12. COUNTY OR PARISH  
Lea

13. STATE  
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETION

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON\*

SHOOTING OR ACIDIZING

ABANDONMENT\*

REPAIR WELL

CHANGE PLANS

(Other) \_\_\_\_\_

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

The above well was plugged and abandoned in the following manner:

Set plug 4970 - 4320 w/ 57 sx C1C Neat.

Set plug 1098 - 998 w/ 50 sx C1C Neat.

Set plug 658 - 500 w/ 50 sx C1C Neat.

Set plug 50 - Surface w/ 20 sx C1C Neat.

Cut off wellhead and install dry hole marker.

18. I hereby certify that the foregoing is true and correct

SIGNED

*Melba Knippling*

TITLE

Unit Head

DATE

6-27-85

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

11

RECEIVED

JUL - 2 1985

HEAD