

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.	30-025-30746
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name	Double ABJ State
8. Well No.	1
9. Pool name or Wildcat	Und. Lea Strawn Gas

1. Type of Well:	Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other <input type="checkbox"/>
------------------	---

2. Name of Operator	YATES PETROLEUM CORPORATION
---------------------	-----------------------------

3. Address of Operator	105 South 4th St., Artesia, NM 88210
------------------------	--------------------------------------

4. Well Location	Unit Letter <u>B</u> : <u>660</u> Feet From The <u>North</u> Line and <u>1980</u> Feet From The <u>East</u> Line
	Section <u>16</u> Township <u>24S</u> Range <u>32E</u> NMPM <u>Lea</u> County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)	
--	--

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: Add perforations & acidize <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-20-98 - Rigged up derrick, slickline and lubricator. TIH with gauge ring to 14800'. Did not feel anything. TOOH with gauge ring. Did not feel fluid. Tried to test annulus. Could not get valves to work.

5-21-98 - Changed out flange on casing valve. Shut down until 5-26-98.

5-27-98 - Rigged up wireline. Pumped 20 bbls 2% KCL. TIH with 1-11/16" thru tubing gun to 13000'. Schlumberger did not have enough cable. TOOH with gun. Rigged down wireline.

5-28-98 - Rigged up wireline and derrick truck. TIH with 1-11/16" Enerjet gun and perforated 14373-14384' w/22 .32" holes (2 SPF - Strawn). TOOH with guns and rigged down wireline. Bled casing down.

5-29-98 - Rigged up treesaver. Acidized perforations 14050-14384' with 10000 gallons 15% iron control HCL acid, 10000 gallons CO2 and ball sealers. Overflushed with 100 bbls of 50:50 2% KCL and CO2. Rigged down treesaver. Flowing well back.

5-30-98 - Flow testing. Released well to production department.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Operations Technician DATE June 8, 1998

TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use)

APPROVED BY Paul Bartz TITLE Geologist DATE June 8, 1998

CONDITIONS OF APPROVAL, IF ANY:

123456789101112  
MAY 1998  
Received  
Hobbs  
OCD