

Submit 3 copies to Appropriate District Office

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	3002531483
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	WEST DOLLARHIDE DRINKARD UNIT
8. Well No.	115
9. Pool Name or Wildcat	DOLLARHIDE TUBB DRINKARD

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well: OIL WELL  GAS WELL  OTHER

2. Name of Operator: TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator: 205 E. Bender, HOBBS, NM 88240

4. Well Location: Unit Letter A : 121 Feet From The NORTH Line and 1309 Feet From The EAST Line  
Section 5 Township 25S Range 38E NMPM LEA COUNTY

10. Elevation (Show whether DF, RKB, RT,GR, etc.) 3165'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPERATION <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	ACID WASH PERFS <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7/27/00: MIRU. NDWH. NUBOP. TAG @ 6827'.  
 7/28/00: KILL WELL. TIH W/SONIC HAMMER TOOL ON TBG TO 5967'.  
 7/31/00: TIH W/TBG & SONIC HAMMER TO 6072'. ACID WASH DRINKARD CSG PERFS 6072-6788 W.4000 GALS 15% NEFE HCL. SCALE SQUEEZE SAME PERFS W/SONIC HAMMER. PUMPED 165 GALS TH-756 MIXED W/70 BBLS 2% KCL WTR. FLSH W/80 BBLS 2% KCL WTR.  
 8-01-00: KILL CSG W/20 BBLS 2% KCL WTR. TIH W/OPSMA, SN, TBG, TAC. TBG @ 6808. SN @ 6777. TAC @ 6033. NDBOP. NUWH. TIH W/GAS ANCHOR, PUMP, SNKR BARS, RDS. LOAD & TEST TO 500#-OK. PUMPING @ 5:00 PM. RIG DOWN.  
 9/10/00: ON 24 HR OPT. PUMPED 35 BO, 103 BW, & 23 MCF.

FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 9/18/00

TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

(This space for State Use)

APPROVED \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY \_\_\_\_\_