

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240
DISTRICT II
P.O. Box Drawer DD, Artesia, NM 88210
DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30 025 32495
5. Indicate Type of Lease STATE FEE
6. State Oil / Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.
1. Type of Well: OIL WELL [checked] GAS WELL OTHER
2. Name of Operator TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator PO BOX 3109, MIDLAND, TX 79702
4. Well Location Unit Letter H 1980 Feet From The NORTH Line and 330 Feet From The EAST Line Section 8 Township 23S Range 37E NMPM LEA COUNTY
10. Elevation (Show whether DF, RKB, RT,GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK [] PLUG AND ABANDON [] REMEDIAL WORK [checked] ALTERING CASING []
TEMPORARILY ABANDON [] CHANGE PLANS [] COMMENCE DRILLING OPERATION [] PLUG AND ABANDONMENT []
PULL OR ALTER CASING [] CASING TEST AND CEMENT JOB []
OTHER: [] OTHER: ACIDIZE [checked]

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
6-19-01: MIRU. NUBOP. PULL 22 JTS TBG W/TBG COLLARS DRAGGING ON EACH JT UNTIL THE 23RD JT.
6-21-01: PU BIT, BIT SUB. DC'S & WS. TAG UP @ 6300 & WORK SPOT W/BIT. RU SWIVEL.
6-22-01: TIH W/CSG SWEDGE, BMPR SUB, JARS, DC'S. PU WS TO 7043. TBG COLLARS HANGING UP.
6-25-01: TIH W/PKR & SN ON TBG. SET PKR @ 6260.
6-26-01: ACIDIZE DRINKARD ABO PERFS 6353-7010 W/4000 GALS 15% NEFE HCL. SCALE SQUEEZE SAME PERFS W/110 GALS TH-756 MIXED IN 20 BBLs 2% KCL WTR. REL PKR. TIH W/RBP & PKR, & SN ON TBG. SET RBP @ 6290. SET PKR @ 6285. TEST RBP TO 1000#-OK. PULL UP & SET PKR @ 6000. LOAD & TEST BACKSIDE W/165 BBLs 2% KCL WTR & TEST TO 500#-OK.
6-27-01: ACIDIZE TUBB PERFS 6090-6241 W/3000 GALS 15% NEFE HCL. SCALE SQUEEZE SAME PERFS W/110 GALS TH-756 MIXED IN 20 BBLs 2% KCL WTR.
6-28-01: REL PKR & TAG SALT FILL @ 6240. WASH OFF SALT TO RBP @ 6290. LATCH & REL RBP. TIH W/TBG, SN, & TAC.
6-29-01: NDBOP. NUWH. TBG @ 7064. SN @ 7033. TAC @ 6031. TIH W/STRAINER NIPPLE, PMP & RDS. LOAD & TEST TO 500#-OK. PUMPING @ 2:00 PM. RIG DOWN.
7-07-01: ON 24 HR OPT. PUMPING 11 BO, 99 BW, & 81 MCF.

DRINKARD ABO/TUBB PERFS: 6090-7010.

FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.
SIGNATURE [Signature] TITLE Engineering Assistant DATE 9/7/01
TYPE OR PRINT NAME J. Denise Leake Telephone No. 915-688-4752
APPROVED [Signature] TITLE PETROLEUM ENGINEER DATE 2006
CONDITIONS OF APPROVAL, IF ANY: TITLE DATE