Linam Ranch Plant Permit: P094-R3 32.688700 -103.285337

# EHS Event 26464 and report 26463

#### **Event:**

A relay for that controls the Spectra/ treater outlet valve failed causing the valve to close causing the plant to lose all inlet compression, the T-70 residue, 1310 and 1420 on low suction. 1420 blew down automatically when it shut down. AGI Flare

Root Cause: IE Circuit Failure


Limit: Blow down valve automatically closed

Start 07/03/21 9:12:00 AM

Discovery 07/03/21 9:12:00 AM

End 07/03/21 9:18:00 AM

# 32 MCF





Composition	Parameter	Compound Value	C L O Serial
P	07/03/21 07:45:00 am - LINAM DISCHARGE - RESIDUE FLARE - FlowGal Mole%	Carbon Dioxide = 0 mo	is VVV
P	07/03/21 07:45:00 am - LINAM DISCHARGE - RESIDUE FLARE - FlowCal Mole%	Methane = 93.514778 mg	is VVV
P	07/03/21 07:45:00 am - LINAM DISCHARGE - RESIDUE FLARE - FlowCal Mole%	Carbon Monoxide = 0 mo	D
P	07/03/21 07:45:00 am - LINAM DISCHARGE - RESIDUE FLARE - FlowCal Mole%	Hydrogen Sulfide = 0 mo	is VVV
P	07/03/21 07:45:00 am - LINAM DISCHARGE - RESIDUE FLARE - FlowCal Mole%	Hexane = 0.000777 mg	is VVV
P	07/03/21 07:45:00 am - LINAM DISCHARGE - RESIDUE FLARE - FlowCal Mole%	Butane = 0.005848 mg	ix VVV
P	07/03/21 07:45:00 am - LINAM DISCHARGE - RESIDUE FLARE - FlowCal Mole%	Pentane = 0.001375 mg	is VVV
P	07/03/21 07:45:00 am - LINAM DISCHARGE - RESIDUE FLARE - FlowCal Mole%	Heptane = 0 mo	1% / / /
P	07/03/21 07:45:00 am - LINAM DISCHARGE - RESIDUE FLARE - FlowCal Mole%	n-Decane = 0 mo	is VVV
P	07/03/21 07:45:00 am - LINAM DISCHARGE - RESIDUE FLARE - FlowCal Mole's	n-Nonane = 0 mo	is VVV
P	07/03/21 07:45:00 am - LINAM DISCHARGE - RESIDUE FLARE - FlowCal Mole%	n-Octane = 0 mo	is VVV
P	07/03/21 07:45:00 am - LINAM DISCHARGE - RESIDUE FLARE - FlowCal Mole%	Nitrogen = 3.009529 mg	is VVV
P	07/03/21 07:45:00 am - LINAM DISCHARGE - RESIDUE FLARE - FlowCal Mole%	Propane = 0.041942 mg	is VVV
P	07/03/21 07:45:00 am - LINAM DISCHARGE - RESIDUE FLARE - FlowCal Mole%	Ethane = 3.421911 mg	(x
P	07/03/21 07:45:00 am - LINAM DISCHARGE - RESIDUE FLARE - FlowCal Mole%	Isobutane = 0.002441 mg	is VVV
P	07/03/21 07:45:00 am - LINAM DISCHARGE - RESIDUE FLARE - FlowCal Mole%	sopentane	is VVV
P	07/03/21 07:45:00 am - LINAM DISCHARGE - RESIDUE FLARE - FlowCal Mole%	Water = 0 mg	is VVV
P	07/03/21 07:45:00 am - LINAM DISCHARGE - RESIDUE FLARE - FlowCal Mole%	Argon = 0 mo	is VVV
P	07/03/21 07:45:00 am - LINAM DISCHARGE - RESIDUE FLARE - FlowCal Mole's	Hydrogen = 0 mo	is VVV
P	07/03/21 07:45:00 am - LINAM DISCHARGE - RESIDUE FLARE - FlowCal Mole%	Helium = 0 mo	1%
P	07/03/21 07:45:00 am - LINAM DISCHARGE - RESIDUE FLARE - FlowCal Mole%	Oxygen = 0 mo	is VVV
P P	07/03/21 07:45:00 am - LINAM DISCHARGE - RESIDUE FLARE - FlowCal	Mole's Mole's	Moles         Hydrogen         = 0 mc           Moles         Hellum         = 0 mc
07/03/21 07:45:00 am - LINAM RAW INLET FLARE - FlowCal M	tole's	Carbon Dioxide = 1.	1482 mol %
p	07/03/21 07:45:00 am - LINAM RAW INLET FLARE - FlowCal Mole%	Methane = 73.4	5544 mol %
P	07/03/21 07:45:00 am - LINAM RAW INLET FLARE - FlowCal Mole%	Carbon Monoxide =	0 mol %
P	07/03/21 07:45:00 am - LINAM RAW INLET FLARE - FlowCal Mole%	Hydrogen Sulfide = 0.3	3308 mol %

P	07/03/21 07:45:00 am - LINAM RAW INLET FLARE - FlowCal Mole <sup>®</sup>	Carbon Dioxide =	1.1482 mol %	~	~	~
P	07/03/21 07:45:00 am - LINAM RAW INLET FLARE - FlowCal Mole%	Methane *	73.6544 mol %	<b>4</b>	~	1
P	07/03/21 07:45:00 am - LINAM RAW INLET FLARE - FlowCal Mole%	Carbon Monoxide =	0 mol %	~	~	1
P	07/03/21 07:45:00 am - LINAM RAW INLET FLARE - FlowCal Mole%	Hydrogen Sulfide   *	0.3308 mol %	4	~	~
P	07/03/21 07:45:00 am - LINAM RAW INLET FLARE - FlowCal Mole's	Hexane =	0,1597 mol %	~	1	<b>✓</b>
P	07/03/21 07:45:00 am - LINAM RAW INLET FLARE - FlowCal Mole%	Butane =	1.554 mol %	1	~	1
P	07/03/21 07:45:00 am - LINAM RAW INLET FLARE - FlowCal Mole%	Pentane =	0.3008 mol %	~	~	<b>V</b>
P	07/03/21 07:45:00 am - LINAM RAW INLET FLARE - FlowCal Mole%	Heptane =	0.074 mol %	<b>V</b>	1	<b>✓</b>
P	■07/03/21 07:45:00 am - LINAM RAW INLET FLARE - FlowCal Mole%	n-Decane =	0 mol %	1	~	<b>V</b>
P	07/03/21 07:45:00 am - LINAM RAW INLET FLARE - FlowCal Mole%	n-Nonane =	0.0005 mol %	<b>~</b>	~	1
P	07/03/21 07:45:00 am - LINAM RAW INLET FLARE - FlowCal Mole%	n-Octane =	0.0155 mol %	~	~	<b>V</b>
P	■07/03/21 07:45:00 am - LINAM RAW INLET FLARE - FlowCal Mole%	Nitrogen =	2.3114 mol %	1	~	<b>V</b>
P	07/03/21 07:45:00 am - LINAM RAW INLET FLARE - FlowCal Mole's	Propane =	6.2943 mol %	1	1	~
P	07/03/21 07:45:00 am - LINAM RAW INLET FLARE - FlowCal Mole%	Ethane =	13.1522 mol %	~	~	<b>V</b>
P	07/03/21 07:45:00 am - LINAM RAW INLET FLARE - FlowCal Mole%	Isobutane =	0.6872 mol %	<b>~</b>	1	<b>✓</b>
P	07/03/21 07:45:00 am - LINAM RAW INLET FLARE - FlowCal Mole's	Isopentane =	0.317 mol %	V	~	1
P	07/03/21 07:45:00 am - LINAM RAW INLET FLARE - FlowCal Mole%	Water =	0 mol %	1	4	<b>V</b>
P	07/03/21 07:45:00 am - LINAM RAW INLET FLARE - FlowCal Mole%	Argon =	0 mol %	<b>~</b>	1	1
P	■07/03/21 07:45:00 am - LINAM RAW INLET FLARE - FlowCal Mole%	Hydrogen =	0 mol %	~	1	1
P	07/03/21 07:45:00 am - LINAM RAW INLET FLARE - FlowCal Mole's	Helium =	0 mol %	1	~	1

Event: 26463

Event, Limit are the same as above.

MCF 559.5

Start 07/03/21 7:45 AM

Discovery 07/03/21 7:45 AM

End Date 07/03/21 08:10 AM

Manual Gas Composition? No

Material Template FlowCal Metered Material

Meters/Streams (Count) 2

Meter or Spill Material 1 LINAM RAW INLET FLARE

Meter 2 LINAM DISCHARGE - RESIDUE FLARE

Gas Volume by Stream 535 Volume Calculator 1

(mscf) - Meter 1

Gas Volume by Stream 24.5 Volume Calculator 2

(mscf) - Meter 2

Criteria Event Totals	Parameter	Compound	Value
P	07/03/21 07:45:00 am - Manual Override Total Event - Speciated - Criteria	Carbon Monoxide =	lb.
P	07/03/21 07:45:00 am - Manual Override Total Event - Speciated - Criteria	Sulfur Dioxide =	- Ib
p	07/03/21 07:45:00 am - Manual Override Total Event - Speciated - Criteria	Nitrogen Oxides =	lb
P	07/03/21 07:45:00 am - Total Event - Speciated - Criteria	Carbon Monoxide =	1,190.259057 lb
P	07/03/21 07:45:00 am - Total Event - Speciated - Criteria	Sulfur Dioxide =	292.938577 lb
P	07/03/21 07:45:00 am - Total Event - Speciated - Criteria	Nitrogen Oxides =	213.253039 lb

Composition	Parameter	Compound	Value	C L O Serial
P	07/03/21 09:12:00 am - Linam AGI Field Flare - FlowCal Mole's	Carbon Dioxide	= 86.223595 mol %	111
P	07/03/21 09:12:00 am - Linam AGI Field Flare - FlowCal Mole*s	Methane	= 0.905681 mol %	4 4 4
P	07/03/21 09:12:00 am - Linam AGI Field Flare - FlowCal Mole's	Carbon Monoxide	■ 0 mol %	4 4 4
P	07/03/21 09:12:00 am - Linam AGI Field Flare - FlowCal Mole's	Hydrogen Sulfide	= 12.073922 mol %	444
P	07/03/21 09:12:00 am - Linam AGI Field Flare - FlowCal Mole's	Hexane	= 0.174643 mol %	4 4 4
P	07/03/21 09:12:00 am - Linam AGI Field Flare - FlowCal Mole's	Butane	= 0.065556 mol %	4 4 4
P	07/03/21 09:12:00 am - Linam AGI Field Flare - FlowCal Mole%	Pentane	= 0.022438 mol %	4 4 4
P	07/03/21 09:12:00 am - Linam AGI Field Flare - FlowCal Mole's	Heptane	= 0 mol %	111
P	07/03/21 09:12:00 am - Linam AGI Field Flare - FlowCal Mole's	n-Decane	= 0 mol %	4 4 4
P	07/03/21 09:12:00 am - Linam AGI Field Flare - FlowCal Mole's	n-Nonane	= 0 mol %	444
P	07/03/21 09:12:00 am - Linam AGI Field Flare - FlowCal Mole%	n-Octane	= 0 mol %	111
P	07/03/21 09:12:00 am - Linam AGI Field Flare - FlowCal Mole's	Nitrogen	■ 0.0517 mol %	444
P	07/03/21 09:12:00 am - Linam ASI Field Flare - FlowCal Mole%	Propane	= 0.135144 mol %	444
P	07/03/21 09:12:00 am - Linam AGI Field Flare - FlowCal Mole's	Ethane	= 0.21683 mol %	V V V
P	07/03/21 09:12:00 am - Linam AGt Field Flare - FlowCal Mole's	Isobutane	= 0.112499 mol %	111
P	07/03/21 09:12:00 am - Linam AGI Field Flare - FlowCal Mole's	Isopentane	= 0.017992 mol %	4 4 4
P	07/03/21 09:12:00 am - Linam AGI Field Flare - FlowCal Mole's	Water	= 0 mol %	4 4 4
P	07/03/21 09:12:00 am - Linam AGI Field Flare - FlowCal Mole%	Argon	= 0 mol %	111
P	07/03/21 09:12:00 am - Linam AGI Field Flare - FlowCal Mole's	Hydrogen	= 0 mol %	4 4 4
P	07/03/21 09:12:00 am - Linam AGI Field Flare - FlowCal Mole%	Helium	= 0 mol %	4 4 4
P	07/03/21 09:12:00 am - Linam AGt Field Flare - FlowCal Mole's	Oxygen	= 0 mol %	111
P	07/03/21 09:12:00 am - AGI Flare Agaist - FlowCal Mole%	Carbon Dioxide	= 0.000167 mol %	111
P	07/03/21 09:12:00 am - AGI Flare Asaist - FlowCal Mole's	Methane	= 92.090721 mol %	444
P	07/03/21 09:12:00 am - AGI Flare Agains - FlowCal Mole%	Carbon Monoxide	= 0 mol %	444
P	07/03/21 09:12:00 am - AGI Flare Assist - FlowCal Mole%	Hydrogen Sulfide	= 0 mol %	111
P	■07/03/21 09:12:00 am - AGI Flare Addist - FlowCal Mole%	Hexane	= 0 mol %	111
P	07/03/21 09:12:00 am - AGI Flare Assist - FlowCal Mole%	Butane	= 0 mol %	111

P	07/03/21 09:12:00 am - AGI Flare Assist - FlowCal Mole%	Pentane	= 0 mol %	~	4	4
P	07/03/21 09:12:00 am - AGI Flare Assist - FlowCal Mole%	Heptane	= 0 mal %	V	· ~	1
P	07/03/21 09:12:00 am - AGI Flare Assist - FlowCal Mole's	n-Decane	= 0 mol %	~	1	1
P	07/03/21 09:12:00 am - AGI Flare Assist - FlowCal Mole's	n-Nonane	= 0 mol %	~	1	4
P	07/03/21 09:12:00 am - AGI Flare Assist - FlowCal Mole's	n-Octane	= 0 mol %	4	1	1
P	07/03/21 09:12:00 am - AGI Flare Assist - FlowCal Mole%	Nitrogen	= 3.112708 mol %	~	1	1
P	07/03/21 09:12:00 am - AGI Flare Assist - FlowCal Mole%	Propane	= 0.049759 mol %	~	~	4
P	07/03/21 09:12:00 am - AGI Flare Assist - FlowCal Mole%	Ethane	= 4.746645 mol %	~	· ~	<b>V</b>
P	07/03/21 09:12:00 am - AGI Flare Assist - FlowCal Mole*	Isobutane	= 0 mol %	V	4	V
P	07/03/21 09:12:00 am - AGI Flare Assist - FlowCal Mole's	Isopentane	= 0 mol %	4	1	1
P	07/03/21 09:12:00 am - AGI Flare Assist - FlowCal Mole's	Water	= 0 mol %	~	1	V
P	07/03/21 09:12:00 am - AGI Flare Assist - FlowCal Mole's	Argon	= 0 mol %	~	1	1
P	07/03/21 09:12:00 am - AGI Flare Assist - FlowCal Molets	Hydrogen	= 0 mol %	~	1	4
P	07/03/21 09:12:00 am - AGI Flare Assist - FlowCal Mole%	Helium	= 0 mol %	~	1	4
P	07/03/21 09:12:00 am - AGI Flare Assist - FlowCal Mole%	Oxygen	= 0 mol %	~	· ~	1
P	07/03/21 09:12:00 am - Event Mole% Consistency Check		= 100 mol %	~	1	4
P	07/03/21 09:12:00 am - Gas Volume Flared		= 32,000 scf	~	· ~	1
P	<b>07/03/21 09:12:00 am</b> - Gas Volume Vented		= 0 scf	1	1	1

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

# **State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS

Action 35079

## **QUESTIONS**

Operator:	OGRID:
DCP OPERATING COMPANY, LP	36785
370 17th Street, Suite 2500	Action Number:
Denver, CO 80202	35079
	Action Type:
	[C-129] Venting and/or Flaring (C-129)

### QUESTIONS

Determination of Reporting Requirements				
Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide addional guidance.				
Was or is this venting or flaring caused by an emergency or malfunction	Yes			
Did or will this venting or flaring last eight hours or more cumulatively within any 24-hour period from a single event	No			
Is this considered a submission for a notification of a major venting or flaring	Yes, major venting or flaring of natural gas.			
The operator shall file a form C-141 instead of a form C-129 for a release that includes liquid during venting or flaring that is or may be a major or minor release under				
Was there or will there be at least 50 MCF of natural gas vented or flared during this event	Yes			
Did this venting or flaring result in the release of <b>ANY</b> liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No			

Unregistered Facility Site		
Please provide the facility details, if the venting or flaring occurred or is occuring at a facility that does not have an Facility ID (f#) yet.		
Facility or Site Name Not answered.		
Facility Type	Not answered.	

Equipment Involved		
Primary Equipment Involved	Not answered.	
Additional details for Equipment Involved. Please specify	Linam Ranch Plant Permit: P094-R3 32.688700 -103.285337 EHS Event 26464 and report 26463 Event: A relay for that controls the Spectra/ treater outlet valve failed causing the valve to close causing the plant to lose all inlet compression, the T-70 residue, 1310 and 1420 on low suction. 1420 blew down automatically when it shut down. AGI Flare Root Cause: IE Circuit Failure Limit: Blow down valve automatically closed Start 07/03/21 9:12:00 AM Discovery 07/03/21 9:12:00 AM End 07/03/21 9:18:00 AM	

Representative Compositional Analysis of Vented or Flared Natural Gas			
Please provide the mole percent for the percentage questions in this group.			
Methane (CH4) percentage	94		
Nitrogen (N2) percentage, if greater than one percent	3		
Hydrogen Sulfide (H2S) PPM, rounded up	0		
Carbon Dioxide (C02) percentage, if greater than one percent	0		
Oxygen (02) percentage, if greater than one percent	0		
If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.			
Methane (CH4) percentage quality requirement	Not answered.		
Nitrogen (N2) percentage quality requirement	Not answered.		
Hydrogen Sufide (H2S) PPM quality requirement	Not answered.		
Carbon Dioxide (C02) percentage quality requirement	Not answered.		
Oxygen (02) percentage quality requirement	Not answered.		

Date(s) and Time(s)	
Date venting or flaring was discovered or commenced	07/03/2021
Time venting or flaring was discovered or commenced	09:12 AM
Is the venting or flaring event complete	Yes
Date venting or flaring was terminated	07/03/2021
Time venting or flaring was terminated	09:18 AM
Total duration of venting or flaring in hours, if venting or flaring has terminated	1
Longest duration of cumulative hours within any 24-hour period during this event	1

Measured or Estimated Volume of Vented or Flared Natural Gas	
Natural Gas Vented (Mcf) Details	Not answered.
Natural Gas Flared (Mcf) Details	Cause: Other   Gas Plant   Natural Gas Flared   Spilled: 592 Mcf   Recovered: 0 Mcf   Lost: 592 Mcf
Other Released Details	Not answered.
Additional details for Measured or Estimated Volume(s). Please specify	Linam Ranch Plant Permit: P094-R3 32.688700 -103.285337 EHS Event 26464 and report 26463 Event: A relay for that controls the Spectra/ treater outlet valve failed causing the valve to close causing the plant to lose all inlet compression, the T-70 residue, 1310 and 1420 on low suction. 1420 blew down automatically when it shut down. AGI Flare Root Cause: IE Circuit Failure Limit: Blow down valve automatically closed Start 07/03/21 9:12:00 AM Discovery 07/03/21 9:12:00 AM End 07/03/21 9:18:00 AM
Is this a gas only submission (i.e. only Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.

Venting or Flaring Resulting from Downstream Activity	
Was or is this venting or flaring a result of downstream activity	Not answered.
Date notified of downstream activity requiring this venting or flaring	Not answered.
Time notified of downstream activity requiring this venting or flaring	Not answered.

Steps and Actions to Prevent Waste		
For this event, the operator could not have reasonably anticipated the current event and it was beyond the operator's control.	True	
Please explain reason for why this event was beyond your operator's control	Event: A relay for that controls the Spectra/ treater outlet valve failed causing the valve to close causing the plant to lose all inlet compression, the T-70 residue, 1310 and 1420 on low suction. 1420 blew down automatically when it shut down. AGI Flare Root Cause: IE Circuit Failure Limit: Blow down valve automatically closed	
Steps taken to limit the duration and magnitude of venting or flaring	Event: A relay for that controls the Spectra/ treater outlet valve failed causing the valve to close causing the plant to lose all inlet compression, the T-70 residue, 1310 and 1420 on low suction. 1420 blew down automatically when it shut down. AGI Flare Root Cause: IE Circuit Failure Limit: Blow down valve automatically closed	
Corrective actions taken to eliminate the cause and reoccurrence of venting or flaring	Event: A relay for that controls the Spectra/ treater outlet valve failed causing the valve to close causing the plant to lose all inlet compression, the T-70 residue, 1310 and 1420 on low suction. 1420 blew down automatically when it shut down. AGI Flare Root Cause: IE Circuit Failure Limit: Blow down valve automatically closed	

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

CONDITIONS

Action 35079

## **CONDITIONS**

Operator:	OGRID:
DCP OPERATING COMPANY, LP	36785
370 17th Street, Suite 2500	Action Number:
Denver, CO 80202	35079
	Action Type:
	[C-129] Venting and/or Flaring (C-129)

#### CONDITIONS

Created By	Condition	Condition Date
system	If the information provided in this report requires an amendment, submit a [C-129] Request to Amend Venting and/or Flaring Incident, utilizing your incident number from this event.	7/6/2021