

September 14, 2022

District Supervisor
Oil Conservation Division, District 1
1625 North French Drive
Hobbs, New Mexico 88240

Re: REVISED

Liner Inspection and Closure Request
ConocoPhillips (Heritage Concho)
Super Cobra State Com #001H Battery Valve Release
Unit Letter I, Section 13, Township 19 South, Range 34 East
Lea County, New Mexico
Incident ID# NAPP2218128367

Sir or Madam:

Tetra Tech, Inc. (Tetra Tech) was contacted by ConocoPhillips to assess a release that occurred from an equipment failure at the Super Cobra State Com #001H Battery. The release footprint is located in Public Land Survey System (PLSS) Unit Letter I, Section 13, Township 19 South, Range 34 East, in Lea County, New Mexico (Site). The approximate release point occurred at coordinates 32.658672°, -103.507145°, as shown on Figures 1 through 3.

BACKGROUND

According to the State of New Mexico Form C-141 Initial Report (Appendix A), the release was discovered on June 20, 2020. The release occurred as the result of equipment failure, specifically a crack in a liquid kimray valve.

Approximately 8.4 barrels (bbls) of produced water were reported released, of which 8.4 bbls were recovered. The produced water was released into a lined secondary containment. The volume determination submitted to the NMOCD along with the C-141 documented that all fluids were removed from the secondary containment and back calculated that 8.4 bbls of produced water were released based upon the volume recovered by the vacuum truck. Brittany N. Esparza submitted the initial Form C-141 on June 30, 2022. The NMOCD approved the initial C-141 on July 5, 2022, and subsequently assigned the release the Incident ID NAPP2218128367.

SITE CHARACTERIZATION

A site characterization was performed and no sinkholes, residences, schools, hospitals, institutions, churches, springs, private domestic water wells, wetlands, incorporated municipal boundaries, subsurface mines, or floodplains are located within the distances specified in 19.15.29 New Mexico Administrative Code (NMAC). The Site is in an area of low karst potential. An NMOSE stream body was identified in the release footprint vicinity, however it is located approximately 400 feet from the lateral extents of the release.

According to the New Mexico Office of the State Engineers (NMOSE) reporting system, there are no water wells within $\frac{1}{2}$ mile (800 meters) of the Site. There is one (1) water well within 1,600 meters of the site with a depth to groundwater of 60 feet below ground surface (bgs). The site characterization data is included in Appendix B.

Tetra Tech

901 West Wall St., Suite 100, Midland, TX 79701

REGULATORY FRAMEWORK

Based upon the release footprint and in accordance with Subsection E of 19.15.29.12 NMAC, per 19.15.29.11 NMAC, the site characterization data was used to determine recommended remedial action levels (RRALs) for benzene, toluene, ethylbenzene, and xylene (collectively referred to as BTEX), total petroleum hydrocarbons (TPH), and chlorides in soil.

Based on the relative absence of water wells within $\frac{1}{2}$ mile of the Site, the strictest Table I closure criteria will be applied to this release incident in lieu of drilling a boring for groundwater depth verification. Thus, based on the site characterization, and in accordance with Table I of 19.15.29.12 NMAC, the RRALs for the Site are as follows:

Constituent	Site RRAL
Chloride	600 mg/kg
TPH (GRO+DRO+ORO)	100 mg/kg
ВТЕХ	50 mg/kg
Benzene	10 mg/kg

SITE VISIT SUMMARY

On August 5, 2022, Tetra Tech personnel were at the Site to assess current site conditions and take photographs of the impacted area, if any. Photos provided by COP personnel to Tetra Tech indicate the release area footprint and were reviewed prior to the site visit. The photographs are provided in Appendix C.

During the site visit, no evidence of a release was observed in the northern portion of the tank battery secondary containment. The secondary containment is made up of steel walls approximately 2 feet tall with an intact polyethylene liner. The liner was exposed and intact at the time of the site visit. As mentioned, the release was reported as having been contained within the lined secondary containment and, as documented in the C-141, initial response efforts were successful in recovering all released fluids. Photographic documentation of site conditions at the time of the site visit is included in Appendix C.

LINER INTEGRITY

In accordance with 19.15.29.11(A)(5)(a) NMAC, notification of a liner inspection at the Super Cobra State Com #001H Battery was sent via email to the NMOCD on August 2, 2022. The liner inspection notification email correspondence is included in Appendix D.

On August 5, 2022, Tetra Tech personnel performed an inspection of the liner within the secondary containment of the Super Cobra State Com #001H Battery. The liner was observed to underlie the entirety of the tank battery secondary containment area. The liner was intact with no visible rips or tears and encompassed by a 2-foot-tall steel wall. The liner extended up the steel "muscle" wall. At the time of the liner inspection, a minimal amount of stormwater had accumulated in the lined area due to recent rain events. The standing water lends further evidence to the integrity of the liner as a competent fluid barrier. At the time of the inspection, the liner was intact and had the ability to contain the leak in question. Photographic documentation of the liner inspection is included in Appendix C.

LINER INSPECTION AND CLOSURE REQUEST

The Initial Liner Inspection and Closure Request was prepared by Tetra Tech on behalf of ConocoPhillips and submitted to NMOCD on September 13, 2022, with fee application payment PO Number 8G8CH-220913-C-1410. Inadvertently, an incomplete C-141 was submitted along with the report. The Closure Request was rejected via email by Jocelyn Harimon the same day, stating the report was rejected for the following reasons:

A closure report cannot be reviewed without the corresponding C-141 closure pages. The OCD requires all C- 141 pages to be completely filled out, signed and dated when submitting.

A copy of the NMOCD correspondence is included as Appendix C. The completed, signed and dated C-141 forms are included with this revised submittal.

CONCLUSION

Based on the results of the liner inspection, ConocoPhillips respectfully requests closure of the subject incident. The release occurred within a lined containment area. The liner integrity demonstration is complete. The affected area of the liner has been visually inspected where the release occurred, and the liner remains intact and had the ability to contain the leak in question. Two business days' notice was provided to the appropriate division district office before conducting the liner inspection.

The final C-141 forms are enclosed in Appendix A. If you have any questions concerning the liner inspection for the Site, please call me at (432) 210-6952 or Christian at (512) 288-6281.

Sincerely,

Tetra Tech, Inc.

Joe Tyler

Project Manager

Christian M, Llull, P.G Program Manager

CC:

Mr. Charles Beauvais, PBU - ConocoPhillips

ConocoPhillips

LIST OF ATTACHMENTS

Figures:

Figure 1 – Overview Map

Figure 2 – Topographic Map

Figure 3 – Site Feature Map and Release Extent

Appendices:


Appendix A – C-141 Forms


Appendix B – Site Characterization Data


Appendix C – Photographic Documentation

Appendix D – Regulatory Correspondence

FIGURES







APPENDIX A C-141 Forms

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party OGR				OGRID			
Contact Name				Contact T	ontact Telephone		
Contact email				Incident #	Incident # (assigned by OCD)		
Contact mail	ing address			<u> </u>			
			Location	of Release S	Source		
Latitude				Longitude			
			(NAD 83 in dec	cimal degrees to 5 deci	imal places)		
Site Name				Site Type			
Date Release	Discovered			API# (if ap	pplicable)		
Unit Letter	Section	Township	Range	Cou	nty	_	
Surface Owner	r: State	☐ Federal ☐ Tr	ribal Drivata ()	Nama		,	
Surface Owner	i. State	rederar 11	ibai 🔲 Fiivate (1	vame)	
			Nature and	d Volume of	Release		
	Materia	l(s) Released (Select al	ll that annly and attach	calculations or specifi	e justification for th	ne volumes provided below)	
Crude Oil		Volume Release		curculations of specifi		overed (bbls)	
Produced	Water	Volume Release	ed (bbls)		Volume Recovered (bbls)		
			tion of dissolved c	hloride in the	☐ Yes ☐ No		
	4.	produced water			1411)		
Condensa		Volume Release			Volume Recovered (bbls)		
Natural G		Volume Release			Volume Recovered (Mcf)		
Other (describe) Volume/Weight Released (provide units			e units)	Volume/We	ight Recovered (provide units)		
Cause of Rele	ease						

Received by OCD: 9/14/2022/10:47:021M State of New Mexico Page 2 Oil Conservation Division

Pa	ge	41	Df.	32
----	----	----	-----	----

Incident ID	
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC? ☐ Yes ☐ No	If YES, for what reason(s) does the resp	onsible party consider this a major release?
If YES, was immediate no	otice given to the OCD? By whom? To v	whom? When and by what means (phone, email, etc)?
	Initial I	Response
The responsible	party must undertake the following actions immedia	ely unless they could create a safety hazard that would result in injury
☐ The source of the rele	ease has been stopped.	
☐ The impacted area ha	s been secured to protect human health an	d the environment.
Released materials ha	ave been contained via the use of berms or	dikes, absorbent pads, or other containment devices.
☐ All free liquids and re	ecoverable materials have been removed a	nd managed appropriately.
has begun, please attach	a narrative of actions to date. If remedia	remediation immediately after discovery of a release. If remediation l efforts have been successfully completed or if the release occurred please attach all information needed for closure evaluation.
regulations all operators are public health or the environr failed to adequately investig	required to report and/or file certain release no ment. The acceptance of a C-141 report by the ate and remediate contamination that pose a th	e best of my knowledge and understand that pursuant to OCD rules and tifications and perform corrective actions for releases which may endanger OCD does not relieve the operator of liability should their operations have reat to groundwater, surface water, human health or the environment. In f responsibility for compliance with any other federal, state, or local laws
Printed Name		Title:
Signature:	tangoparge	Date:
email:		Telephone:
OCD Only		
Received by:Jocelyn	Harimon	Date:07/05/2022

					L	48 Spill V	olume Estimate	Form	
Received by OCD	: 9/14/2	022 10	1:47:02 AM ber:	Super Cobra St #1		100			Page 12 of 32
(2.			Asset Area:	DBE				NAPP221	8128367
12.	Releas	e Disco	very Date & Time:	6/20/2022 10:20					
(A			Release Type:	Produced Water					
Provide a	ny know	n details	s about the event:	liquid kem ray cracl	ked on diss charg	e side od pun	np		
					Spil	l Calculation	n - On Pad Surface	Pool Spill	
Convert Irregular shape into a series of rectangles	Length (ft.)	Width (ft.)	Deepest point in each of the areas (in.)	No. of boundaries of "shore" in each area	Estimated <u>Pool</u> Area (sq. ft.)	Estimated Average Depth (ft.)	Estimated volume of each pool area (bbl.)	Penetration allowance (ft.)	Total Estimated Volume of Spill (bbl.)
Rectangle A	117.0	33.0	0.50	4	3861.000	0.010	7.159	0.001	7.163
Rectangle B	54.0	9.0	0.50	3	486.000	0.014	1.202	0.001	1.202
Rectangle C					0.000	#DIV/0!	#DIV/0!	#DIV/0!	#DIV/0!
Rectangle D					0.000	#DIV/0!	#DIV/0!	#DIV/0!	#DIV/0!
Rectangle E					0.000	#DIV/0!	#DIV/0!	#DIV/0!	#DIV/0!
Rectangle F					0.000	#DIV/0!	#DIV/0!	#DIV/0!	#DIV/0!
Rectangle G					0.000	#DIV/0!	#DIV/0!	#DIV/0!	#DIV/0!
Rectangle H					0.000	#DIV/0!	#DIV/0!	#DIV/0!	#DIV/0!

0.000

0.000

#DIV/0!

#DIV/0!

#DIV/0!

#DIV/0!

#DIV/0!

#DIV/0!

Total Volume Release:

#DIV/0!

#DIV/0!

8.365

Released to Imaging: 9/15/2022 2:45:26 PM

Rectangle I

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 122661

CONDITIONS

Operator:	OGRID:
COG OPERATING LLC	229137
600 W Illinois Ave	Action Number:
Midland, TX 79701	122661
	Action Type:
	[C-141] Release Corrective Action (C-141)

CONDITIONS

Created By		Condition Date
jharimon	None	7/5/2022

Received by OCD: 9/14/2022 10:47:02 AM
Form C-141 State of New Mexico
Page 3 Oil Conservation Division

_		Page
	Incident ID	
ion	District RP	
	Facility ID	
	Application ID	

Site Assessment/Characterization

 $This information \ must \ be \ provided \ to \ the \ appropriate \ district \ of fice \ no \ later \ than \ 90 \ days \ after \ the \ release \ discovery \ date.$

What is the shallowest depth to groundwater beneath the area affected by the release?	(ft bgs)				
Did this release impact groundwater or surface water?					
Are the lateral extents of the release within 300 feet of a continuously flowing watercourse or any other significant watercourse?	☐ Yes ☐ No				
Are the lateral extents of the release within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)?					
Are the lateral extents of the release within 300 feet of an occupied permanent residence, school, hospital, institution, or church?	☐ Yes ☐ No				
Are the lateral extents of the release within 500 horizontal feet of a spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes?	☐ Yes ☐ No				
Are the lateral extents of the release within 1000 feet of any other fresh water well or spring?	☐ Yes ☐ No				
Are the lateral extents of the release within incorporated municipal boundaries or within a defined municipal fresh water well field?	☐ Yes ☐ No				
Are the lateral extents of the release within 300 feet of a wetland?	☐ Yes ☐ No				
Are the lateral extents of the release overlying a subsurface mine?	☐ Yes ☐ No				
Are the lateral extents of the release overlying an unstable area such as karst geology?					
Are the lateral extents of the release within a 100-year floodplain?	☐ Yes ☐ No				
Did the release impact areas not on an exploration, development, production, or storage site?					
Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics.					
Characterization Report Checklist: Each of the following items must be included in the report.					
Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells. Field data Data table of soil contaminant concentration data Depth to water determination Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release Boring or excavation logs Photographs including date and GIS information Topographic/Aerial maps Laboratory data including chain of custody					

If the site characterization report does not include completed efforts at remediation of the release, the report must include a proposed remediation plan. That plan must include the estimated volume of material to be remediated, the proposed remediation technique, proposed sampling plan and methods, anticipated timelines for beginning and completing the remediation. The closure criteria for a release are contained in Table 1 of 19.15.29.12 NMAC, however, use of the table is modified by site- and release-specific parameters.

Received by OCD: 9/14/2022 10:47:02 AM Form C-141 State of New Mexico Page 4 Oil Conservation Division

	Page 15 of 32
Incident ID	
District RP	
Facility ID	
A1' ID	

I hereby certify that the information given above is true and complete to the	best of my knowledge and understand that pursuant to OCD rules and
regulations all operators are required to report and/or file certain release not	
public health or the environment. The acceptance of a C-141 report by the	OCD does not relieve the operator of liability should their operations have
failed to adequately investigate and remediate contamination that pose a thr	eat to groundwater, surface water, human health or the environment. In
addition, OCD acceptance of a C-141 report does not relieve the operator of	f responsibility for compliance with any other federal, state, or local laws
and/or regulations.	
Printed Name:	Title:
Timed Name.	Title:
Signature: Charles R. Beauvais 99	Deter
Signature: Charace X. Detabate 17	Date:
email:	Telephone:
OCD Only	
Received by: Jocelyn Harimon	Date: 09/14/2022
Treceived by:	Dutc

Received by OCD: 9/14/2022	2 10:47:02 AM
Form C-141	State of New Mexico
Page 6	Oil Conservation Division

	Page 16 of 32
Incident ID	
District RP	
Facility ID	
Application ID	

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following items must be included in the closure report.

☐ A scaled site and sampling diagram as described in 19.15.29.1	1 NMAC
Photographs of the remediated site prior to backfill or photos must be notified 2 days prior to liner inspection)	of the liner integrity if applicable (Note: appropriate OCD District office
☐ Laboratory analyses of final sampling (Note: appropriate ODC	C District office must be notified 2 days prior to final sampling)
☐ Description of remediation activities	
and regulations all operators are required to report and/or file certain may endanger public health or the environment. The acceptance of	ntions. The responsible party acknowledges they must substantially nditions that existed prior to the release or their final land use in OCD when reclamation and re-vegetation are complete.
Signature: Charles R. Beauvais 99	
email:	Telephone:
OCD Only	
Received by: Jocelyn Harimon	Date:09/14/2022
	of liability should their operations have failed to adequately investigate and water, human health, or the environment nor does not relieve the responsible or regulations.
Closure Approved by:	Date:
Printed Name:	

APPENDIX BSite Characterization Data



New Mexico Office of the State Engineer Water Column/Average Depth to Water

No records found.

UTMNAD83 Radius Search (in meters):

Easting (X): 639998.318 **Northing (Y):** 3614432 **Radius:** 800



New Mexico Office of the State Engineer Water Column/Average Depth to Water

(A CLW##### in the POD suffix indicates the POD has been replaced & no longer serves a water right file.) (R=POD has been replaced, O=orphaned, C=the file is

closed)

(quarters are 1=NW 2=NE 3=SW 4=SE)

(quarters are smallest to largest)

(NAD83 UTM in meters)

(In feet)

 POD

 Sub Q Q Q
 Depth Depth Water

 POD Number
 Code basin County 64 16 4 Sec Tws Rng
 X
 Y
 Distance Well Water Column

 L 08234 S
 L LE 4 4 1 18 19S 35E 640871 3614751* ● 929 106 60 46
 929 106 60 46

Average Depth to Water: 60 feet

Minimum Depth: 60 feet

Maximum Depth: 60 feet

Record Count: 1

UTMNAD83 Radius Search (in meters):


Easting (X): 639998.318 **Northing (Y):** 3614432 **Radius:** 1600

*UTM location was derived from PLSS - see Help


The data is furnished by the NMOSE/ISC and is accepted by the recipient with the expressed understanding that the OSE/ISC make no warranties, expressed or implied, concerning the accuracy, completeness, reliability, usability, or suitability for any particular purpose of the data.

8/26/22 11:36 AM


WATER COLUMN/ AVERAGE DEPTH TO WATER



New Mexico NFHL Data



August 26, 2022



FEMA, Esri, HERE, Garmin, (c) OpenStreetMap contributors, and the GIS user community, Source: Esri, Maxar, Earthstar Geographics, and the GIS

APPENDIX C Photographic Documentation




TETRA TECH, INC. PROJECT NO.	DESCRIPTION	Initial response photo of release point provided by COP representatives onsite at that time.	1
212C-MD-02810	SITE NAME	ConocoPhillips Super Cobra Battery Valve Release	7/11/2022




TETRA TECH, INC. PROJECT NO.	DESCRIPTION	Initial response photo of release within the secondary containment provided by COP representatives onsite.	2
212C-MD-02810	SITE NAME	ConocoPhillips Super Cobra Battery Valve Release	7/11/2022



TETRA TECH, INC.	ETRA TECH, INC. DESCRIPTION PROJECT NO.	View of the Super Cobra Battery signage.	3
212C-MD-02810	SITE NAME	ConocoPhillips Super Cobra Battery Valve Release	8/05/2022




TETRA TECH, INC. PROJECT NO.	DESCRIPTION	View West of the battery.	4
212C-MD-02810	SITE NAME	ConocoPhillips Super Cobra Battery Valve Release	8/05/2022




TETRA TECH, INC. PROJECT NO.	DESCRIPTION	Release point area after valve replacement.	5
212C-MD-02810	SITE NAME	ConocoPhillips Super Cobra Battery Valve Release	8/05/2022



TETRA TECH, INC. PROJECT NO.	DESCRIPTION	View inside the secondary containment of intact liner with no visual evidence of release remaining.	6
212C-MD-02810	SITE NAME	ConocoPhillips Super Cobra Battery Valve Release	8/11/2022



TETRA TECH, INC. DESCR	DESCRIPTION	View inside the secondary containment of intact liner with no visual evidence of release remaining.	7
212C-MD-02810	SITE NAME	ConocoPhillips Super Cobra Battery Valve Release	8/05/2022



TETRA TECH, INC. PROJECT NO.	DESCRIPTION	View inside the secondary containment of intact liner with no visual evidence of release remaining.	8
212C-MD-02810	SITE NAME	ConocoPhillips Super Cobra Battery Valve Release	8/05/2022



TETRA TECH, INC. PROJECT NO. 212C-MD-02810	DESCRIPTION	View inside the secondary containment of intact liner with no visual evidence of release remaining.	9
	SITE NAME	ConocoPhillips Super Cobra Battery Valve Release	8/05/2022



TETRA TECH, INC. PROJECT NO. 212C-MD-02810	DESCRIPTION	View inside the secondary containment of intact liner with no visual evidence of release remaining.	10
	SITE NAME	ConocoPhillips Super Cobra Battery Valve Release	8/05/2022

APPENDIX D Regulatory Correspondence

Tyler, Joe

From: Nobui, Jennifer, EMNRD < Jennifer.Nobui@state.nm.us>

Sent: Tuesday, August 2, 2022 5:04 PM

To: Tyler, Joe

Cc: Bratcher, Mike, EMNRD; Hamlet, Robert, EMNRD; Harimon, Jocelyn, EMNRD

Subject: FW: [EXTERNAL] Incident ID: NAPP2218128367 - Liner Inspection

A CAUTION: This email originated from an external sender. Verify the source before opening links or attachments. **A**

Joe

Thank you for the notification. Please include a copy of this and all notifications in the remedial and/or closure reports to ensure the notifications are documented in the project file.

Thanks, Jennifer Nobui

From: Enviro, OCD, EMNRD < OCD. Enviro@state.nm.us>

Sent: Tuesday, August 2, 2022 3:53 PM

To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Nobui, Jennifer, EMNRD <Jennifer.Nobui@state.nm.us>; Harimon, Jocelyn, EMNRD <Jocelyn.Harimon@state.nm.us>; Velez, Nelson, EMNRD <Nelson.Velez@state.nm.us>;

Hamlet, Robert, EMNRD < Robert. Hamlet@state.nm.us>

Subject: Fw: [EXTERNAL] Incident ID: NAPP2218128367 - Liner Inspection

From: Tyler, Joe < <u>Joe.Tyler@tetratech.com</u>>
Sent: Tuesday, August 2, 2022 3:47 PM

To: Enviro, OCD, EMNRD < ocn.enviro@state.nm.us <a href="https://ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.enviro.ocn.envir

Subject: [EXTERNAL] Incident ID: NAPP2218128367 - Liner Inspection

CAUTION: This email originated outside of our organization. Exercise caution prior to clicking on links or opening attachments.

Incident ID (n#) NAPP2218128367 (Super Cobra St Com #1 Battery Release)

To whom it may concern,

In accordance with Subsection A of 19.15.29.11 NMAC, the responsible party must verbally notify the appropriate division district office prior to conducting the liner inspection.

Thus, on behalf of ConocoPhillips for the above referenced incident, Tetra Tech is duly providing this communication which serves as notification that a liner inspection will be conducted at this site on August 5, 2022.

NOTE: If you have any questions regarding this schedule, please contact me.

Joe Tyler | Staff Geologist

Mobile +1 (432) 210-6952 | Direct +1 (432) 687-8144 | joe.tyler@tetratech.com

Tetra Tech | *Leading with Science*[®] | OGA-Midland 901 West Wall, Suite 100 | Midland, Texas | tetratech.com

This message, including any attachments, may include privileged, confidential and/or inside information. Any distribution or use of this communication by anyone other than the intended recipient is strictly prohibited and may be unlawful. If you are not the intended recipient, please notify the sender by replying to this message and then delete it from your system.







Please consider the environment before printing. Read more



Llull, Christian

From: OCDOnline@state.nm.us

Sent: Tuesday, September 13, 2022 4:23 PM

To: Llull, Christian

Subject: The Oil Conservation Division (OCD) has rejected the application, Application ID: 143012

⚠ CAUTION: This email originated from an external sender. Verify the source before opening links or attachments. ⚠

To whom it may concern (c/o Christian Llull for COG OPERATING LLC),

The OCD has rejected the submitted Application for administrative approval of a release notification and corrective action (C-141), for incident ID (n#) nAPP2218128367, for the following reasons:

A closure report cannot be reviewed without the corresponding C-141 closure pages. The OCD requires all C-141 pages to be completely filled out, signed and dated when submitting.

The rejected C-141 can be found in the OCD Online: Permitting - Action Status, under the Application ID: 143012. Please review and make the required correction(s) prior to resubmitting.

If you have any questions why this application was rejected or believe it was rejected in error, please contact me prior to submitting an additional C-141.

Thank you, Jocelyn Harimon **Environmental Specialist** 575-748-1283 Jocelyn.Harimon@state.nm.us

New Mexico Energy, Minerals and Natural Resources Department 1220 South St. Francis Drive Santa Fe, NM 87505

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 143271

CONDITIONS

Operator:	OGRID:
COG OPERATING LLC	229137
600 W Illinois Ave	Action Number:
Midland, TX 79701	143271
	Action Type:
	[C-141] Release Corrective Action (C-141)

CONDITIONS

Created By		Condition Date
jnobui	Closure Report Approved.	9/15/2022