



## Certificate of Analysis

Number: 6030-25081176-001A

Artesia Laboratory

200 E Main St.  
Artesia, NM 88210  
Phone 575-746-3481Chandler Montgomery  
Occidental Petroleum  
1502 W Commerce Dr.  
Carlsbad, NM 88220

|                   |                                       |                    |                                   |
|-------------------|---------------------------------------|--------------------|-----------------------------------|
| Field:            | PERMIAN_RESOURCES                     | Report Date:       | 09/07/2025                        |
| Station Name:     | GOLD CTB TRAIN 2 CHECK (FMP) -- Meter | Sampled By:        | JE                                |
| Station Number:   | 17222C                                | Sample Of:         | Gas                               |
| Station Location: | OP-L2111-BT002                        | Sample Type:       | Spot                              |
| Sample Point:     | Meter                                 | Sample Conditions: | 101 psig, @ 95 °F Ambient: 100 °F |
| Property ID:      | FMP/LSE NMNM138937                    | Sample Date:       | 08/26/2025 12:25                  |
| Formation:        | NEW_MEXICO                            | Received Date:     | 08/27/2025                        |
| County:           | Eddy, NM                              | Login Date:        | 08/27/2025                        |
| Well Name:        | CTB                                   | Effective Date:    | 09/01/2025                        |
| Type of Sample :  | Spot-Cylinder                         | Flow Rate:         | 28242 MSCFD                       |
| Sampling Company: | SPL - OXY                             | Sampling Method:   | Purge/Fill                        |
| Instrument:       | 70142339 (Inficon GC-MicroFusion)     | Heating Method:    | Heat Trace                        |
| Last Inst. Cal.:  | 09/02/2025 0:00 AM                    | PO/Ref. No:        | 4502756513                        |
| Analyzed:         | 09/02/2025 09:57:27 by CDW            | Method:            | GPA 2286                          |
|                   |                                       | Cylinder No:       | 9999-005159                       |

## Analytical Data

| Components       | Un-normalized<br>Mol % | Mol. %   | Wt. %    | GPM at<br>14.65 psia |               |
|------------------|------------------------|----------|----------|----------------------|---------------|
| Hydrogen Sulfide | 0.0000                 | 0.0000   | 0.0000   |                      | GPM TOTAL C2+ |
| Nitrogen         | 1.7718                 | 1.7571   | 2.2056   |                      | 6.422         |
| Carbon Dioxide   | 1.1354                 | 1.1260   | 2.2205   |                      |               |
| Methane          | 75.3486                | 74.7252  | 53.7164  |                      |               |
| Ethane           | 11.9247                | 11.8260  | 15.9340  | 3.157                |               |
| Propane          | 5.9484                 | 5.8992   | 11.6562  | 1.622                |               |
| Iso-Butane       | 0.8306                 | 0.8237   | 2.1453   | 0.269                |               |
| n-Butane         | 2.0062                 | 1.9896   | 5.1817   | 0.626                |               |
| Iso-Pentane      | 0.4903                 | 0.4862   | 1.5719   | 0.178                |               |
| n-Pentane        | 0.5490                 | 0.5445   | 1.7603   | 0.197                |               |
| Hexanes          | 0.3430                 | 0.3402   | 1.3137   | 0.140                |               |
| Heptanes         | 0.3148                 | 0.3122   | 1.4018   | 0.144                |               |
| Octanes          | 0.1363                 | 0.1352   | 0.6920   | 0.069                |               |
| Nonanes Plus     | 0.0352                 | 0.0349   | 0.2006   | 0.020                |               |
|                  | 100.8343               | 100.0000 | 100.0000 | 6.422                |               |

|                                                                        |              |            |
|------------------------------------------------------------------------|--------------|------------|
| <b>Calculated Physical Properties</b>                                  | <b>Total</b> | <b>C9+</b> |
| Calculated Molecular Weight                                            | 22.32        | 128.26     |
| Compressibility Factor                                                 | 0.9960       |            |
| Relative Density Real Gas                                              | 0.7733       | 4.4283     |
| <b>GPA 2172 Calculation:</b>                                           |              |            |
| <b>Calculated Gross BTU per ft<sup>3</sup> @ 14.65 psia &amp; 60°F</b> |              |            |
| Real Gas Dry BTU                                                       | 1290.8       | 6974.4     |
| Water Sat. Gas Base BTU                                                | 1268.7       | 6852.4     |
| Ideal, Gross HV - Dry                                                  | 1285.6       | 6946.6     |
| Ideal, Gross HV - Wet                                                  | 1263.1       | 6822.2     |

Comments: H2S Field Content: 0 %

Petroleum Chemist

Quality Assurance: The above analyses are performed in accordance with ASTM, UOP, GPA guidelines for quality assurance, unless otherwise stated. The test results apply to the sample as received.

**UPSET VENTING EVENT SPECIFIC JUSTIFICATIONS FORM****API #:** 30-015-45247**Operator:** OXY USA, Inc.**Well Name:** Iridium MDP1 28 21 Federal Com #006H**Vent Date:** 09/24/2025**Duration of Event:** 24 Hours**MCF Vented:** 54**Start Time:** 12:00 AM**End Time:** 11:59 PM**Cause:** Venting Leak > Underground Injection Line**Method of Vented Gas Measurement:** Allocated Vent Calculation

---

**1. Reason Why this event was beyond Operator's control:**

This emissions event was caused by the unforeseen, unexpected, sudden, and unavoidable breakdown of equipment or process that was beyond the owner/operator's control and did not stem from activity that could have been foreseen and avoided, and could not have been avoided by good design, operation, and preventative maintenance practices. The vicinity of this well site remains unattended except during routine visits by OXY production technicians, who collect operational data and perform daily inspections at adjacent facilities to ensure proper functioning and address any issues or support other field personnel as needed. In this case, OXY recently received a flyover observation report indicating that, during an internal flyover conducted on September 9<sup>th</sup>, 2025, evidence suggested venting from the Iridium MDP1 28 21 Federal Com #006H gas injection line may have begun on or around that date.

The exceedance of NMOCD's threshold of 50 MCF/D was not identified by OXY or its operations personnel until an internal flyover report was received on September 27, 2025. This submission addresses the findings provided to OXY following the September 9, 2025, flyover. Upon notification of the venting leak detected during the flyover, OXY's Operations team promptly dispatched an emissions technician to verify the finding using a FLIR camera, confirming that the gas injection line was venting from an underground source. The leak was traced to the top angle of the injection line at the outlet of the meter run piping. The injection line was subsequently isolated, and the relevant wells were shut down to facilitate and schedule necessary repairs. Investigation determined that a sudden and unforeseen failure of the underground gas injection line at the Iridium 28-21 Fed Com #176 well resulted in venting at the Iridium MDP1 28 21 Federal Com #006H. After shutting down the appropriate wells connected to the Iridium MDP1 28 21 Federal Com #006H injection line, venting ceased as of September 30, 2025. An additional FLIR camera inspection by an OXY emissions technician confirmed that venting had ceased. Although this venting incident was outside of OXY's control, all feasible measures were taken to effectively minimize emissions.

**2. Steps Taken to limit duration and magnitude of venting or flaring:**

This emissions event was caused by the unforeseen, unexpected, sudden, and unavoidable breakdown of equipment or process that was beyond the owner/operator's control and did not stem from activity that could have been foreseen and avoided, and could not have been avoided by good design, operation, and preventative maintenance practices. The vicinity of this well site remains unattended except during routine visits by OXY production technicians, who collect operational data and perform daily inspections at adjacent facilities to ensure proper functioning and address any issues or support other field personnel as needed. In this case, OXY recently received a flyover observation report indicating that, during an internal flyover conducted on September 9<sup>th</sup>, 2025, evidence suggested venting from the Iridium MDP1 28 21 Federal Com #006H gas injection line may have begun on or around that date.

The exceedance of NMOCD's threshold of 50 MCF/D was not identified by OXY or its operations personnel until an internal flyover report was received on September 27, 2025. This submission addresses the findings provided to OXY

following the September 9, 2025, flyover. Upon notification of the venting leak detected during the flyover, OXY's Operations team promptly dispatched an emissions technician to verify the finding using a FLIR camera, confirming that the gas injection line was venting from an underground source. The leak was traced to the top angle of the injection line at the outlet of the meter run piping. The injection line was subsequently isolated, and the relevant wells were shut down to facilitate and schedule necessary repairs. Investigation determined that a sudden and unforeseen failure of the underground gas injection line at the Iridium 28-21 Fed Com #176 well resulted in venting at the Iridium MDP1 28 21 Federal Com #006H. After shutting down the appropriate wells connected to the Iridium MDP1 28 21 Federal Com #006H injection line, venting ceased as of September 30, 2025. An additional FLIR camera inspection by an emissions technician confirmed that venting had ceased. Although this venting incident was outside of OXY's control, all feasible measures were taken to effectively minimize emissions.

### **3. Corrective Actions taken to eliminate the cause and reoccurrence of venting or flaring:**

OXY's capacity to mitigate and prevent recurrence of vent leaks from injection lines caused by corrosion is inherently limited, as such leaks can occur unexpectedly and without prior indication or warning. While it is not possible for OXY to predict or anticipate the timing of unexpected leaks in underground gas injection pipelines, OXY remains dedicated and committed to promptly detecting, isolating, and addressing these unexpected underground vent emissions whenever they are discovered. OXY's available actions in these situations include addressing vent leak issues as they are identified and maintaining ongoing area flyover surveys, which form an integral part of its comprehensive operations and maintenance initiatives and practices.

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico  
Energy, Minerals and Natural Resources  
Oil Conservation Division  
1220 S. St Francis Dr.  
Santa Fe, NM 87505

DEFINITIONS

Action 514335

DEFINITIONS

|                                                                    |                                                        |
|--------------------------------------------------------------------|--------------------------------------------------------|
| Operator:<br>OXY USA INC<br>P.O. Box 4294<br>Houston, TX 772104294 | OGRID:<br>16696                                        |
|                                                                    | Action Number:<br>514335                               |
|                                                                    | Action Type:<br>[C-129] Venting and/or Flaring (C-129) |

DEFINITIONS

|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <p>For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application:</p> <ul style="list-style-type: none"><li>• this application's operator, hereinafter "this operator";</li><li>• venting and/or flaring, hereinafter "vent or flare";</li><li>• any notification or report(s) of the C-129 form family, hereinafter "any C-129 forms";</li><li>• the statements in (and/or attached to) this, hereinafter "the statements in this";</li><li>• and the past tense will be used in lieu of mixed past/present tense questions and statements.</li></ul> |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

QUESTIONS

Action 514335

**QUESTIONS**

|                                                                    |                                                        |
|--------------------------------------------------------------------|--------------------------------------------------------|
| Operator:<br>OXY USA INC<br>P.O. Box 4294<br>Houston, TX 772104294 | OGRID:<br>16696                                        |
|                                                                    | Action Number:<br>514335                               |
|                                                                    | Action Type:<br>[C-129] Venting and/or Flaring (C-129) |

**QUESTIONS**

|                                                                                                                                                                                                   |                                                     |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------|
| <b>Prerequisites</b><br><i>Any messages presented in this section, will prevent submission of this application. Please resolve these issues before continuing with the rest of the questions.</i> |                                                     |
| Incident Well                                                                                                                                                                                     | [30-015-45247] IRIDIUM MDP1 28 21 FEDERAL COM #006H |
| Incident Facility                                                                                                                                                                                 | Unavailable.                                        |

|                                                                                                                                                                                                                                                                                            |                                                   |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------|
| <b>Determination of Reporting Requirements</b><br><i>Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide additional guidance.</i>                                                                                               |                                                   |
| Was this vent or flare caused by an emergency or malfunction                                                                                                                                                                                                                               | Yes                                               |
| Did this vent or flare last eight hours or more cumulatively within any 24-hour period from a single event                                                                                                                                                                                 | Yes                                               |
| Is this considered a submission for a vent or flare event                                                                                                                                                                                                                                  | Yes, minor venting and/or flaring of natural gas. |
| <i>An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during venting and/or flaring that is or may be a major or minor release under 19.15.29.7 NMAC.</i>                                                                                     |                                                   |
| Was there <b>at least 50 MCF</b> of natural gas vented and/or flared during this event                                                                                                                                                                                                     | Yes                                               |
| Did this vent or flare result in the release of <b>ANY</b> liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water | No                                                |
| Was the vent or flare within an incorporated municipal boundary or within 300 feet from an occupied permanent residence, school, hospital, institution or church in existence                                                                                                              | No                                                |

|                                                           |                                           |
|-----------------------------------------------------------|-------------------------------------------|
| <b>Equipment Involved</b>                                 |                                           |
| Primary Equipment Involved                                | Other (Specify)                           |
| Additional details for Equipment Involved. Please specify | Venting Leak > Underground Injection Line |

|                                                                                                                                                                    |               |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|
| <b>Representative Compositional Analysis of Vented or Flared Natural Gas</b><br><i>Please provide the mole percent for the percentage questions in this group.</i> |               |
| Methane (CH4) percentage                                                                                                                                           | 75            |
| Nitrogen (N2) percentage, if greater than one percent                                                                                                              | 2             |
| Hydrogen Sulfide (H2S) PPM, rounded up                                                                                                                             | 0             |
| Carbon Dioxide (CO2) percentage, if greater than one percent                                                                                                       | 1             |
| Oxygen (O2) percentage, if greater than one percent                                                                                                                | 0             |
| <i>If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.</i>                               |               |
| Methane (CH4) percentage quality requirement                                                                                                                       | Not answered. |
| Nitrogen (N2) percentage quality requirement                                                                                                                       | Not answered. |
| Hydrogen Sulfide (H2S) PPM quality requirement                                                                                                                     | Not answered. |
| Carbon Dioxide (CO2) percentage quality requirement                                                                                                                | Not answered. |
| Oxygen (O2) percentage quality requirement                                                                                                                         | Not answered. |

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

QUESTIONS, Page 2

Action 514335

**QUESTIONS (continued)**

|                                                                    |                                                        |
|--------------------------------------------------------------------|--------------------------------------------------------|
| Operator:<br>OXY USA INC<br>P.O. Box 4294<br>Houston, TX 772104294 | OGRID:<br>16696                                        |
|                                                                    | Action Number:<br>514335                               |
|                                                                    | Action Type:<br>[C-129] Venting and/or Flaring (C-129) |

**QUESTIONS**

| Date(s) and Time(s)                            |            |
|------------------------------------------------|------------|
| Date vent or flare was discovered or commenced | 09/24/2025 |
| Time vent or flare was discovered or commenced | 12:00 AM   |
| Time vent or flare was terminated              | 11:59 PM   |
| Cumulative hours during this event             | 24         |

| Measured or Estimated Volume of Vented or Flared Natural Gas              |                                                                                                           |
|---------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------|
| Natural Gas Vented (Mcf) Details                                          | Cause: Other   Other (Specify)   Natural Gas Vented   Released: 54 Mcf   Recovered: 0 Mcf   Lost: 54 Mcf. |
| Natural Gas Flared (Mcf) Details                                          | Not answered.                                                                                             |
| Other Released Details                                                    | Not answered.                                                                                             |
| Additional details for Measured or Estimated Volume(s). Please specify    | Allocated Vent Calculations                                                                               |
| Is this a gas only submission (i.e. only significant Mcf values reported) | Yes, according to supplied volumes this appears to be a "gas only" report.                                |

| Venting or Flaring Resulting from Downstream Activity             |               |
|-------------------------------------------------------------------|---------------|
| Was this vent or flare a result of downstream activity            | No            |
| Was notification of downstream activity received by this operator | Not answered. |
| Downstream OGRID that should have notified this operator          | Not answered. |
| Date notified of downstream activity requiring this vent or flare | Not answered. |
| Time notified of downstream activity requiring this vent or flare | Not answered. |

| Steps and Actions to Prevent Waste                                                                                               |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         |
|----------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| For this event, this operator could not have reasonably anticipated the current event and it was beyond this operator's control. | True                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |
| Please explain reason for why this event was beyond this operator's control                                                      | This emissions event was caused by the unforeseen, unexpected, sudden, and unavoidable breakdown of equipment or process that was beyond the owner/operator's control and did not stem from activity that could have been foreseen and avoided, and could not have been avoided by good design, operation, and preventative maintenance practices. The vicinity of this well site remains unattended except during routine visits by OXY production technicians, who collect operational data and perform daily inspections at adjacent facilities to ensure proper functioning and address any issues or support other field personnel as needed. In this case, OXY recently received a flyover observation report indicating that, during an internal flyover conducted on September 9th, 2025, evidence suggested venting from the Iridium MDP1 28 21 Federal Com #006H gas injection line may have begun on or around that date.    |
| Steps taken to limit the duration and magnitude of vent or flare                                                                 | This submission addresses the findings provided to OXY following the September 9, 2025, flyover. Upon notification of the venting leak detected during the flyover, OXY's Operations team promptly dispatched an emissions technician to verify the finding using a FLIR camera, confirming that the gas injection line was venting from an underground source. The leak was traced to the top angle of the injection line at the outlet of the meter run piping. The injection line was subsequently isolated, and the relevant wells were shut down to facilitate and schedule necessary repairs. Investigation determined that a sudden and unforeseen failure of the underground gas injection line at the Iridium 28-21 Fed Com #176 well resulted in venting at the Iridium MDP1 28 21 Federal Com #006H. After shutting down the appropriate wells connected to the Iridium MDP1 28 21 Federal Com #006H injection line, venting |

|                                                                                   |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |
|-----------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
|                                                                                   | ceased as of September 30, 2025. An additional FLIR camera inspection by an emissions technician confirmed that venting had ceased. Although this venting incident was outside of OXY's control, all feasible measures were taken to effectively minimize emissions.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |
| Corrective actions taken to eliminate the cause and reoccurrence of vent or flare | OXY's capacity to mitigate and prevent recurrence of vent leaks from injection lines caused by corrosion is inherently limited, as such leaks can occur unexpectedly and without prior indication or warning. While it is not possible for OXY to predict or anticipate the timing of unexpected leaks in underground gas injection pipelines, OXY remains dedicated and committed to promptly detecting, isolating, and addressing these unexpected underground vent emissions whenever they are discovered. OXY's available actions in these situations include addressing vent leak issues as they are identified and maintaining ongoing area flyover surveys, which form an integral part of its comprehensive operations and maintenance initiatives and practices. |

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

ACKNOWLEDGMENTS

Action 514335

**ACKNOWLEDGMENTS**

|                                                                    |                                                        |
|--------------------------------------------------------------------|--------------------------------------------------------|
| Operator:<br>OXY USA INC<br>P.O. Box 4294<br>Houston, TX 772104294 | OGRID:<br>16696                                        |
|                                                                    | Action Number:<br>514335                               |
|                                                                    | Action Type:<br>[C-129] Venting and/or Flaring (C-129) |

**ACKNOWLEDGMENTS**

|                                     |                                                                                                                                                                                                                                                                                                                           |
|-------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <input checked="" type="checkbox"/> | I acknowledge that I am authorized to submit a <i>Venting and/or Flaring</i> (C-129) report on behalf of this operator and understand that this report can be a <b>complete</b> C-129 submission per 19.15.27.8 and 19.15.28.8 NMAC.                                                                                      |
| <input checked="" type="checkbox"/> | I acknowledge that upon submitting this application, I will be creating a new incident file (assigned to this operator) to track any C-129 forms, pursuant to 19.15.27.7 and 19.15.28.8 NMAC and understand that this submission meets the notification requirements of Paragraph (1) of Subsection G and F respectively. |
| <input checked="" type="checkbox"/> | I hereby certify the statements in this report are true and correct to the best of my knowledge and acknowledge that any false statement may be subject to civil and criminal penalties under the Oil and Gas Act.                                                                                                        |
| <input checked="" type="checkbox"/> | I acknowledge that the acceptance of any C-129 forms by the OCD does not relieve this operator of liability should their operations have failed to adequately investigate, report, and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment.                       |
| <input checked="" type="checkbox"/> | I acknowledge that OCD acceptance of any C-129 forms does not relieve this operator of responsibility for compliance with any other applicable federal, state, or local laws and/or regulations.                                                                                                                          |

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico  
Energy, Minerals and Natural Resources  
Oil Conservation Division  
1220 S. St Francis Dr.  
Santa Fe, NM 87505

CONDITIONS

Action 514335

CONDITIONS

|                                                                    |                                                        |
|--------------------------------------------------------------------|--------------------------------------------------------|
| Operator:<br>OXY USA INC<br>P.O. Box 4294<br>Houston, TX 772104294 | OGRID:<br>16696                                        |
|                                                                    | Action Number:<br>514335                               |
|                                                                    | Action Type:<br>[C-129] Venting and/or Flaring (C-129) |

CONDITIONS

| Created By | Condition                                                                                                                                                                          | Condition Date |
|------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------|
| marialuna2 | If the information provided in this report requires an amendment, submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event. | 10/12/2025     |