	Sample Information
	· · · · · · · · · · · · · · · · · · ·
Sample Name	SALT FLAT CTB TRAIN 3 CHECK (FMP)
Technician	NOE GARCIA
Analyzer Make & Model	INFICON MICRO GC
Last Calibration/Validation Date	6/26/2025
Meter Number	18723C
Air temperature	79
Flow Rate (MCF/Day)	23592
Heat Tracing	Heated Hose & Gasifier
Sample description/mtr name	SALT FLAT CTB TRAIN 3 CHECK (FMP)
Sampling Method	fill and empty
Operator	AKM MEASUREMENT
State	New Mexico
Region Name	PERMIAN_RESOURCES
Lease name	SALT FLAT CTB TRAIN 3 CHECK (FMP)
System	WEST
FLOC	OP-L2116-BT002
Sample Sub Type	СТВ
Sample Name Type	meter
Vendor	AKM MEASUREMENT
Cylinder #	38599
Sampled by	AUSTIN MCCOY
Sample date	6/18/2025
Analyzed date	6/26/2025
Method Name	C9
Injection Date	2025-06-26 12:26:45
Report Date	2025-06-26 12:40:54
EZReporter Configuration File	1-16-2023 OXY GPA C9+ H2S #2 (1) (1).cfgx
Source Data File	e755d9c4-b2a0-4099-9f6e-c61aea786761
NGA Phys. Property Data Source	GPA Standard 2145-16 (FPS)
Data Source	INFICON Fusion Connector

Component Results

Component Name	Peak Area	Raw Amount	Response Factor	Norm Mole%	Gross HV (Dry) (BTU / Ideal cu.ft.)	Relative Gas Density (Dry)	GPM (Dry) (Gal. / 1000 cu.ft.)	
Nitrogen	26859.5	1.8717	0.00006969	1.8722	0.0	0.01811	0.207	
Methane	857398.1	75.6371	0.00008822	75.6539	765.9	0.41905	12.871	
CO2	32510.4	1.8707	0.00005754	1.8711	0.0	0.02843	0.320	
Ethane	201864.6	11.2000	0.00005548	11.2025	198.7	0.11630	3.007	
H2S	0.0	0.0003	0.00000000	0.0003	0.0	0.00000	0.000	
Propane	134528.2	5.3472	0.00003975	5.3485	134.9	0.08143	1.479	
iso-butane	68480.0	0.6728	0.00000982	0.6730	21.9	0.01351	0.221	
n-Butane	174296.5	1.6939	0.00000972	1.6943	55.4	0.03400	0.536	
iso-pentane	47769.7	0.4156	0.00000870	0.4157	16.7	0.01036	0.153	
n-Pentane	58218.1	0.4843	0.00000832	0.4845	19.5	0.01207	0.176	
hexanes	48038.0	0.4185	0.00000871	0.4186	20.0	0.01246	0.173	
heptanes	46736.0	0.2483	0.00000531	0.2483	13.7	0.00859	0.115	
octanes	22936.0	0.1059	0.00000462	0.1059	6.6	0.00418	0.054	
nonanes+	5485.0	0.0112	0.00000204	0.0112	0.8	0.00050	0.006	
Total:		99.9775		100.0000	1254.0	0.75898	19.318	

Results Summary

Result	Dry	Sat.
Total Un-Normalized Mole%	99.9775	
Pressure Base (psia)	14.730	
Temperature Base (Deg. F)	60.00	
Flowing Temperature (Deg. F)	88.0	
Flowing Pressure (psia)	72.0	

eceived by OCD: 14d442025 2:04:25 PM	Dry	Sat.
Gross Heating Value (BTU / Ideal cu.ft.)	1254.0	1232.2
Gross Heating Value (BTU / Real cu.ft.)	1258.8	1237.4
Relative Density (G), Real	0.7615	0.7595

Monitored Parameter Report

Parameter	Value	Lower Limit	Upper Limit	Status	
Total un-normalized amount	99.9775	97.0000	103.0000	Pass	



UPSET FLARING EVENT SPECIFIC JUSTIFICATIONS FORM

Facility Id# fAPP2126563666 **Operator:** OXY USA, Inc.

Facility: Salt Flat CTB Flare Date: 10/29/2025

Duration of Event: 2 Hours 40 Minutes

MCF Flared: 1040

Start Time: 08:10 AM

End Time: 10:50 AM

Cause: Emergency Flare > Third Party > USA Compression > Salt Flat Boo Compressor Station > Multiple

Compression Equipment Issues

Method of Flared Gas Measurement: Gas Flare Meter

1. Reason why this event was beyond Operator's control:

This emissions event was caused by the unforeseen, unexpected, sudden, and unavoidable breakdown of equipment or process that was beyond the owner/operator's control and did not stem from activity that could have been foreseen and avoided, and could not have been avoided by good design, operation, and preventative maintenance practices. OXY engages in respectable and good facility operation practices while also maintaining its continuous facility equipment preventative maintenance program. In this instance, USA Compression encountered multiple compressor equipment malfunctions at its Salt Flat Boo compressor station, which led to an unexpected restriction in gas flow intake from OXY's Salt Flat CTB facility. Consequently, this third party caused operational limitation resulted in a flaring event at the Salt Flat CTB due to the accumulation of backed-up gas. To mitigate the risks associated with overpressure from unexpected backed up gas and to ensure the safety of our operations, OXY had to resort to controlled flaring. This process allows OXY to safely burn off the excess gas, thereby preventing potential hazards such as equipment damage, leaks, or even explosions. While flaring is not OXY's preferred method of handling backed up gas, it is a necessary step under these exceptional circumstances to maintain the integrity and safety of our operations. OXY's Salt Flat CTB was operating normally prior to the flaring incident occurring. This event is out of OXY's control yet OXY made every effort to control and minimize emissions as much as possible by working safely and diligently.

2. Steps Taken to limit duration and magnitude of venting or flaring:

It is OXY's policy to route its stranded gas to a flare during an unforeseen and unavoidable emergency or malfunction, that is beyond OXY's control to avoid, prevent or foresee, to minimize emissions as much as possible as part of the overall steps taken to limit duration and magnitude of flaring. The flare at this facility has 98% combustion efficiency to lessen emissions as much as possible. In this instance, USA Compression encountered multiple compressor equipment malfunctions at its Salt Flat Boo compressor station, which led to an unexpected restriction in gas flow intake from OXY's Salt Flat CTB facility. Consequently, this third party caused operational limitation resulted in a flaring event at the Salt Flat CTB due to the accumulation of backed-up gas. OXY's field and operations teams diligently oversee the facility and field pressure to swiftly identify any deviations from accepted standard operational parameters and as soon as flaring occurred, the wells auto-choke system began adjusting injection rates. Field personnel in the area were directed to assist with manually shutting in additional wells to cease flaring, which took time to do. While flaring is not OXY's preferred method of handling backed up gas, it is a necessary step under these exceptional circumstances to maintain the integrity and safety of our operations. OXY's Salt Flat CTB was operating normally prior to the flaring incident occurring. This event is out of OXY's control yet OXY made every effort to control and minimize emissions as much as possible by working safely and diligently.

3. Corrective Actions taken to eliminate the cause and reoccurrence of venting or flaring:

OXY is limited in its ability to take any form of corrective actions to eliminate the cause and potential reoccurrence of a third-party owned and operated compressor station's sudden and unexpected gas flow intake restriction or shut-in, as this control issue is downstream of OXY's custody transfer point and out of OXY's control to foresee, avoid, prevent from happening or recurring. Third-party downstream compression station owner operators may have equipment issues, which will recur from time to time, which in turn, directly impacts OXY's ability to send its sales gas to them, and potentially trigger a flaring event. OXY makes every effort to control and minimize emissions as much as possible. The only action that OXY can take and handle that is within its control is to continually communicate with USA Compression personnel, who operate the Salt Flat Boo Compressor Station, when possible, during these types of circumstances.

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

DEFINITIONS

Action 525924

DEFINITIONS

Operator:	OGRID:
OXY USA INC	16696
P.O. Box 4294	Action Number:
Houston, TX 772104294	525924
	Action Type:
	[C-129] Amend Venting and/or Flaring (C-129A)

DEFINITIONS

For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application:

- this application's operator, hereinafter "this operator";
- venting and/or flaring, hereinafter "vent or flare";
- any notification or report(s) of the C-129 form family, hereinafter "any C-129 forms";
- the statements in (and/or attached to) this, hereinafter "the statements in this";
- and the past tense will be used in lieu of mixed past/present tense questions and statements.

Sante Fe Main Office Phone: (505) 476-3441 General Information

Phone: (505) 629-6116

Online Phone Directory
https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS

Action 525924

Q	UESTIONS		
Operator:	OGRID:		
OXY USA INC P.O. Box 4294	16696 Action Number:		
Houston, TX 772104294	525924		
	Action Type: [C-129] Amend Venting and/or Flaring (C-129A)		
QUESTIONS			
Prerequisites			
Any messages presented in this section, will prevent submission of this application. Please resolve	these issues before continuing with the rest of the questions.		
Incident ID (n#)	Unavailable.		
Incident Name	Unavailable.		
Incident Type	Flare		
Incident Status	Unavailable.		
Incident Facility	[fAPP2126563666] SALT FLAT CTB		
Only valid Vent, Flare or Vent with Flaring incidents (selected above in the Application Details section	on) that are assigned to your current operator can be amended with this C-129A application.		
Determination of Panasting Paguiyaments			
Determination of Reporting Requirements Answer all questions that apply. The Reason(s) statements are calculated based on your answers are	nd may provide addional quidance		
Was this vent or flare caused by an emergency or malfunction	Yes		
Did this vent or flare last eight hours or more cumulatively within any 24-hour period from a single event	No		
Is this considered a submission for a vent or flare event	Yes, major venting and/or flaring of natural gas.		
An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during v Was there at least 50 MCF of natural gas vented and/or flared during this event	Yes		
Did this vent or flare result in the release of ANY liquids (not fully and/or completely	165		
flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No		
Was the vent or flare within an incorporated municipal boundary or withing 300 feet from an occupied permanent residence, school, hospital, institution or church in existence	No		
-			
Equipment Involved	-		
Primary Equipment Involved	Other (Specify)		
Additional details for Equipment Involved. Please specify	Emergency Flare > Third Party > USA Compression > Salt Flat Boo Compressor Station > Multiple Compression Equipment Issues		
Representative Compositional Analysis of Vented or Flared Natural Gas			
Please provide the mole percent for the percentage questions in this group.			
Methane (CH4) percentage	76		
Nitrogen (N2) percentage, if greater than one percent	2		
Hydrogen Sulfide (H2S) PPM, rounded up	3		
Carbon Dioxide (C02) percentage, if greater than one percent	2		
Oxygen (02) percentage, if greater than one percent	0		
7.5 . 71 0 . 0			
If you are venting and/or flaring because of Pipeline Specification, please provide the required spec			
Methane (CH4) percentage quality requirement	Not answered.		
Nitrogen (N2) percentage quality requirement	Not answered.		
Hydrogen Sufide (H2S) PPM quality requirement	Not answered.		

Not answered.

Not answered.

Oxygen (02) percentage quality requirement

Carbon Dioxide (C02) percentage quality requirement

Sante Fe Main Office Phone: (505) 476-3441 General Information

Phone: (505) 629-6116
Online Phone Directory
https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS, Page 2

Action 525924

QUEST	IONS (continued)
Operator:	OGRID:
OXY USA INC	16696
P.O. Box 4294 Houston, TX 772104294	Action Number: 525924
110dSt011, 17 772104294	Action Type: [C-129] Amend Venting and/or Flaring (C-129A)
QUESTIONS	[0-129] Amenu Venting and/or Flaming (0-129A)
Date(s) and Time(s)	
Date vent or flare was discovered or commenced	10/29/2025
Time vent or flare was discovered or commenced	08:10 AM
Time vent or flare was terminated	10:50 AM
Cumulative hours during this event	3
Measured or Estimated Volume of Vented or Flared Natural Gas	·
Natural Gas Vented (Mcf) Details	Not answered.
Natural Gas Flared (Mcf) Details	Cause: Other Other (Specify) Natural Gas Flared Released: 1,040 Mcf Recovered: 0 Mcf Lost: 1,040 Mcf.
Other Released Details	Not answered.
Additional details for Measured or Estimated Volume(s). Please specify	Gas Flare Meter
Is this a gas only submission (i.e. only significant Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.
Venting or Flaring Resulting from Downstream Activity	
Was this vent or flare a result of downstream activity	No
Was notification of downstream activity received by this operator	Not answered.
Downstream OGRID that should have notified this operator	Not answered.
Date notified of downstream activity requiring this vent or flare	
Time notified of downstream activity requiring this vent or flare	Not answered.
Steps and Actions to Prevent Waste	
For this event, this operator could not have reasonably anticipated the current event and it was beyond this operator's control	True
Please explain reason for why this event was beyond this operator's control	This emissions event was caused by the unforeseen, unexpected, sudden, and unavoidable breakdown of equipment or process that was beyond the owner/operator's control and did not stem from activity that could have been foreseen and avoided, and could not have been avoided by good design, operation, and preventative maintenance practices. OXY engages in respectable and good facility operation practices while also maintaining its continuous facility equipment preventative maintenance program. In this instance, USA Compression encountered multiple compressor equipment malfunctions at its Salt Flat Boo compressor station, which led to an unexpected restriction in gas flow intake from OXY's Salt Flat CTB facility. Consequently, this third party caused operational limitation resulted in a flaring event at the Salt Flat CTB due to the accumulation of backed-up gas. To mitigate the risks

associated with overpressure from unexpected backed up gas and to ensure the safety of our operations, OXY had to resort to controlled flaring. This process allows OXY to safely burn off the excess gas, thereby preventing potential hazards such as equipment damage, leaks, or even explosions. While flaring is not OXY's preferred method of handling backed up gas, it is a necessary step under these exceptional circumstances to maintain the integrity and safety of our operations. OXY's Salt Flat CTB was operating normally prior to the flaring incident occurring. This event is out of OXY's control yet OXY made every effort to control and

It is OXY's policy to route its stranded gas to a flare during an unforeseen and unavoidable emergency or malfunction, that is beyond OXY's control to avoid, prevent or foresee, to

minimize emissions as much as possible by working safely and diligently

Steps taken to limit the duration and magnitude of vent or flare	minimize emissions as much as possible as part of the overall steps taken to limit duration and magnitude of flaring. The flare at this facility has 98% combustion efficiency to lessen emissions as much as possible. In this instance, USA Compression encountered multiple compressor equipment malfunctions at its Salt Flat Boo compressor station, which led to an unexpected restriction in gas flow intake from OXY's Salt Flat CTB facility. Consequently, this third party caused operational limitation resulted in a flaring event at the Salt Flat CTB due to the accumulation of backed-up gas. OXY's field and operations teams diligently oversee the facility and field pressure to swiftly identify any deviations from accepted standard operational parameters and as soon as flaring occurred, the wells auto-choke system began adjusting injection rates. Field personnel in the area were directed to assist with manually shutting in additional wells to cease flaring, which took time to do. While flaring is not OXY's preferred method of handling backed up gas, it is a necessary step under these exceptional circumstances to maintain the integrity and safety of our operations. OXY's Salt Flat CTB was operating normally prior to the flaring incident occurring. This event is out of OXY's control yet OXY made every effort to control and minimize emissions as much as possible by working safely and diligently.
Corrective actions taken to eliminate the cause and reoccurrence of vent or flare	OXY is limited in its ability to take any form of corrective actions to eliminate the cause and potential reoccurrence of a third-party owned and operated compressor station's sudden and unexpected gas flow intake restriction or shut-in, as this control issue is downstream of OXY's custody transfer point and out of OXY's control to foresee, avoid, prevent from happening or recurring. Third-party downstream compression station owner operators may have equipment issues, which will recur from time to time, which in turn, directly impacts OXY's ability to send its sales gas to them, and potentially trigger a flaring event. OXY makes every effort to control and minimize emissions as much as possible. The only action that OXY can take and handle that is within its control is to continually communicate with USA Compression personnel, who operate the Salt Flat Boo Compressor Station, when possible, during these types of circumstances.

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

ACKNOWLEDGMENTS

Action 525924

ACKNOWLEDGMENTS

Operator:	OGRID:
OXY USA INC	16696
P.O. Box 4294	Action Number:
Houston, TX 772104294	525924
	Action Type:
	[C-129] Amend Venting and/or Flaring (C-129A)

ACKNOWLEDGMENTS

$\overline{\lor}$	I acknowledge that with this application I will be amending an existing incident file (assigned to this operator) for a vent or flare event, pursuant to 19.15.27 and 19.15.28 NMAC.
~	I acknowledge that amending an incident file does not replace original submitted application(s) or information and understand that any C-129 forms submitted to the OCD will be logged and stored as public record.
~	I hereby certify the statements in this amending report are true and correct to the best of my knowledge and acknowledge that any false statement may be subject to civil and criminal penalties under the Oil and Gas Act.
~	I acknowledge that the acceptance of any C-129 forms by the OCD does not relieve this operator of liability should their operations have failed to adequately investigate, report, and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment.
~	I acknowledge that OCD acceptance of any C-129 forms does not relieve this operator of responsibility for compliance with any other applicable federal, state, or local laws and/or regulations.

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 525924

CONDITIONS

Operator:	OGRID:
OXY USA INC	16696
P.O. Box 4294	Action Number:
Houston, TX 772104294	525924
	Action Type:
	[C-129] Amend Venting and/or Flaring (C-129A)

CONDITIONS

Created By	Condition	Condition Date
marialuna2	If the information provided in this report requires further amendment(s), submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event.	11/12/2025