



Certificate of Analysis

Number: 6030-25030113-001A

Artesia Laboratory
 200 E Main St.
 Artesia, NM 88210
 Phone 575-746-3481

Chandler Montgomery
 Occidental Petroleum
 1502 W Commerce Dr.
 Carlsbad, NM 88220

Field:	PERMIAN_RESOURCES	Report Date:	03/11/2025
Station Name:	Red Tank 19 Train 2 Check	Sampled By:	Ian Pollock
Station Number:	15622C	Sample Of:	Gas
Station Location:	OP-L2151-BT001	Sample Type:	Spot
Sample Point:	Meter	Sample Conditions:	128 psig, @ 78.1 °F
Property ID:	FMP/LSE N/A	Sample Date:	02/28/2025 11:40
Formation:	NEW_MEXICO	Received Date:	03/07/2025
County:		Login Date:	03/07/2025
Well Name:	CTB	Effective Date:	03/01/2025
Type of Sample :	Spot-Cylinder	Flow Rate:	35692 MSCFD
Sampling Company:	SPL	Sampling Method:	
Heat Trace Used:	N/A	Heating Method:	
Sampling Method:	Purge and Fill	Method:	GPA-2261M
Last Inst. Cal.:	03/10/2025 07:40:57	Cylinder No:	5030-03289
Analyzed:	03/11/2025 07:14:46 by CDW	Instrument:	6030_GC6 (Inficon GC-3000 Micro)

Analytical Data

Components	Un-normalized Mol %	Mol. %	Wt. %	GPM at 14.65 psia	
Hydrogen Sulfide	0.0000	0.0003	0.0005		GPM TOTAL C2+ 6.319
Nitrogen	2.2260	2.2093	2.7879		GPM TOTAL C3+ 3.071
Methane	74.0508	73.4967	53.1133		GPM TOTAL iC5+ 0.443
Carbon Dioxide	1.8717	1.8577	3.6829		
Ethane	12.2596	12.1678	16.4814	3.248	
Propane	6.4182	6.3702	12.6536	1.752	
Iso-butane	0.8106	0.8045	2.1064	0.263	
n-Butane	1.9626	1.9479	5.1000	0.613	
Iso-pentane	0.3830	0.3801	1.2354	0.139	
n-Pentane	0.3985	0.3955	1.2854	0.143	
Hexanes Plus	0.3728	0.3700	1.5532	0.161	
	100.7538	100.0000	100.0000	6.319	

Calculated Physical Properties	Total	C6+
Relative Density Real Gas	0.7691	3.2176
Calculated Molecular Weight	22.20	93.19
Compressibility Factor	0.9962	
GPA 2172 Calculation:		
Calculated Gross BTU per ft³ @ 14.65 psia & 60°F		
Real Gas Dry BTU	1259	5113
Water Sat. Gas Base BTU	1237	5024
Ideal, Gross HV - Dry at 14.65 psia	1253.7	5113.2
Ideal, Gross HV - Wet	1231.8	5023.7
Net BTU Dry Gas - real gas	1143	
Net BTU Wet Gas - real gas	1123	

Comments: H2S Field Content: 2.5 ppm

Mostaq Ahamed

 Hydrocarbon Laboratory Manager

Quality Assurance: The above analyses are performed in accordance with ASTM, UOP, GPA guidelines for quality assurance, unless otherwise stated. The test results apply to the sample as received.



UPSET FLARING EVENT SPECIFIC JUSTIFICATIONS FORM

Facility Id# fAPP2127031815

Facility: Red Tank 19 CTB

Duration of Event: 45 Minutes

Start Time: 09:10 AM

Cause: Emergency Flare > Third Party > USA Compression > Red Tank BOO 26 > ESD > Faulty Switch

Method of Flared Gas Measurement: Gas Flare Meter

Operator: OXY USA, Inc.

Flare Date: 02/26/2026

MCF Flared: 593

End Time: 09:55 AM

1. Reason why this event was beyond Operator's control:

This emissions event was caused by an unexpected and unavoidable interruption, restriction, or complete shutdown of a gas pipeline by a third-party pipeline compressor station operator. This incident impacted OXY's ability to deliver or transport its gas through the pipeline. This incident could not have been anticipated or prevented through OXY's operational or preventative maintenance practices. In this instance, a flaring event was initiated at the Red Tank 19 CTB following an emergency shutdown at the Red Tank 26 Boo compressor station, operated by USA Compression. Initial reports from USA Compression personnel to OXY Control room staff suggested that the emergency shutdown button had been activated; however, it was subsequently determined that a faulty switch at their Boo compressor station caused the shutdown, resulting in increased field pressure and subsequent flaring at the Red Tank 19 CTB. Although this flaring incident was caused by issues downstream of OXY's custody transfer point, field personnel and Control Room personnel implemented every feasible intervention to minimize emissions efficiently by choking back several wells to cease flaring.

2. Steps Taken to limit duration and magnitude of venting or flaring:

This facility is unmanned, except when OXY production techs are gathering data daily or conduct daily walk-throughs to ensure that there are no problems, circumstances and/or assist other personnel on-site for maintenance purposes. It is OXY's policy to route its stranded gas to a flare during an unforeseen and unavoidable emergency or malfunction to minimize emissions as much as possible as part of the overall steps taken to limit duration and magnitude of flaring. This approach aims to minimize emissions as much as possible and is part of OXY's broader efforts to limit both the duration and scale of flaring events. The flare at this facility has a 98% combustion efficiency to lessen emissions as much as possible. The steps taken to limit duration of excess emissions during this event were for field personnel and OXY Control Room personnel to execute immediate measures to cease flaring by choking back several wells. Initial reports from USA Compression personnel to OXY Control room staff suggested that the emergency shutdown button had been activated; however, it was subsequently determined that a faulty switch at their Boo compressor station caused the shutdown, resulting in increased field pressure and subsequent flaring at the Red Tank 19 CTB. Although flaring is not OXY's preferred method for handling excess gas, it is necessary to ensure the safety of our operations, equipment, and field personnel. OXY took all possible measures to manage and reduce emissions to the greatest extent.

3. Corrective Actions taken to eliminate the cause and reoccurrence of venting or flaring:

OXY is not in a position to implement corrective measures to address the root cause and prevent future incidents of a gas flow restriction, shut-in or suspension caused by third party compressor station operators, since the cause of such is beyond OXY's custody transfer point and outside of OXY's capacity to correct or prevent from happening again. When USA Compression and its operations face challenges managing the volume of sales gas flow from OXY, it then limits OXY's ability to push forward with its sales gas transmission, which in turn prompts OXY to flare its excess gas. OXY is committed to minimizing emissions as much as possible during these types of circumstances.

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

DEFINITIONS

Action 562937

DEFINITIONS

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 562937
	Action Type: [C-129] Amend Venting and/or Flaring (C-129A)

DEFINITIONS

For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application:

- this application's operator, hereinafter "this operator";
- venting and/or flaring, hereinafter "vent or flare";
- any notification or report(s) of the C-129 form family, hereinafter "any C-129 forms";
- the statements in (and/or attached to) this, hereinafter "the statements in this";
- and the past tense will be used in lieu of mixed past/present tense questions and statements.

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 562937

QUESTIONS

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 562937
	Action Type: [C-129] Amend Venting and/or Flaring (C-129A)

QUESTIONS

Prerequisites	
<i>Any messages presented in this section, will prevent submission of this application. Please resolve these issues before continuing with the rest of the questions.</i>	
Incident ID (n#)	Unavailable.
Incident Name	Unavailable.
Incident Type	Flare
Incident Status	Unavailable.
Incident Facility	[fAPP2127031815] RED TANK 19 CTB
<i>Only valid Vent, Flare or Vent with Flaring incidents (selected above in the Application Details section) that are assigned to your current operator can be amended with this C-129A application.</i>	

Determination of Reporting Requirements	
<i>Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide additional guidance.</i>	
Was this vent or flare caused by an emergency or malfunction	Yes
Did this vent or flare last eight hours or more cumulatively within any 24-hour period from a single event	No
Is this considered a submission for a vent or flare event	Yes, major venting and/or flaring of natural gas.
<i>An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during venting and/or flaring that is or may be a major or minor release under 19.15.29.7 NMAC.</i>	
Was there at least 50 MCF of natural gas vented and/or flared during this event	Yes
Did this vent or flare result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No
Was the vent or flare within an incorporated municipal boundary or within 300 feet from an occupied permanent residence, school, hospital, institution or church in existence	No

Equipment Involved	
Primary Equipment Involved	Other (Specify)
Additional details for Equipment Involved. Please specify	Emergency Flare > Third Party > USA Compression > Red Tank BOO 26 > ESD > Faulty Switch

Representative Compositional Analysis of Vented or Flared Natural Gas	
<i>Please provide the mole percent for the percentage questions in this group.</i>	
Methane (CH4) percentage	73
Nitrogen (N2) percentage, if greater than one percent	2
Hydrogen Sulfide (H2S) PPM, rounded up	3
Carbon Dioxide (CO2) percentage, if greater than one percent	2
Oxygen (O2) percentage, if greater than one percent	0
<i>If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.</i>	
Methane (CH4) percentage quality requirement	Not answered.
Nitrogen (N2) percentage quality requirement	Not answered.
Hydrogen Sulfide (H2S) PPM quality requirement	Not answered.
Carbon Dioxide (CO2) percentage quality requirement	Not answered.
Oxygen (O2) percentage quality requirement	Not answered.

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS, Page 2

Action 562937

QUESTIONS (continued)

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 562937
	Action Type: [C-129] Amend Venting and/or Flaring (C-129A)

QUESTIONS

Date(s) and Time(s)	
Date vent or flare was discovered or commenced	02/26/2026
Time vent or flare was discovered or commenced	09:10 AM
Time vent or flare was terminated	09:55 PM
Cumulative hours during this event	1

Measured or Estimated Volume of Vented or Flared Natural Gas	
Natural Gas Vented (Mcf) Details	<i>Not answered.</i>
Natural Gas Flared (Mcf) Details	Cause: Equipment Failure Gas Compressor Station Natural Gas Flared Released: 593 Mcf Recovered: 0 Mcf Lost: 593 Mcf.
Other Released Details	<i>Not answered.</i>
Additional details for Measured or Estimated Volume(s). Please specify	Gas Flare Meter
Is this a gas only submission (i.e. only significant Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.

Venting or Flaring Resulting from Downstream Activity	
Was this vent or flare a result of downstream activity	No
Was notification of downstream activity received by this operator	<i>Not answered.</i>
Downstream OGRID that should have notified this operator	<i>Not answered.</i>
Date notified of downstream activity requiring this vent or flare	
Time notified of downstream activity requiring this vent or flare	<i>Not answered.</i>

Steps and Actions to Prevent Waste	
For this event, this operator could not have reasonably anticipated the current event and it was beyond this operator's control	True
Please explain reason for why this event was beyond this operator's control	This emissions event was caused by an unexpected and unavoidable interruption, restriction, or complete shutdown of a gas pipeline by a third-party pipeline compressor station operator. This incident impacted OXY's ability to deliver or transport its gas through the pipeline. This incident could not have been anticipated or prevented through OXY's operational or preventative maintenance practices. In this instance, a flaring event was initiated at the Red Tank 19 CTB following an emergency shutdown at the Red Tank 26 Boo compressor station, operated by USA Compression. Initial reports from USA Compression personnel to OXY Control room staff suggested that the emergency shutdown button had been activated; however, it was subsequently determined that a faulty switch at their Boo compressor station caused the shutdown, resulting in increased field pressure and subsequent flaring at the Red Tank 19 CTB. Although this flaring incident was caused by issues downstream of OXY's custody transfer point, field personnel and Control Room personnel implemented every feasible intervention to minimize emissions efficiently by choking back several wells to cease flaring.
	This facility is unmanned, except when OXY production techs are gathering data daily or conduct daily walk-throughs to ensure that there are no problems, circumstances and/or assist other personnel on-site for maintenance purposes. It is OXY's policy to route its stranded gas to a flare during an unforeseen and unavoidable emergency or malfunction to minimize emissions as much as possible as part of the overall steps taken to limit duration and magnitude of flaring. This approach aims to minimize emissions as much as possible

<p>Steps taken to limit the duration and magnitude of vent or flare</p>	<p>and is part of OXY's broader efforts to limit both the duration and scale of flaring events. The flare at this facility has a 98% combustion efficiency to lessen emissions as much as possible. The steps taken to limit duration of excess emissions during this event were for field personnel and OXY Control Room personnel to execute immediate measures to cease flaring by choking back several wells. Initial reports from USA Compression personnel to OXY Control room staff suggested that the emergency shutdown button had been activated; however, it was subsequently determined that a faulty switch at their Boo compressor station caused the shutdown, resulting in increased field pressure and subsequent flaring at the Red Tank 19 CTB. Although flaring is not OXY's preferred method for handling excess gas, it is necessary to ensure the safety of our operations, equipment, and field personnel. OXY took all possible measures to manage and reduce emissions to the greatest extent.</p>
<p>Corrective actions taken to eliminate the cause and reoccurrence of vent or flare</p>	<p>OXY is not in a position to implement corrective measures to address the root cause and prevent future incidents of a gas flow restriction, shut-in or suspension caused by third party compressor station operators, since the cause of such is beyond OXY's custody transfer point and outside of OXY's capacity to correct or prevent from happening again. When USA Compression and its operations face challenges managing the volume of sales gas flow from OXY, it then limits OXY's ability to push forward with its sales gas transmission, which in turn prompts OXY to flare its excess gas. OXY is committed to minimizing emissions as much as possible during these types of circumstances.</p>

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

ACKNOWLEDGMENTS

Action 562937

ACKNOWLEDGMENTS

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 562937
	Action Type: [C-129] Amend Venting and/or Flaring (C-129A)

ACKNOWLEDGMENTS

<input checked="" type="checkbox"/>	I acknowledge that with this application I will be amending an existing incident file (assigned to this operator) for a vent or flare event, pursuant to 19.15.27 and 19.15.28 NMAC.
<input checked="" type="checkbox"/>	I acknowledge that amending an incident file does not replace original submitted application(s) or information and understand that any C-129 forms submitted to the OCD will be logged and stored as public record.
<input checked="" type="checkbox"/>	I hereby certify the statements in this amending report are true and correct to the best of my knowledge and acknowledge that any false statement may be subject to civil and criminal penalties under the Oil and Gas Act.
<input checked="" type="checkbox"/>	I acknowledge that the acceptance of any C-129 forms by the OCD does not relieve this operator of liability should their operations have failed to adequately investigate, report, and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment.
<input checked="" type="checkbox"/>	I acknowledge that OCD acceptance of any C-129 forms does not relieve this operator of responsibility for compliance with any other applicable federal, state, or local laws and/or regulations.

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 562937

CONDITIONS

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 562937
	Action Type: [C-129] Amend Venting and/or Flaring (C-129A)

CONDITIONS

Created By	Condition	Condition Date
marialuna2	If the information provided in this report requires further amendment(s), submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event.	3/13/2026