District I State of New Mexico Form C-103 1625 N. French Dr., Hobbs, NM 88240 Permit 113606 Energy, Minerals and Natural Resources Phone:(505) 393-6161 Fax:(505) 393-0720 WELL API NUMBER Oil Conservation Division 1301 W. Grand Ave., Artesia, NM 88210 30-021-20511 Phone:(505) 748-1283 Fax:(505) 748-9720 1220 S. St Francis Dr. Santa Fe, NM 87505 Indicate Type of Lease 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170 1220 S. St Francis Dr., Santa Fe, NM 87505 6. State Oil & Gas Lease No. Phone:(505) 476-3470 Fax:(505) 476-3462 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO MITCHELL A DIFFRENT RESERVIOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH 8. Well Number PROPOSALS.) 111L 1. Type of Well:C 9. OGRID Number 2. Name of Operator HESS CORPORATION 495 3. Address of Operator 10. Pool name or Wildcat P.O. BOX 840, SEMINOLE, TX 79360 4. Well Location Unit Letter 1650 S 760 W feet from the line and feet from the 1ine NMPM 18N 30E Range Harding Township County 11. Elevation (Show whether DR, KB, BT, GR, etc.) 4375 GR Pit or Below-grade Tank Application or Closure __ Depth to Groundwater_ Distance from nearest fresh water well__ Distance from nearest surface water_ Pit Type Below-Grade Tank: Volume_ _ mil bbls; Construction Material Pit Liner Thickness: Check Appropriate Box to Indicate Nature of Notice, Report or Other Data SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK | PLUG AND ABANDON | REMEDIAL WORK ALTER CASING TEMPORARILY ABANDON CHANGE OF PLANS COMMENCE DRILLING OPNS. | PLUG AND ABANDON | PULL OR ALTER CASING | MULTIPLE COMPL CASING/CEMENT JOB X Other: Other: Drilling/Cement 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. RU, safety meeting rig inspection, spud well, drill, circulate and condition, run surf csg, cement surf csg, test lines, wait on cement 4 hrs, drill plug and cement, circ and condition TOOOH, run log, Run production csg, circ and condition cement production csg, 460sx circ 59sx cement to surface. Wait on cement4hrs, Clean pit, ND BOP, RD 4/27/2010 Spudded well. Casing and Cement Program Weight Grade Fluid Hole Csg Est Dpth Pres Open String Sacks Yield Class Date Dpth Type Size Size lb/ft TOC Set Held 24 J-55 04/28/10 12.25 8.625 0 753 414 Surf 04/29/10 7.875 4.5 12.75 0 2230 515 I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan . SIGNATURE Electronically Signed TITLE Engineering Tech DATE 5/6/2010

E-mail address rsmith@hess.com

TITLE District Supervisor

Type or print name Rita Smith

Ed Martin

For State Use Only: APPROVED BY: Telephone No. 432-758-6726

DATE 5/11/2010 2:07:14 PM