UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

Lease Serial No.

SUNDRY Do not use thi abandoned we	JIC97 6. If Indian, Allottee or Tribe Name JICARILLA APACHE				
SUBMIT IN T	7. If Unit or CA/Agreement, Name and/or No.				
Type of Well		8. Well Name and No. TRIBAL C 1			
Name of Operator HILCORP ENERGY COMPAN		9. API Well No. 30-039-06655-0	0-C1		
3a. Address 382 ROAD 3100 AZTEC, NM 87410		Field and Pool or Exploratory Area BASIN TAPACITO			
4. Location of Well (Footage, Sec., T.		11. County or Parish, State			
Sec 6 T26N R3W SWSW 790		RIO ARRIBA CO	DUNTY, NM		
12. CHECK THE AF	PPROPRIATE BOX(ES) TO I	NDICATE NATURE OF	F NOTICE, I	REPORT, OR OTH	ER DATA
TYPE OF SUBMISSION	ON TYPE OF ACTION				
☐ Notice of Intent	☐ Acidize	□ Deepen	☐ Production	on (Start/Resume)	☐ Water Shut-Off
■ Subsequent Report	☐ Alter Casing	☐ Hydraulic Fracturing	☐ Reclamat		☐ Well Integrity
	Casing Repair	□ New Construction	Recompl		⊠ Other
☐ Final Abandonment Notice	☐ Change Plans ☐ Convert to Injection	☐ Plug and Abandon☐ Plug Back☐	☐ Temporarily Abandon☐ Water Disposal		
following completion of the involved testing has been completed. Final Abdetermined that the site is ready for fi Hilcorp Energy performed a bi wellbore schematic. Well is currently shut-in with p	radenhead repair for subject we	a multiple completion or record after all requirements, including the self. See attached summa	mpletion in a ne ing reclamation,	w interval, a Form 3160 have been completed a	0-4 must be filed once
14. I hereby certify that the foregoing is	Electronic Submission #539393	Y COMPANY, sent to the	Rio Puerco	•	
Name (Printed/Typed) ETTA TRUJILLO		• •	OPERATIONS/REGULATORY TECH SR		
Signature (Electronic S	Submission)	Date 12/04/20	020		
	THIS SPACE FOR FE	EDERAL OR STATE (OFFICE US	E	
Approved By ACCEPT	ED	JOE KILLIN TitlePETROLEI		ER	Date 12/30/2020
Conditions of approval, if any, are attached certify that the applicant holds legal or equal which would entitle the applicant to condu	iitable title to those rights in the subjec	orrant or ct lease Office Rio Puer	co		
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s			willfully to mak	te to any department or	agency of the United

Revisions to Operator-Submitted EC Data for Sundry Notice #539393

Operator Submitted BLM Revised (AFMSS)

Sundry Type: OTHER SR

JIC97 Lease: JIC97

Agreement:

Operator: HILCORP ENERGY COMPANY HILCORP ENERGY COMPANY

1111 TRAVIS STREET HOUSTON, TX 77002 382 ROAD 3100 AZTEC, NM 87410 Ph: 505-324-5161

ETTA TRUJILLO OPERATIONS REGULATORY TECH SR Admin Contact:

ETTA TRUJILLO OPERATIONS/REGULATORY TECH SR

OTHER SR

E-Mail: ettrujillo@hilcorp.com E-Mail: ettrujillo@hilcorp.com

Ph: 505-324-5161 Ph: 505-324-5161

ETTA TRUJILLO OPERATIONS REGULATORY TECH SR E-Mail: ettrujillo@hilcorp.com Tech Contact:

ETTA TRUJILLO OPERATIONS/REGULATORY TECH SR E-Mail: ettrujillo@hilcorp.com

Ph: 505-324-5161 Ph: 505-324-5161

Location:

NM RIO ARRIBA

State: County: NM RIO ARRIBA

BASIN TAPACITO Field/Pool: PC DK

TRIBAL C 1 TRIBAL C 1 Well/Facility:

Sec 6 T026N R03W Mer NMP SWSW 790FSL 1190FWL Sec 6 T26N R3W SWSW 790FSL 1190FWL

3003906655 - Tribal C 1

BH Repair

10/19/20 – RU. ND WH. NU BOP. Tbg hanger stuck. ND BOP. NU WH. SIW.

10/20/20 –ND WH. NU BOP. Jar on the hanger until free. TOOH w/the SIW.

10/21/20 – Unable to get 7-5/8 pkr & string mill into wellbore due to undersized the head. SIW.

10/22/20 – ND BOP ND TH. NU replacement tbg head. NU BOP. PU 6-3/4" bit. TIH to liner top @ 3833'. TOOH. PT WH. TIH RBP set @ 3652'. TOOH. SIW.

10/23/20 – Latch onto RBP to verify set. TOOH. TIH w/pkr set @ 3610'. PT csg f/3652' – t/3610' to 600psi. No test. TOOH w/pkr. MU RBP to 3578', unable to release. SIW.

10/26/20 – RU air unit. Establish circ. Latch onto RBP & work free. TOOH w/plug. Round trip 7-5/8" csg scraper to liner top 3833'. TOOH w/scraper.

10/27/20 – Set 7-5/8 RBP @ 3450', set AS1X Pkr @ 3416'. PT. No test. PT tbg. Good test. Pull RBP to 3000', Pkr @ 2961'. PT. No test. Pull RBP to 2000', Pkr @ 1961'. PT. No test. Release RBP & Pkr. TOOH. SIW.

10/28/20 – PU 7-5/8" AS1X pkr. Set @ 90' & again at 60'. PT csg to surface. Lost 200psi/min. PU 7-5/8" full bore tension pkr. Set @ 60', 30', 15', PT csg to surface. Lost 200 psi/min. LD pkr. SIW.

10/29/20 – RU WL. **Run csg caliper log f/3800' – t/surface. No test**. RD WL. Set RBP @ 455'. PT csg f/455' – t/surface. No test. LD pkr. Release RBP. SIW.

10/30/20 – RU WL. Set RBP @ 3060'. RD WL. TIH set 7-5/8" pkr @ 3047'. PT. lost 120psi/10mins. Set pkr @ 2019', 560psi lost 40psi/15mins. Set pkr @ 419' lost 0psi/20mins. TIH. SIW.

11/2/20 – Notified (Brandon Powell – NMOCD, Joe Killins – BLM, JOGA) path forward – Sqz w/cmt & circ cmt to surface, additional cmt into annulus. If hole is shallower, perf sqz @ 347' and cmt. PU pkr set @ 57', RBP set @ 3060'. PT w/600psi, lost 200psi/15mins Rel pkr. Set RBP @ 50'. Set pkr @ 33', PT w/600psi, lost 105psi/15mins. Release pkr and RBP. RU WL. TIH & shoot sqz perfs @ 347'. RD WL. Establish circ w/9bbls. Circ clean. SIW.

11/3/20 – PU pkr set @ 76'. Establish circ thru sqz perfs@347'. Circ 20bbls. LD pkr. PU cmt retainer set @ 297'. Mix & pump 148sxs Class G, 15.8PPG, 1.15yield. Circ 19sxs. Cmt to surface. SIW.

11/4/20 – PT test f/surface t/297'. Lost 300psi/1min. Circ established up BH. Isolate csg leak @ 41' – 61'. Set pkr @ 41'. PT, lost 100psi/15mins. No circ up BH. Release pkr. Shut-in well 1hr pressure build, BH-0 CSG-0. Establish inj rate down csg & up BH. PU RBP set @ 40', set pkr @ 8'. Test good. PT csg 600psi, lost 160psi/5mins. Release pkr & RBP. SIW. Received approval from Brandon Powell (NMOCD), Joe Killins (BLM), JOGA path forward – lay balance plug from ~75' to surface & sqz cmt. A secondary seal will be installed to fix WH leak.

11/5/20 – ND BOP. Weld stub up on 7-5/8 csg. Install secondary seals. NU BOP. PT. Good test. Set pkr @ 30'. PT csg f/30' t/surface. Good test. LD pkr. TIH to 75', **Mix & pump 21sxs Type III cmt, 14.6PPG, 1.37yield. Circ cmt to surface.** ND BOP. NU WH. SIW

11/9/20 - PU 3-1/2" drill collar & 6-3/4" tri cone bit. TOC @ 28'. DO cmt f/28' - t/75'. PT to 600psi, lost 60psi/15mins. PU drill collars & tagged TOC @ 274' (cmt retainer @ 297'). SIW.

3003906655 - Tribal C 1

BH Repair

11/10/20 – PT csg w/600psi, lost 30psi/30mins. DO cmt f/274' t/297'. Circ clean. TOOH w/drill collars. MU junk mill. Tag cmt retainer @ 297'. DO cmt retainer f/297' t/300'. Circ clean. SIW.

11/11/20 - TOOH w/drill collars & 6-3/4". TIH w/6-3/4" tri cone bit. DO cmt f/318' t/334'. TOOH w/drill collars. SIW.

11/12/20 – Received approval from Brandon Powel (NMOCD), Joe Killins (BLM), JOGA – on path forward to leave RBP @ 3060' & tbg @ ~2700'. TIH w/drill collars. Tag TOC @ 334'. Establish circ. DO cmt. Circ clean. PT failed. TOOH. TIH with 2-3/8" tbg, 83jnts set @ 2700', SN @ 2699'. Set RBP @ 3060'. SIW.

11/13/20 – ND BOP NU WH. RD Release rig.


Well left shut-in with plans to P&A or return back to production in 2021.

Hilcorp Energy Compar

Current Schematic - Version 3

Well Name: TRIBAL C #1

Surface Legal Location ield Name Well Configuration Type 3003906655 M-6-26N-3W **BASIN** 1414 **NEW MEXICO** Ground Elevation (ft) Original KB/RT Elevation (ft) KB-Ground Distance (ft) KB-Casing Flange Distance (ft) KB-Tubing Hanger Distance (ft) 6,948.00 6,959.00 11 00



<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410

Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 13777

CONDITIONS OF APPROVAL

Operator:			OGRID:	Action Number:	Action Type:
HILCORP ENERGY COMPANY	1111 Travis Street	Houston, TX77002	372171	13777	C-103X

OCD Reviewer	Condition
ahvermersch	None