

U.S. Department of the Interior BUREAU OF LAND MANAGEMENT

Sundry Print Report

Well Name: DIAMONDBACK 24 Well Location: T19S / R32E / SEC 24 / County or Parish/State: LEA /

FEDERAL COM SWSE / 32.64047 / 103.717618

Well Number: 01 Type of Well: CONVENTIONAL GAS Allottee or Tribe Name:

WELL

Lease Number: NMNM077006 Unit or CA Name: Unit or CA Number:

US Well Number: 300253562200S2 Well Status: Producing Oil Well Operator: CHISHOLM ENERGY

**OPERATING LLC** 

### **Notice of Intent**

Type of Submission: Notice of Intent

Type of Action Temporary Abandonment

Date Sundry Submitted: 01/14/2021 Time Sundry Submitted: 09:39

Date proposed operation will begin: 01/20/2021

**Procedure Description:** Chisholm Energy Operating, LLC TA'd this well on 11/01/2019; Set CIBP @ 8880'TVD and dump bailed cmnt on top of CIBP. Well failed MIT; Before planned operations, it was discovered that this well had been perforated by the previous operator and not reported to BLM or OCD for record. These perforations are from 9006'-8860'; It is our belief that the cmnt that was dump bailed did not fill the perforations above the CIBP from 8880'-8860' thus causing it to fail the MIT. Chisholm Energy Operating respectfully requests to TA this will with the procedure as shown below. Procedure: RIH; Set CIBP @ 8810'TVD Dump Bail 35' of Class C Cmnt w/Est TOC being at 8775'TVD NOI to run an MIT after TA will be submitted to BLM

### **Surface Disturbance**

Is any additional surface disturbance proposed?: No

**Accepted for Record Only** 

3/17/21 NMOCD

### **NOI Attachments**

**Procedure Description** 

Diamondback\_24\_Fed\_Com\_1\_20210114093901.pdf

FEDERAL COM

Well Location: T19S / R32E / SEC 24 /

SWSE / 32.64047 / 103.717618

County or Parish/State: LÉ

Well Number: 01

Type of Well: CONVENTIONAL GAS

WELL

Lease Number: NMNM077006 **Unit or CA Name:**  Allottee or Tribe Name:

**Unit or CA Number:** 

**US Well Number:** 300253562200S2 Well Status: Producing Oil Well **Operator: CHISHOLM ENERGY** 

**OPERATING LLC** 

# **Conditions of Approval**

### **Specialist Review**

TA COA 20210121123323.docx

## **Operator Certification**

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a submission of Form 3160-5 or a Sundry Notice.

**Operator Electronic Signature: ELROD** Signed on: JAN 14, 2021 09:37 AM

Name: CHISHOLM ENERGY OPERATING LLC

Title: Senior Regulatory Technician

Street Address: 801 CHERRY STREET SUITE 1200 UNIT 20

City: FORT WORTH State: TX

Phone: (817) 953-6063

Email address: info@chisholmenergy.com

### **Field Representative**

**Representative Name:** 

**Street Address:** 

State: City: Zip:

Phone:

**Email address:** 

# **BLM Point of Contact**


Signature: Jonathon Shepard

**BLM POC Name:** Jonathon W Shepard **BLM POC Title:** Petroleum Engineer

**BLM POC Phone:** 5752345972 BLM POC Email Address: jshepard@blm.gov

**Disposition:** Approved Disposition Date: 01/21/2021

Page 2 of 2



#### **BUREAU OF LAND MANAGEMENT**

Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

### **Conditions of Approval for Temporary Abandonment of Wells**

**Definition:** A temporarily abandoned well is a completion that is not capable of production in paying quantities, but which may have future value. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

- 1. TA status will be effective for a period of up to one year from the date of sundry approval and can be renewed annually thereafter per IM NM-2016-017.
- 2. A bridge plug (CIBP) must be installed 50 to 100 feet above any open perforations or open hole. The CIBP must be capped with either a minimum of 25 sacks of cement if placed with tubing or 35 feet of cement if placed with a bailer. The top of the cement must be verified by tagging.
- 3. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. If the well does not pass the casing integrity test, then the operator shall, within 30 days, submit a procedure to either repair the casing or to plug and abandon the well.
- 4. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 5. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if it is not isolated by a packer.
- 6. A bradenhead test must be conducted. If the test indicates a problem, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
- 7. Submit a subsequent Sundry Notice (Form 3160-5) with the following information:
  - a. A well bore diagram with all perforations, CIBP's, and tops of cement on CIBP's.
  - b. A description of the temporary abandonment procedure.
  - c. A clear copy or the original of the pressure test chart.

#### BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

## **Conditions of Approval for Temporary Abandonment of Wells**

**Definition:** A temporarily abandoned well is a completion that is not capable of production in paying quantities, but which may have future value. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

- 1. TA status will be effective for a period of up to one year from the date of sundry approval and can be renewed annually thereafter per IM NM-2016-017.
- 2. A bridge plug (CIBP) must be installed 50 to 100 feet above any open perforations or open hole. The CIBP must be capped with either a minimum of 25 sacks of cement if placed with tubing or 35 feet of cement if placed with a bailer. The top of the cement must be verified by tagging.
- 3. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. If the well does not pass the casing integrity test, then the operator shall, within 30 days, submit a procedure to either repair the casing or to plug and abandon the well.
- 4. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 5. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if it is not isolated by a packer.
- 6. A bradenhead test must be conducted. If the test indicates a problem, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
- 7. Submit a subsequent Sundry Notice (Form 3160-5) with the following information:
  - a. A well bore diagram with all perforations, CIBP's, and tops of cement on CIBP's.
  - b. A description of the temporary abandonment procedure.
  - c. A clear copy or the original of the pressure test chart.

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III
1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

# **State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 15271

#### **CONDITIONS OF APPROVAL**

Operator:			OGRID:	Action Number:	Action Type:
CHISHOLM ENERGY OPERATING, LLC	801 Cherry Street	Fort Worth, TX76102	372137	15271	C-103X

OCD Reviewer	Condition
kfortner	None