Submit I Copy To Appropriate District

	Energy, Minerals and Nat	lurai Resources		sed July 18, 2013
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION		30-025-35303 5. Indicate Type of Lease	
<u>District III</u> - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Fra		STATE FE	E X
<u>District IV</u> - (505) 476-3460	Santa Fe, NM 8	37505	6. State Oil & Gas Lease No	
1220 S. St. Francis Dr., Santa Fe, NM 87505				
SUNDRY NOT	ICES AND REPORTS ON WELL		7. Lease Name or Unit Agre	ement Name
(DO NOT USE THIS FORM FOR PROPO	OSALS TO DRILL OR TO DEEPEN OR PL CATION FOR PERMIT" (FORM C-101) F	LUG BACK TO'A	State CK	
1. Type of Well: Oil Well	Gas Well Other		8. Well Number #005	
2. Name of Operator			9. OGRID Number	
Apache Corporation 3. Address of Operator			873 10. Pool name or Wildcat	,
CONTRACTOR	2000 Mid-1 TV 7070F		900 ST 100 ST 10	
 303 Veterans Airpark Lane, Ste Well Location 	. 3000, Midiand, [X /9/05		Penrose Skelly: Grayburg	
Unit Letter K :	1743 feet from the S	line and	1680 feet from the	W line
Section 19	Township 21S R		NMPM County	
ASSESSED BY THE RESIDENCE OF THE PERSON OF T	11. Elevation (Show whether DI			N. S. Trees.
	3510' GR			
10.01	4 . w w	1 . 034 4	B = -	
12. Check	Appropriate Box to Indicate N	Nature of Notice,	Report or Other Data	
NOTICE OF IN	NTENTION TO:	SUB	SEQUENT REPORT O	F:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR		G CASING
TEMPORARILY ABANDON □	CHANGE PLANS	COMMENCE DRI		
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	T JOB	PNR
DOWNHOLE COMMINGLE				
CLOSED-LOOP SYSTEM OTHER:	П	OTHER:		
of starting any proposed we	ork). SEE RULE 19.15.7.14 NMA	C. For Multiple Cor	l give pertinent dates, includin npletions: Attach wellbore dia	gram of
of starting any proposed we proposed completion or reconstruction. 1. 02/08/21 Move in P&A equipment	ork). SEE RULE 19.15.7.14 NMA	C. For Multiple Cor	npletions: Attach wellbore dia	egram of
of starting any proposed we proposed completion or reconstruction. 1. 02/08/21 Move in P&A equipme @ 3650'-3310'. Spot 2 @ 1070'. Spot 30 sx c	ork). SEE RULE 19.15.7.14 NMA completion. ent. Tag CIBP @ 3650'. Pretest 5 1/2 cs	C. For Multiple Cor	npletions: Attach wellbore dia	egram of
of starting any proposed we proposed completion or reconstruction. 1. 02/08/21 Move in P&A equipme @ 3650'-3310'. Spot 2 @ 1070'. Spot 30 sx c	ork). SEE RULE 19.15.7.14 NMA completion. ent. Tag CIBP @ 3650'. Pretest 5 1/2 cs	C. For Multiple Cor	npletions: Attach wellbore dia	egram of
of starting any proposed we proposed completion or reconstruction. 1. 02/08/21 Move in P&A equipme @ 3650'-3310'. Spot 2 @ 1070'. Spot 30 sx c	ork). SEE RULE 19.15.7.14 NMA completion. ent. Tag CIBP @ 3650'. Pretest 5 1/2 cs	C. For Multiple Cor	npletions: Attach wellbore dia	egram of
of starting any proposed we proposed completion or reconstruction. 1. 02/08/21 Move in P&A equipme @ 3650'-3310'. Spot 3 @ 1070'. Spot 30 sx of	ork). SEE RULE 19.15.7.14 NMA completion. ent. Tag CIBP @ 3650'. Pretest 5 1/2 cs	C. For Multiple Cor	npletions: Attach wellbore dia	egram of
of starting any proposed we proposed completion or reconstruction. 1. 02/08/21 Move in P&A equipme @ 3650'-3310'. Spot 2 @ 1070'. Spot 30 sx c	ork). SEE RULE 19.15.7.14 NMA completion. ent. Tag CIBP @ 3650'. Pretest 5 1/2 cs	C. For Multiple Cor	npletions: Attach wellbore dia	egram of
of starting any proposed we proposed completion or reconstruction. 1. 02/08/21 Move in P&A equipme @ 3650'-3310'. Spot 2 @ 1070'. Spot 30 sx c	ork). SEE RULE 19.15.7.14 NMA completion. ent. Tag CIBP @ 3650'. Pretest 5 1/2 cs	C. For Multiple Cor	npletions: Attach wellbore dia	egram of
of starting any proposed we proposed completion or reconstruction. 1. 02/08/21 Move in P&A equipme @ 3650'-3310'. Spot 2 @ 1070'. Spot 30 sx c	ork). SEE RULE 19.15.7.14 NMA completion. ent. Tag CIBP @ 3650'. Pretest 5 1/2 cs	C. For Multiple Cor	npletions: Attach wellbore dia	agram of C cmt g TOC LA
of starting any proposed we proposed completion or reconstruction of reconstruction of reconstruction of the start of the	ork). SEE RULE 19.15.7.14 NMA completion. ent. Tag CIBP @ 3650'. Pretest 5 1/2 cs 25 sx class C cmt @ 2508'-2308'. Spot 2 class C cmt @ 300' in 5 1/2 csg to surface	C. For Multiple Con	npletions: Attach wellbore dia	agram of C cmt g TOC LA
of starting any proposed we proposed completion or reconstruction of reconstruction of reconstruction of the start of the	ork). SEE RULE 19.15.7.14 NMA completion. ent. Tag CIBP @ 3650'. Pretest 5 1/2 cs	C. For Multiple Con	npletions: Attach wellbore dia	agram of C cmt g TOC LA
of starting any proposed we proposed completion or reconstruction of reconstruction of reconstruction of the start of the	ork). SEE RULE 19.15.7.14 NMA completion. ent. Tag CIBP @ 3650'. Pretest 5 1/2 cs 25 sx class C cmt @ 2508'-2308'. Spot 2 class C cmt @ 300' in 5 1/2 csg to surface	C. For Multiple Con	npletions: Attach wellbore dia	agram of C cmt g TOC LA
of starting any proposed we proposed completion or reconstruction of reconstruction of reconstruction of the starting and proposed we proposed complete.	ork). SEE RULE 19.15.7.14 NMA completion. ent. Tag CIBP @ 3650'. Pretest 5 1/2 cs 25 sx class C cmt @ 2508'-2308'. Spot 2 class C cmt @ 300' in 5 1/2 csg to surface	C. For Multiple Conseq 500 psi 15 min ok. Ci 25 sx class C cmt @ 12 ce. Cut off wellhead & late:	rc 60 bbls MLF < spot 35 sx class (58'-1062' w/2% calcium, WOC, Ta remove, Install dry hole marker, P8	agram of C cmt g TOC LA
of starting any proposed we proposed completion or reconstruction of reconstruction of reconstruction of the proposed complete. 1. 02/08/21 Move in P&A equipme @ 3650'-3310'. Spot 2 @ 1070'. Spot 30 sx of complete.	ork). SEE RULE 19.15.7.14 NMA completion. ent. Tag CIBP @ 3650'. Pretest 5 1/2 cs 25 sx class C cmt @ 2508'-2308'. Spot 2 class C cmt @ 300' in 5 1/2 csg to surface	C. For Multiple Conseq 500 psi 15 min ok. Ci 25 sx class C cmt @ 12 ce. Cut off wellhead & late:	rc 60 bbls MLF < spot 35 sx class (58'-1062' w/2% calcium, WOC, Ta remove, Install dry hole marker, P8	agram of C cmt g TOC LA
of starting any proposed we proposed completion or recompletion or recomplete. 1. 02/08/21 Move in P&A equipme @ 3650'-3310'. Spot 2 @ 1070'. Spot 30 sx of complete.	ork). SEE RULE 19.15.7.14 NMA completion. ent. Tag CIBP @ 3650'. Pretest 5 1/2 cs 25 sx class C cmt @ 2508'-2308'. Spot 2 class C cmt @ 300' in 5 1/2 csg to surface	C. For Multiple Conseq 500 psi 15 min ok. Ci 25 sx class C cmt @ 12 ce. Cut off wellhead & late:	rc 60 bbls MLF < spot 35 sx class 58'-1062' w/2% calcium. WOC. Ta remove. Install dry hole marker. P8	agram of C cmt g TOC LA
of starting any proposed we proposed completion or recompletion or recomplete. 1. 02/08/21 Move in P&A equipme @ 3650'-3310'. Spot 3 @ 1070'. Spot 30 sx of complete. Spud Date: hereby certify that the information IGNATURE	ork). SEE RULE 19.15.7.14 NMA completion. ent. Tag CIBP @ 3650'. Pretest 5 1/2 cs 25 sx class C cmt @ 2508'-2308'. Spot 2 class C cmt @ 300' in 5 1/2 csg to surfact above is true and complete to the b	C. For Multiple Conseq 500 psi 15 min ok. Ci 25 sx class C cmt @ 12 ce. Cut off wellhead & late:	rc 60 bbls MLF < spot 35 sx class 58'-1062' w/2% calcium. WOC. Ta remove. Install dry hole marker. P8	agram of C cmt g TOC LA
of starting any proposed we proposed completion or recompletion or recomplete. 1. 02/08/21 Move in P&A equipme @ 3650'-3310'. Spot 2 @ 1070'. Spot 30 sx of complete. Spud Date: hereby certify that the information of the state Use Only	Rig Release Dabove is true and complete to the balance of the bala	C. For Multiple Consider Special Speci	rc 60 bbls MLF < spot 35 sx class 58'-1062' w/2% calcium. WOC. Ta remove. Install dry hole marker. P8 and belief. DATE 02/e@yahoo.com PHONE: 432-	agram of C cmt g TOC LA
of starting any proposed we proposed completion or recomplete. 1. 02/08/21 Move in P&A equipme @ 3650'-3310'. Spot 2 @ 1070'. Spot 30 sx of complete. Spud Date: hereby certify that the information with the information of the state Use Only APPROVED BY:	Rig Release Date of the balance of t	c. For Multiple Consists 500 psi 15 min ok. Ci 25 sx class C cmt @ 12 ce. Cut off wellhead & consists of my knowledge Agent se: sunsetwellservice mpliance Officer A	rc 60 bbls MLF < spot 35 sx class 58'-1062' w/2% calcium. WOC. Ta remove. Install dry hole marker. P8 and belief. DATE 02/ DATE 4/16	agram of C cmt g TOC LA
of starting any proposed we proposed completion or recompletion or recomplete. 1. 02/08/21 Move in P&A equipme @ 3650'-3310'. Spot 2 @ 1070'. Spot 30 sx of complete. Spud Date: hereby certify that the information are given by the complete of the complete. IGNATURE	Rig Release Date of the balance of t	c. For Multiple Consists 500 psi 15 min ok. Ci 25 sx class C cmt @ 12 ce. Cut off wellhead & consists of my knowledge Agent se: sunsetwellservice mpliance Officer A	rc 60 bbls MLF < spot 35 sx class 58'-1062' w/2% calcium. WOC. Ta remove. Install dry hole marker. P8 and belief. DATE 02/ DATE 4/16	agram of C cmt g TOC LA
of starting any proposed we proposed completion or recompletion or recomplete. 1. 02/08/21 Move in P&A equipme @ 3650'-3310'. Spot 2 @ 1070'. Spot 30 sx of complete. pud Date: hereby certify that the information IGNATURE	Rig Release D. above is true and complete to the b TITLE Bagley TITLE Con TITLE Con TITLE Con	c. For Multiple Consists 500 psi 15 min ok. Ci 25 sx class C cmt @ 12 ce. Cut off wellhead & consists of my knowledge Agent se: sunsetwellservice mpliance Officer A	rc 60 bbls MLF < spot 35 sx class 58'-1062' w/2% calcium. WOC. Ta remove. Install dry hole marker. P8 and belief. DATE 02/ DATE 4/16	09/21 -561-8600

State of New Mexico

Form C-103

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III
1000 Rio Brazos Rd., Aztec, NM 87410

Phone:(505) 334-6178 Fax:(505) 334-6170 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

COMMENTS

Action 17655

COMMENTS

Operator	:		OGRID:	Action Number:	Action Type:
	APACHE CORPORATION	303 Veterans Airpark Ln	873	17655	C-103P
#1000	Midland, TX79705				

Created By	Comment	Comment Date
plmartinez	DATA ENTRY PM	04/28/2021

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III
1000 Rio Brazos Rd., Aztec, NM 87410

Phone:(505) 334-6178 Fax:(505) 334-6170 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 17655

CONDITIONS OF APPROVAL

Operator	:		OGRID:	Action Number:	Action Type:
	APACHE CORPORATION	303 Veterans Airpark Ln	873	17655	C-103P
#1000	Midland, TX79705				

OCD Reviewer	Condition
kfortner	None