eceined by OCD: 4/30/2021 9:52:47 Office				Form C-103	
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		Revised July 18, 2013 WELL API NO.		
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-015-38961 5. Indicate Type of Lease		
<u>District III</u> – (505) 334-6178	1220 South St. Fran	1220 South St. Francis Dr.		FEE	
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	Santa Fe, NM 87	505	STATE FEE 6. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM 87505					
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Unit Agreement Name Pardue B 8808 JV-P		
1. Type of Well: Oil Well	PROPOSALS.) 1. Type of Well: Oil Well 🕅 Gas Well 🗍 Other			7	
2. Name of Operator BTA Oil Producers LLC			9. OGRID Number: 260297		
3. Address of Operator			10. Pool name or Wildcat		
104 S. Pecos, Midland, TX 79701			Loving; Delaware East; 40370		
4. Well Location					
Unit Letter <u>L</u> : 1980	<u>)</u> feet from the <u>South</u> line and	<u>330</u> feet from	n the <u>West</u> line		
Section 11	*	Range 28E		Eddy County	
	11. Elevation (<i>Show whether DR</i> ,	RKB, RT, GR, etc	.)		
	2990' GL				
12 Check A	Appropriate Box to Indicate Na	ature of Notice	Report or Other D	ata	
			-		
NOTICE OF IN			SEQUENT REPO		
		REMEDIAL WOR		_TERING CASING 🗌	
TEMPORARILY ABANDON		CHANGE PLANS COMMENCE DRILLING C MULTIPLE COMPL CASING/CEMENT JOB			
PULL OR ALTER CASING		CASING/CEMEN			
CLOSED-LOOP SYSTEM					
OTHER:		OTHER:			
	leted operations. (Clearly state all p				
proposed completion or rec	ork). SEE RULE 19.15.7.14 NMAC	. For Multiple Co	Simpletions: Attach well	bore diagram of	
proposed completion of ree	ompiction.				
THE FOLLOWING WAS	PERFORMED IN ORDER TO ReC	COMPLETE THE	CHERRY CANYON Z	ZONE.	
1) New Observe Commen	D. f	2500 ² (2 amf 2	0 (1, , 1, , , , , , 1) 0/20/20	10	
	Perforations were added @ 3502 reak down @ 1800 psi @ .5 bbl/n		36 holes total) $9/20/20$	119.	
	NEFE acid to break down form				
4) Swab back load with					
· · · · · · · · · · · · · · · · · · ·	39,460# resin coated proppant @	20 bpm, avg. ps	si 3167.		
	ks, overnight recovering 270 bbl				
	, RIH w/production equipment.				
8) Returned well to pro-	duction.				
Spud Date:	Rig Release Da	ta:		7	
9/18/2019	Kig Kelease Da	9/26/2019			
I hereby certify that the information	above is true and complete to the be	st of my knowleds	ge and belief.		
	ľ				
	λ				
7 emi	Epne				
SIGNATURE		uction Superinten	<u>dent</u> DATE: <u>04/28/20</u>	<u>21</u>	
The second state of the se	P	DUCUE	122 (82 2752		
Type or print name <u>Kevin Jones</u> For State Use Only	E-mail address: <u>kjones@btaoil.</u>	<u>com</u> PHONE: <u>4</u>	+32-682-3/33 .		
Kurt Simmon	s NMO	CD		05/07/2021	
APPROVED BY:	TITLE		DATE	5570772021	

.

Conditions of Approval (if any): Released to Imaging: 5/7/2021 1:24:42 PM

BTA Oil Producers 8808 JV-P Pardue "B" #7 Procedure to Complete Cherry Canyon Eddy County, NM

API #: 30-015-38961 SPUD: 3/11/2012 ORIGINAL COMPLETION: 6/1/2012

PBTD: 5367' **TD**: 6051'

K.B. ELEVATION: 3012' (22' KB) G.L. ELEVATION: 2990'

SURFACE CASING: 13-3/8" 54.5# J-55 @ 458' w/ 615 sx cmt TOC @ Surface via Circulation Hole Size: 17-1/2"

INTERMEDIATE CASING: 8-5/8" 32# J-55 @ 2638' w/ 705 sx cmt TOC @ Surface via Circulation Hole Size: 11"

PRODUCTION CASING: 5-1/2" 17# J-55 @ 5451' w/ 705 sx cmt TOC @ Surface via Circulation Hole Size: 7-7/8"

PERFORATIONS:

OPEN – Brushy Canyon: 4700' - 4712'; 4720' – 4732'; 4740' – 4748' (67 holes – 2 JSPF)

FISH IN HOLE:

Possibly two pieces, drill collars @ 5477' – 5585' (108') and drill collars & drilling BHA including motor and 7-7/8" bit @ 5800' - 6003 (203').

PRODUCTION EQUIPMENT IN HOLE:

Tubing String (6/8/2018)		R	R <u>od String (6/8/2018)</u>				
-	139 jts	39 jts 2-7/8" Tubing			Polished Rod 1-1/4" X ?'		
		TAC @ 4525'			w/ 1-1/2" X 12' PRL		
	4 jts	jts 2-7/8" Tubing		178	3/4" X 25' Sucker Rods		
		SN @ 4655'		6	1-1/2" K Bars		
		4' Perforated Sub			25-150-RXBC-16-5 Rod Pump		
	1 jt	Mud Anchor with BP					
		EOT @ 4692'					
				<u> </u>			

8808 JV-P Pardue B #7 Complete Cherry Canyon Eddy County, New Mexico Capacities:

Capacities:				
2-7/8" 6.5# Tubing	0.00579 bbl/ft			
5-1/2" 15.5# Casing	0.0238 bbl/ft			
Between tbg and casing	0.0158 bbl/ft			

Procedure:

- 1. MIRU pulling unit.
- 2. Unseat pump.
- 3. Hot water tubing and rods w/ 60 BBL water and paraffin dispersant.
- 4. POOH & LD pump. POOH w/ rods & sinker bars. (LD if needed to RDMO while waiting for frac crew.)
- 5. ND WH. Release TAC. NU 7-1/16" 5M BOP.
- 6. POOH & standback 2-7/8" production tubing. LD SN and mud joint inspect for possible replacement.
- 7. PU 5-1/2" CIBP on tubing. RIH to set CIBP @ +/- 4680'.
- 8. Load hole with 2% KCl water and pressure test CIBP to 500 psi for 10 minutes.
- 9. POOH and LD tubing to 3460'.
- 10. Continue POOH & standback remainder of tubing.
- 11. MIRU WL Unit.
- 12. RIH w/ 3-1/8" perforating guns loaded w/ 4 JSPF.


Perforate 3502' – 3520' (Cherry Canyon).

Correlate depths with Compensated Neutron Gamma Ray / Collar Log dated 4/14/2012 (Black Warrior Wireline for BTA Oil Producers, Pardue B #7, Loving East Field)

- 13. RIH w/ dump bailer and dump bail 35' cement on top of CIBP.
- 14. RD WL Unit.
- 15. RU Tubing Testers.
- 16. PU 2.313" XN nipple, 6' tbg sub, and AS-1X packer.
- 17. RIH on 2-7/8" production tubing while pressure testing to 6000 psi.
- 18. Set packer @ +/- 3460'.
- 19. Pressure test 5-1/2" X 2-7/8" casing annulus from 3460' to surface to 1000 psi.
- 20. Break down perfs w/ pressure using 2% KCl.
- 21. MIRU Acidizing Equipment.
- 22. Acidize Cherry Canyon with 1000 gallons 10% NEFE HCl acid and displace 2 BBL past perfs. SWI as advised.
- 23. As soon as possible, swab test and report results back to office.
- 24. Spot 3 frac tanks and fill each with 400 BBL fresh water
- 25. MIRU frac crew.
- 26. Frac Cherry Canyon as per attached frac design. Displace to top perf.
- 27. Flow down well. Swab test and report results to the office.
- 28. POOH and LD packer.
- 29. Add TAC to BHA for the production string. Space out TAC above new perfs.
- 30. PU production rod pumping BHA and RIH. Place pump intake near top of new perfs.
- 31. ND BOP, Set TAC, NU WH.
- 32. PU and RIH w/ pump and rods. Load and Test. Hang on well.
- 33. RDMO pulling unit. Put well on production.

Estimated Cost: Cherry Canyon Frac: \$288,305

BH - 8/13/2019



District I 1625 N. French Dr., Hobbs, NM 88240

District II

District IV

Phone:(575) 393-6161 Fax:(575) 393-0720

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

District III 1000 Rio Brazos Rd., Aztec, NM 87410 CONDITIONS

Action 26428

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS OF APPROVAL

Operator:				OGRID:	Action Number:	Action Type:
BTA OIL PRODUCERS, LLC	104 S Pecos	Midland, TX79701		260297	26428	C-103R
OCD Reviewer			Cond	ition		
ksimmons			None			