
Form 3160-3 (June 2015) UNITED STATES	2			FORM OMB No Expires: Ja	b. 1004-0	137
DEPARTMENT OF THE IN BUREAU OF LAND MANA	5. Lease Serial No. NMNM105213					
APPLICATION FOR PERMIT TO D		6. If Indian, Allotee	or Tribe	Name		
la. Type of work: 🖌 DRILL	EENT	ER		7. If Unit or CA Agr	eement, 1	Name and No.
1b. Type of Well:	ther			8. Lease Name and V	Well No	
Ic. Type of Completion: Hydraulic Fracturing	ngle Z	Cone Multiple Zone		FULLY LOADED 1		ОСОМ
2. Name of Operator DEVON ENERGY PRODUCTION COMPANY LP				9. API Well No.	0 015	48492
3a. Address 333 WEST SHERIDAN AVE, OKLAHOMA CITY, OK 7310		Phone No. <i>(include area code</i> ) 235-3611		10. Field and Pool, of PIERCE CROSSIN	1	5
4. Location of Well ( <i>Report location clearly and in accordance w</i> At surface SENW / 1516 FNL / 1405 FWL / LAT 32.235				11. Sec., T. R. M. or SEC 12/T24S/R29		Survey or Area
At proposed prod. zone LOT 4 / 20 FNL / 330 FWL / LAT	32.2	53911 / LONG -103.94566	65			
14. Distance in miles and direction from nearest town or post offi	.ce*			12. County or Parish EDDY	1	13. State NM
15. Distance from proposed* location to nearest property or lease line, ft. (Also to nearest drig. unit line, if any)	16.1	No of acres in lease	17. Spacin 480.0	ng Unit dedicated to th	his well	
<ul> <li>18. Distance from proposed location*</li> <li>to nearest well, drilling, completed, applied for, on this lease, ft.</li> <li>939 feet</li> </ul>		Proposed Depth 4 feet / 16862 feet		BIA Bond No. in file		
21. Elevations (Show whether DF, KDB, RT, GL, etc.) 3103 feet		Approximate date work will s 0/2021	tart*	23. Estimated durati 45 days	on	
	24.	Attachments				
The following, completed in accordance with the requirements of (as applicable)	f Onsh	ore Oil and Gas Order No. 1	, and the H	Iydraulic Fracturing ru	ule per 43	3 CFR 3162.3-3
<ol> <li>Well plat certified by a registered surveyor.</li> <li>A Drilling Plan.</li> <li>A Surface Use Plan (if the location is on National Forest System SUPO must be filed with the appropriate Forest Service Office</li> </ol>		Item 20 above).ds, the5. Operator certification	ation.	s unless covered by an mation and/or plans as	-	×
25. Signature (Electronic Submission)	Name (Printed/Typed)         Date           JENNY HARMS / Ph: (800) 583-3866         10/05/2020			2020		
Title Regulatory Compliance Professional						
Approved by (Signature) (Electronic Submission)		Name (Printed/Typed) Cody Layton / Ph: (575) 2	234-5959		Date 03/23/2	2021
Title Assistant Field Manager Lands & Minerals		Office Carlsbad Field Office				
Application approval does not warrant or certify that the applicant applicant to conduct operations thereon. Conditions of approval, if any, are attached.						
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, m of the United States any false, fictitious or fraudulent statements of					iny depar	tment or agency




\*(Instructions on page 2)

.

(Continued on page 2)





nter	nt X		As Dri	lled						
API ‡	ŧ									
									Well Number 231H	
	Off Poin					·				
JL	Section 12	Township 24S	Range 29E	Lot	Feet 2578 FNL	From N/S	Feet 266 FWL	From E/W	County EDDY	
Latitude Longitude NAD									NAD	
	-103.9458									
	2323				-103.9458				83	
32.2	Take Pc	oint (FTP)								
32.2	Take Pc	Township	Range	Lot	Feet	From N/S	Feet 330	From E/W WEST	County	
32.2 First UL E Latitu	Take Pc Section 12	Township 24-S		Lot		SOUTH	Feet 330	From E/W WEST		
32.2 First UL E Latitu 32.2	Take Pc Section 12 Ide 232414°	Township 24-S	Range	Lot	Feet 2557 Longitude	SOUTH			County EDDY NAD	
32.2 irst UL E Latitu 32.2 ast UL	Take Pc Section 12 232414° Take Po Section	Township 24-S int (LTP) Township	Range 29-E Range	Lot	Feet 2557 Longitude -103.9455 Feet	SOUTH	330 Feet	WEST	County EDDY NAD 83 County	
32.2 irst UL E Latitu 32.2	Take Pc Section 12 232414° Take Po Section 1	Township 24-S int (LTP)	Range 29-E		Feet 2557 Longitude -103.9455	SOUTH	330	WEST	County EDDY NAD 83	

Is this well the defining well for the Horizontal Spacing Unit?

Is this well an infill well?

YES
-----

If infill is yes provide API if available, Operator name and well number for Defining well for Horizontal Spacing Unit.

NO

API #		
Operator Name:	Property Name:	Well Number
		KZ 06/29/2018

District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy, Minerals and Natural Resources Department

Submit Original to Appropriate District Office

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

#### GAS CAPTURE PLAN

#### Date: September 30, 2020

 $\boxtimes$  Original

Devon & OGRID No.: Devon Energy Production Co., L.P. 6137

□ Amended - Reason for Amendment:

This Gas Capture Plan outlines actions to be taken by the Devon to reduce well/production facility flaring/venting for new completion (new drill, recomplete to new zone, re-frac) activity.

Note: Form C-129 must be submitted and approved prior to exceeding 60 days allowed by Rule (Subsection A of 19.15.18.12 NMAC).

#### Well(s)/Production Facility – Name of facility

The well(s) that will be located at the production facility are shown in the table below.

Well Name	ΑΡΙ	SHL FOOTAGES				Expected MCF/D	Flared or Vented	СТВ	
FULLY LOADED 12-13 FED									Fully Loaded
COM 231H		12-24S-29E	2256	FNL	1233	FWL			12 CTB 2
FULLY LOADED 12-1 FED			2397		982				Fully Loaded
COM 231H		12-24S-29E	2397	FNL	962	FWL			12 CTB 2
FULLY LOADED 12-13 FED			1516		1405				Fully Loaded
COM 232H		12-24S-29E	1516	FNL	1405	FWL			12 CTB 2
FULLY LOADED 12-1 FED			2397		1012				Fully Loaded
COM 232H		12-24S-29E	2397	FNL	1012	FWL			12 CTB 2
FULLY LOADED 12-13 FED			1516		1435				Fully Loaded
COM 233H		12-24S-29E	1516	FNL	1435	FWL			12 CTB 2
FULLY LOADED 12-1 FED			2207		1042				Fully Loaded
COM 233H		12-24S-29E	2397	FNL	1042	FWL			12 CTB 2

#### **Gathering System and Pipeline Notification**

Well(s) will be connected to a production facility after flowback operations are complete, if DCP system is in place. The gas produced from production facility is dedicated to <u>DCP</u> and will be connected to <u>DCP</u> low/high pressure gathering system located in Lea County, New Mexico. It will require 4442' of pipeline to connect the facility to low/high pressure gathering system. Devon will build the line to DCP and then after the line is ready for service, Devon give the to DCP for operations. <u>Devon</u> provides (periodically) to <u>DCP</u> a drilling, completion and estimated first production date for wells that are scheduled to be drilled in the foreseeable future. In addition, <u>Devon</u> and <u>DCP</u> have periodic conference calls to discuss changes to drilling and completion schedules. Gas from these wells will be processed at <u>DCP</u> Processing Plant located in the reference table. The actual flow of the gas will be based on compression operating parameters and gathering system pressures.

#### Flowback Strategy

After the fracture treatment/completion operations, well(s) will be produced to temporary production tanks and gas will be flared or vented. During flowback, the fluids and sand content will be monitored. When the produced fluids contain minimal sand, the wells will be turned to production facilities. Gas sales should start as soon as the wells start flowing through the production facilities, unless there are operational issues on <u>DCP</u> system at that time. Based on current information, it is <u>Devon's</u> belief the system can take this gas upon completion of the well(s).

Safety requirements during cleanout operations from the use of underbalanced air cleanout systems may necessitate that sand and non-pipeline quality gas be vented and/or flared rather than sold on a temporary basis.

#### Alternatives to Reduce Flaring

Below are alternatives considered from a conceptual standpoint to reduce the amount of gas flared.

# Received by OCD: 5/14/2021 1:55:31 PM Power Generation – On lease

.

• Only a portion of gas is consumed operating the generator, remainder of gas will be flared

Compressed Natural Gas – On lease

- Gas flared would be minimal, but might be uneconomical to operate when gas volume declines
- NGL Removal On lease
  - o Plants are expensive, residue gas is still flared, and uneconomical to operate when gas volume declines

#### Reference Table:

DCP Plant locations Artesia Sec. 7, T18S, R28E, Eunice Sec. 5, T21S, R36E Linam Sec. 6, T19S, R37E Zia II Sec. 19, T19S, R32E

## 1. Geologic Formations

TVD of target	8914	Pilot hole depth	N/A
MD at TD:	16862	Deepest expected fresh water	

Basin

Dasm			
	Depth	Water/Mineral	
Formation	(TVD)	Bearing/Target	Hazards*
	from KB	Zone?	
Rustler	358		
Salt	593		
Base of Salt	3093		
Lamar	3093		
Delaware	3328		
Cherry Canyon	4188		
Brushy Canyon	5768		
1st Bone Spring Lime	7008		
Bone Spring 1st	8043		
Bone Spring 2nd	8718		

\*H2S, water flows, loss of circulation, abnormal pressures, etc.

		Wt			Casing	Interval	Casing Interval	
Hole Size	Csg. Size	(PPF)	Grade	Conn	From (MD)	To (MD)	From (TVD)	To (TVD)
17 1/2	13 3/8	48	H40	BTC	0	383	0	383
12 1/4	9 5/8	40	J-55	BTC	0	3193	0	3193
8 3/4	5 1/2	17	P110	BTC	0	16862	0	8914

#### 2. Casing Program

• All casing strings will be tested in accordance with Onshore Oil and Gas Order #2 IILB.1.h Must have table for continengcy casing.

#### FULLY LOADED 12-1 FED COM 231H

Casing	# Sks	тос	Wt. (lb/gal)	Yld (ft3/sack)	Slurry Description
Surface	316	Surf	13.2	1.4	Lead: Class C Cement + additives
Int 1	332	Surf	9.0	3.3	Lead: Class C Cement + additives
Int I	154 500' above shoe 13.2		1.4	Tail: Class H / C + additives	
Int 1	As Needed	Surf	9.0	3.3	Squeeze Lead: Class C Cement + additives
Intermediate	332	Surf	9.0	3.3	Lead: Class C Cement + additives
Squeeze	154	500' above shoe	13.2	1.4	Tail: Class H / C + additives
Production	511	500' tieback	9.0	3.3	Lead: Class H /C + additives
roudenon	1576	KOP	13.2	1.4	Tail: Class H / C + additives

## 3. Cementing Program (3-String Primary Design)

If a DV tool is ran the depth(s) will be adjusted based on hole conditions and cement volumes will be adjusted proportionally. Slurry weights will be adjusted based on estimated fracture gradient of the formation. DV tool will be set a minimum of 50 feet below previous casing and a minimum of 200 feet above current shoe. If cement is not returned to surface during the primary cement job on the surface casing string, a planned top job will be conducted immediately after completion of the primary job.

Casing String	% Excess
Surface	50%
Intermediate	30%
Production	10%

.

BOP installed and tested before drilling which hole?	Size?	Min. Required WP	Туре		✓	Tested to:												
			An	Annular		50% of rated working pressure												
Int 1	13-58"	5M	Blind	d Ram	Х													
IIII I	15-58	5101	Pipe	e Ram		5M												
			Doub	le Ram	Х	5101												
			Other*															
			Annular		Х	50% of rated working pressure												
Production	13-5/8"	5M	5M	5M	5M	5M	Blind	d Ram	Х									
Floduction							5111	JIVI	JIVI	JIVI	JIVI	JIVI	JIVI	JIVI	JIVI	JIVI	JIVI	5101
				Doub	le Ram	Х	5101											
			Other*															
			Annul	ar (5M)														
			Blind Ram															
			Pipe Ram															
			Double Ram															
			Other*															

#### 4. Pressure Control Equipment (Three String Design)

### 5. Mud Program (Three String Design)

Section	Туре	Weight (ppg)		
Surface	FW Gel	8.5-9		
Intermediate	Brine	10-10.5		
Production	WBM	8.5-9		

Sufficient mud materials to maintain mud properties and meet minimum lost circulation and weight increase requirements will be kept on location at all times.

What will be used to monitor the loss or gain of fluid?	PVT/Pason/Visual Monitoring
---	-----------------------------

#### 6. Logging and Testing Procedures

Logging, C	oring and Testing
	Will run GR/CNL from TD to surface (horizontal well - vertical portion of hole). Stated logs run will be in the
Х	Completion Report and sbumitted to the BLM.
	No logs are planned based on well control or offset log information.
	Drill stem test? If yes, explain.
	Coring? If yes, explain.

Additional	logs planned	Interval
	Resistivity	
	Density	
Х	CBL	Production casing
Х	Mud log	KOP to TD
	PEX	

#### 7. Drilling Conditions

Condition	Specfiy what type and where?
BH pressure at deepest TVD	4172
Abnormal temperature	No

Mitigation measure for abnormal conditions. Describe. Lost circulation material/sweeps/mud scavengers.

Hydrogren Sulfide (H2S) monitors will be installed prior to drilling out the surface shoe. If H2S is detected in concentrations greater than 100 ppm, the operator will comply with the provisions of Onshore Oil and Gas Order #6. If Hydrogen Sulfide is encountered measured values and formations will be provided to the BLM.

N	H2S is present
Y	H2S plan attached.

### 8. Other facets of operation

Is this a walking operation? Potentially

- 1 If operator elects, drilling rig will batch drill the surface holes and run/cement surface casing; walking the rig to next wells on the pad.
- 2 The drilling rig will then batch drill the intermediate sections and run/cement intermediate casing; the wellbore will be isolated with a blind flange and pressure gauge installed for monitoring the well before walking to the next well.
- 3 The drilling rig will then batch drill the production hole sections on the wells with OBM, run/cement production casing, and install TA caps or tubing heads for completions.

NOTE: During batch operations the drilling rig will be moved from well to well however, it will not be removed from the pad until all wells have production casing run/cemented.

Will be pre-setting casing? Potentially

- 1 Spudder rig will move in and batch drill surface hole.
  - a. Rig will utilize fresh water based mud to drill surface hole to TD. Solids control will be handled entirely on a closed loop basis.
- 2 After drilling the surface hole section, the spudder rig will run casing and cement following all of the applicable rules and regulations (OnShore Order 2, all COAs and NMOCD regulations).

 $^{3}$  The wellhead will be installed and tested once the surface casing is cut off and the WOC time has been reached.

- 4 A blind flange with the same pressure rating as the wellhead will be installed to seal the wellbore. Pressure will be monitored with a pressure gauge installed on the wellhead.
- 5 Spudder rig operations is expected to take 4-5 days per well on a multi-well pad.
- 6 The NMOCD will be contacted and notified 24 hours prior to commencing spudder rig operations.
- 7 Drilling operations will be performed with drilling rig. At that time an approved BOP stack will be nippled up and tested on the wellhead before drilling operations commences on each well.
  - a. The NMOCD will be contacted / notified 24 hours before the drilling rig moves back on to the pad with the pre-set surface casing.

#### Attachments

X Directional Plan Other, describe





Commitment Runs Deep



Design Plan Operation and Maintenance Plan Closure Plan

SENM - Closed Loop Systems June 2010

## I. Design Plan

Devon uses MI SWACO closed loop system (CLS). The MI SWACO CLS is designed to maintain drill solids at or below 5%. The equipment is arranged to progressively remove solids from the largest to the smallest size. Drilling fluids can thus be reused and savings is realized on mud and disposal costs. Dewatering may be required with the centrifuges to insure removal of ultra fine solids.

The drilling location is constructed to allow storm water to flow to a central sump normally the cellar. This insures no contamination leaves the drilling pad in the event of a spill. Storm water is reused in the mud system or stored in a reserve fluid tank farm until it can be reused. All lubricants, oils, or chemicals are removed immediately from the ground to prevent the contamination of storm water. An oil trap is normally installed on the sump if an oil spill occurs during a storm.

A tank farm is utilized to store drilling fluids including fresh water and brine fluids. The tank farm is constructed on a 20 ml plastic lined, bermed pad to prevent the contamination of the drilling site during a spill. Fluids from other sites may be stored in these tanks for processing by the solids control equipment and reused in the mud system. At the end of the well the fluids are transported from the tank farm to an adjoining well or to the next well for the rig.

Prior to installing a closed-loop system on site, the topsoil, if present, will be stripped and stockpiled for use as the final cover or fill at the time of closure.

Signs will be posted on the fence surrounding the closed-loop system unless the closed-loop system is located on a site where there is an existing well, that is operated by Devon.

## II. Operations and Maintenance Plan

*Primary Shakers*: The primary shakers make the first removal of drill solids from the drilling mud as it leaves the well bore. The shakers are sized to handle maximum drilling rate at optimal screen size. The shakers normally remove solids down to 74 microns.

*Mud Cleaner:* The Mud Cleaner cleans the fluid after it leaves the shakers. A set of hydrocyclones are sized to handle 1.25 to 1.5 times the maximum circulating rate. This ensures all the fluid is being processed to an average cut point of 25 microns. The wet discharged is dewatered on a shaker equipped with ultra fine mesh screens and generally cut at 40 microns.



*Centrifuges*: The centrifuges can be one or two in number depending on the well geometry or depth of well. The centrifuges are sized to maintain low gravity solids at 5% or below. They may or may not need a dewatering system to enhance the removal rates. The centrifuges can make a cut point of 8-10 microns depending on bowl speed, feed rate, solids loading and other factors.

The centrifuge system is designed to work on the active system and be flexible to process incoming fluids from other locations. This set-up is also dependent on well factors.

*Dewatering System:* The dewatering system is a chemical mixing and dosing system designed to enhance the solids removal of the centrifuge. Not commonly used in shallow wells. It may contain pH adjustment, coagulant mixing and dosing, and polymer mixing and dosing. Chemical flocculation binds ultra fine solids into a mass that is within the centrifuge operating design. The

dewatering system improves the centrifuge cut point to infinity or allows for the return of clear water or brine fluid. This ability allows for the ultimate control of low gravity solids.

*Cuttings Boxes:* Cuttings boxes are utilized to capture drill solids that are discarded from the solids control equipment. These boxes are set upon a rail system that allows for the removal and replacement of a full box of cuttings with an empty one. They are equipped with a cover that insures no product is spilled into the environment during the transportation phase.

*Process Tank:* (Optional) The process tank allows for the holding and process of fluids that are being transferred into the mud system. Additionally, during times of lost circulation the process tank may hold active fluids that are removed for additional treatment. It can further be used as a mixing tank during well control conditions.

Sump and Sump Pump: The sump is used to collect storm water and the pump is used to transfer this fluid to the active system or to the tank for to hold in reserve. It can also be used to collect fluids that may escape during spills. The location contains drainage ditches that allow the location fluids to drain to the sump.

*Reserve Fluids (Tank Farm):* A series of frac tanks are used to replace the reserve pit. These are steel tanks that are equipped with a manifold system and a transfer pump. These tanks can contain any number of fluids used during the drilling process. These can include fresh water, cut brine, and saturated salt fluid. The fluid can be from the active well or reclaimed fluid from other locations. A 20 ml liner and berm system is employed to ensure the fluids do not migrate to the environment during a spill.

If a leak develops, the appropriate division district office will be notified within 48 hours of the discovery and the leak will be addressed. Spill prevention is accomplished by maintaining pump packing, hoses, and pipe fittings to insure no leaks are occurring. During an upset condition the source of the spill is isolated and repaired as soon as it is discovered. Free liquid is removed by a diaphragm pump and returned to the mud system. Loose topsoil may be used to stabilize the spill and the contaminated soil is excavated and placed in the cuttings boxes. After the well is finished and the rig has moved, the entire location is scrapped and testing will be performed to determine if a release has occurred.


All trash is kept in a wire mesh enclosure and removed to an approved landfill when full. All spent motor oils are kept in separate containers and they are removed and sent to an approved recycling center. Any spilled lubricants, pipe dope, or regulated chemicals are removed from soil and sent to landfills approved for these products.

These operations are monitored by Mi Swaco service technicians. Daily logs are maintained to ensure optimal equipment operation and maintenance. Screen and chemical use is logged to maintain inventory control. Fluid properties are monitored and recorded and drilling mud volumes are accounted for in the mud storage farm. This data is kept for end of well review to insure performance goals are met. Lessons learned are logged and used to help with continuous improvement.

A MI SWACO field supervisor manages from 3-5 wells. They are responsible for training personnel, supervising installations, and inspecting sites for compliance of MI SWACO safety and operational policy.

## III. Closure Plan

A maximum 340' X 340' caliche pad is built per well. All of the trucks and steel tanks fit on this pad. All fluid cuttings go to the steel tanks to be hauled by various trucking companies to an agency approved disposal.



evon		Eddy Permit Plan		OCOM 231H		Geodetic System: US State Plane 1983 Datum: North American Datum 1927 Ellipsoid: Clarke 1866			
		Design:	Permit Plan	#1					Zone: 3001 - NM East (NAD83)
	MD	INC	AZI	TVD	NS	EW	VS	DLS	Comment
•	(ft) 0.00	(°) 0.00	(°) 0.00	(ft) 0.00	(ft) 0.00	(ft) 0.00	(ft) 0.00	(°/100ft) 0.00	SHL
	100.00	0.00	227.00	100.00	0.00	0.00	0.00	0.00	
	200.00	0.00	227.00	200.00	0.00	0.00	0.00	0.00	
	300.00	0.00	227.00	300.00	0.00	0.00	0.00	0.00	
	358.00	0.00	227.00	358.00	0.00	0.00	0.00	0.00	Rustler
	400.00 500.00	0.00 0.00	227.00 227.00	400.00	0.00	0.00 0.00	0.00 0.00	0.00 0.00	
	593.00	0.00	227.00	500.00 593.00	0.00 0.00	0.00	0.00	0.00	Salt
	600.00	0.00	227.00	600.00	0.00	0.00	0.00	0.00	Sat
	700.00	0.00	227.00	700.00	0.00	0.00	0.00	0.00	
	800.00	0.00	227.00	800.00	0.00	0.00	0.00	0.00	
	900.00	0.00	227.00	900.00	0.00	0.00	0.00	0.00	
	1000.00	0.00	227.00	1000.00	0.00	0.00	0.00	0.00	
	1100.00	0.00	227.00	1100.00	0.00	0.00	0.00	0.00	
	1200.00	0.00	227.00	1200.00	0.00	0.00	0.00	0.00	
	1300.00	0.00	227.00	1300.00	0.00	0.00	0.00	0.00	
	1400.00 1500.00	0.00 0.00	227.00 227.00	1400.00 1500.00	0.00 0.00	0.00 0.00	0.00 0.00	0.00 0.00	
	1600.00	0.00	227.00	1600.00	0.00	0.00	0.00	0.00	
	1700.00	0.00	227.00	1700.00	0.00	0.00	0.00	0.00	
	1800.00	0.00	227.00	1800.00	0.00	0.00	0.00	0.00	
	1900.00	0.00	227.00	1900.00	0.00	0.00	0.00	0.00	
	2000.00	0.00	227.00	2000.00	0.00	0.00	0.00	0.00	Start Tangent
	2100.00	3.00	227.00	2099.95	-1.79	-1.91	-1.44	3.00	
	2200.00	6.00	227.00	2199.63	-7.14	-7.65	-5.77	3.00	
	2300.00	9.00	227.00	2298.77	-16.04	-17.20	-12.98	3.00	
	2400.00 2500.00	12.00 15.00	227.00 227.00	2397.08 2494.31	-28.46 -44.38	-30.52 -47.59	-23.04 -35.92	3.00 1.00	Hold Tangent
	2600.00	15.00	227.00	2590.90	-62.03	-66.52	-50.21	0.00	riola rangent
	2700.00	15.00	227.00	2687.49	-79.69	-85.45	-64.49	0.00	
	2800.00	15.00	227.00	2784.09	-97.34	-104.38	-78.78	0.00	
	2900.00	15.00	227.00	2880.68	-114.99	-123.31	-93.06	0.00	
	3000.00	15.00	227.00	2977.27	-132.64	-142.24	-107.35	0.00	
	3100.00	15.00	227.00	3073.86	-150.29	-161.17	-121.63	0.00	
	3119.81	15.00	227.00	3093.00	-153.79	-164.92	-124.46	0.00	Base of Salt, Lamar
	3200.00	15.00	227.00	3170.46	-167.94	-180.10	-135.92	0.00	
	3300.00	15.00	227.00	3267.05	-185.59	-199.02	-150.21	0.00	Delawara
	3363.10 3400.00	15.00 15.00	227.00 227.00	3328.00 3363.64	-196.73 -203.25	-210.97 -217.95	-159.22 -164.49	0.00 0.00	Delaware
	3500.00	15.00	227.00	3460.23	-2203.25	-236.88	-178.78	0.00	
	3600.00	15.00	227.00	3556.83	-238.55	-255.81	-193.06	0.00	
	3700.00	15.00	227.00	3653.42	-256.20	-274.74	-207.35	0.00	
	3800.00	15.00	227.00	3750.01	-273.85	-293.67	-221.64	0.00	
	3900.00	15.00	227.00	3846.60	-291.50	-312.60	-235.92	0.00	
	4000.00	15.00	227.00	3943.20	-309.15	-331.53	-250.21	0.00	
	4100.00	15.00	227.00	4039.79	-326.81	-350.45	-264.49	0.00	
	4200.00	15.00	227.00	4136.38	-344.46	-369.38	-278.78	0.00	Charge Conver
	4253.44 4300.00	15.00 15.00	227.00 227.00	4188.00 4232.97	-353.89 -362.11	-379.50 -388.31	-286.41 -293.06	0.00 0.00	Cherry Canyon
	4300.00 4400.00	15.00 15.00	227.00 227.00	4232.97 4329.57	-362.11 -379.76	-388.31 -407.24	-293.06 -307.35	0.00	
	4500.00	15.00	227.00	4329.37 4426.16	-379.76	-407.24	-307.55	0.00	
	4600.00	15.00	227.00	4522.75	-415.06	-445.10	-335.92	0.00	
	4700.00	15.00	227.00	4619.34	-432.71	-464.03	-350.21	0.00	
	4800.00	15.00	227.00	4715.94	-450.37	-482.96	-364.49	0.00	
	4900.00	15.00	227.00	4812.53	-468.02	-501.88	-378.78	0.00	
	5000.00	15.00	227.00	4909.12	-485.67	-520.81	-393.06	0.00	
	5100.00	15.00	227.00	5005.72	-503.32	-539.74	-407.35	0.00	
	5200.00	15.00	227.00	5102.31	-520.97	-558.67	-421.64	0.00	
	5300.00 5400.00	15.00	227.00	5198.90	-538.62	-577.60	-435.92	0.00	
	5400.00 5500.00	15.00 15.00	227.00 227.00	5295.49 5392.09	-556.27 -573.93	-596.53 -615.46	-450.21 -464.49	0.00 0.00	
	5600.00	15.00	227.00	5488.68	-575.95	-615.46	-404.49 -478.78	0.00	
	5700.00	15.00	227.00	5585.27	-609.23	-653.31	-493.07	0.00	
	5800.00	15.00	227.00	5681.86	-626.88	-672.24	-507.35	0.00	
	5889.18	15.00	227.00	5768.00	-642.62	-689.12	-520.09	0.00	Brushy Canyon
	5900.00	15.00	227.00	5778.46	-644.53	-691.17	-521.64	0.00	-
	6000.00	15.00	227.00	5875.05	-662.18	-710.10	-535.92	0.00	
	6100.00	15.00	227.00	5971.64	-679.84	-729.03	-550.21	0.00	
	6200.00	15.00	227.00	6068.23	-697.49	-747.96	-564.49	0.00	
	6300.00	15.00	227.00	6164.83	-715.14	-766.89	-578.78	0.00	

•

levon		County: Wellbore:			O COM 231H		Geodetic System: US State Plane 1983 Datum: North American Datum 1927 Ellipsoid: Clarke 1866 Zone: 3001 - NM East (NAD83)				
	MD	INC	AZI	TVD	NS	EW	vs	DLS	Comment		
-	(ft) 6400.00	(°) 15.00	(°) 227.00	(ft) 6261.42	(ft) -732.79	(ft) -785.82	(ft) -593.07	(°/100ft) 0.00			
	6500.00	15.00	227.00	6358.01	-750.44	-804.74	-607.35	0.00			
	6600.00	15.00	227.00	6454.60	-768.09	-823.67	-621.64	0.00			
	6700.00	15.00	227.00	6551.20	-785.74	-842.60	-635.92	0.00			
	6800.00	15.00	227.00	6647.79	-803.40	-861.53	-650.21	0.00			
	6900.00 7000.00	15.00 15.00	227.00 227.00	6744.38 6840.97	-821.05 -838.70	-880.46 -899.39	-664.50 -678.78	0.00 0.00			
	7100.00	15.00	227.00	6937.57	-856.35	-918.32	-693.07	0.00			
	7172.92	15.00	227.00	7008.00	-869.22	-932.12	-703.48	0.00	1st Bone Spring Lime		
	7200.00	15.00	227.00	7034.16	-874.00	-937.25	-707.35	0.00			
	7300.00	15.00	227.00	7130.75	-891.65	-956.17	-721.64	0.00			
	7400.00 7500.00	15.00 15.00	227.00 227.00	7227.34 7323.94	-909.30 -926.96	-975.10 -994.03	-735.92 -750.21	0.00 0.00			
	7600.00	15.00	227.00	7420.53	-944.61	-1012.96	-764.50	0.00			
	7700.00	15.00	227.00	7517.12	-962.26	-1031.89	-778.78	0.00			
	7800.00	15.00	227.00	7613.72	-979.91	-1050.82	-793.07	0.00			
	7866.86	15.00	227.00	7678.30	-991.71	-1063.48	-802.62	0.00	Drop to Vertical		
	7900.00 8000.00	14.34 12.34	227.00 227.00	7710.36 7807.65	-997.43 -1013.16	-1069.62 -1086.49	-807.25 -819.98	2.00 2.00			
	8000.00 8100.00	12.34	227.00	7807.65	-1013.16	-1086.49	-819.98	2.00			
	8200.00	8.34	227.00	8004.37	-1020.07	-1112.73	-839.78	2.00			
	8239.01	7.56	227.00	8043.00	-1041.31	-1116.67	-842.76	2.00	Bone Spring 1st		
	8300.00	6.34	227.00	8103.54	-1046.34	-1122.07	-846.83	2.00			
	8400.00	4.34	227.00	8203.11	-1052.69	-1128.87	-851.97	2.00			
	8500.00 8600.00	2.34 0.34	227.00 227.00	8302.93 8402.90	-1056.66 -1058.25	-1133.13 -1134.83	-855.18 -856.47	2.00 2.00			
	8616.86	0.00	227.00	8419.76	-1058.28	-1134.87	-856.50	2.00	Hold Vertical		
	8692.27	0.00	0.00	8495.17	-1058.28	-1134.87	-856.50	0.00	КОР		
	8700.00	0.77	0.00	8502.90	-1058.23	-1134.87	-856.44	10.00			
	8800.00	10.77	0.00	8602.26	-1048.19	-1134.87	-846.54	10.00			
	8900.00 8921.14	20.77 22.89	0.00 0.00	8698.38 8718.00	-1021.04 -1013.18	-1134.87 -1134.87	-819.76 -812.01	10.00 10.00	Bone Spring 2nd / Point of Penetration		
	9000.00	30.77	0.00	8788.32	-977.61	-1134.87	-776.93	10.00	bone spining zind / i oint of renetration		
	9100.00	40.77	0.00	8869.35	-919.23	-1134.87	-719.35	10.00			
	9200.00	50.77	0.00	8939.01	-847.66	-1134.87	-648.76	10.00			
	9300.00	60.77	0.00	8995.19	-765.09	-1134.87	-567.32	10.00			
	9400.00 9500.00	70.77 80.77	0.00 0.00	9036.17 9060.72	-674.01 -577.20	-1134.87 -1134.87	-477.49 -382.01	10.00 10.00			
	9600.00	90.77	0.00	9068.08	-477.60	-1134.87	-283.77	10.00			
	9604.43	91.22	0.00	9068.00	-473.17	-1134.87	-279.41	10.00	Landing Point		
	9700.00	91.22	0.00	9065.97	-377.62	-1134.87	-185.16	0.00			
	9800.00	91.22	0.00	9063.85	-277.64	-1134.87	-86.56	0.00			
	9900.00 10000.00	91.22 91.22	0.00 0.00	9061.73 9059.61	-177.67 -77.69	-1134.87 -1134.87	12.05 110.66	0.00 0.00			
	10100.00	91.22	0.00	9059.01	22.29	-1134.87	209.26	0.00			
	10200.00	91.22	0.00	9055.36	122.27	-1134.87	307.87	0.00			
	10300.00	91.22	0.00	9053.24	222.24	-1134.87	406.48	0.00			
	10400.00	91.22	0.00	9051.12	322.22	-1134.87	505.08	0.00			
	10500.00	91.22 01.22	0.00	9049.00	422.20	-1134.87	603.69	0.00			
	10600.00 10700.00	91.22 91.22	0.00 0.00	9046.88 9044.75	522.18 622.15	-1134.87 -1134.87	702.30 800.90	0.00 0.00			
	10800.00	91.22	0.00	9042.63	722.13	-1134.87	899.51	0.00			
	10900.00	91.22	0.00	9040.51	822.11	-1134.87	998.12	0.00			
	11000.00	91.22	0.00	9038.39	922.09	-1134.87	1096.72	0.00			
	11100.00	91.22	0.00	9036.27	1022.06	-1134.87	1195.33	0.00			
	11200.00 11300.00	91.22 91.22	0.00 0.00	9034.15 9032.02	1122.04 1222.02	-1134.87 -1134.87	1293.94 1392.54	0.00 0.00			
	11400.00	91.22	0.00	9032.02	1322.02	-1134.87	1392.54	0.00			
	11500.00	91.22	0.00	9027.78	1421.97	-1134.87	1589.76	0.00			
	11600.00	91.22	0.00	9025.66	1521.95	-1134.87	1688.36	0.00			
	11700.00	91.22	0.00	9023.54	1621.93	-1134.87	1786.97	0.00			
	11800.00	91.22 01.22	0.00	9021.42	1721.91	-1134.87	1885.58	0.00			
	11900.00 12000.00	91.22 91.22	0.00 0.00	9019.29 9017.17	1821.88 1921.86	-1134.87 -1134.87	1984.18 2082.79	0.00 0.00			
	12000.00	91.22	0.00	9017.17	2021.86	-1134.87	2082.79	0.00			
	12200.00	91.22	0.00	9012.93	2121.82	-1134.87	2280.01	0.00			
	12300.00	91.22	0.00	9010.81	2221.79	-1134.87	2378.61	0.00			
	12400.00	91.22	0.00	9008.68	2321.77 2421.75	-1134.87 -1134.87	2477.22 2575.83	0.00 0.00			
	12500.00	91.22	0.00	9006.56							

•

von		County: Wellbore:	Eddy		0.000123111				Geodetic System: US State Plane 1983 Datum: North American Datum 1927 Ellipsoid: Clarke 1866 Zone: 3001 - NM East (NAD83)		
	MD	INC	AZI	TVD	NS	EW	vs	DLS	<b>6</b>		
	(ft)	(°)	(°)	(ft)	(ft)	(ft)	(ft)	(°/100ft)	Comment		
	12700.00	91.22	0.00	9002.32	2621.70	-1134.87	2773.04	0.00			
	12800.00	91.22	0.00	9000.20	2721.68	-1134.87	2871.65	0.00			
	12900.00	91.22	0.00	8998.08	2821.66	-1134.87	2970.25	0.00			
	13000.00	91.22	0.00	8995.95	2921.64	-1134.87	3068.86	0.00			
	13100.00	91.22	0.00	8993.83	3021.61	-1134.87	3167.47	0.00			
	13200.00	91.22	0.00	8991.71	3121.59	-1134.87	3266.07	0.00			
	13300.00	91.22	0.00	8989.59	3221.57	-1134.87	3364.68	0.00			
	13400.00	91.22	0.00	8987.47	3321.55	-1134.87	3463.29	0.00			
	13500.00	91.22	0.00	8985.35	3421.52	-1134.87	3561.89	0.00			
	13600.00	91.22	0.00	8983.22	3521.50	-1134.87	3660.50	0.00			
	13700.00	91.22	0.00	8981.10	3621.48	-1134.87	3759.11	0.00			
	13800.00	91.22	0.00	8978.98	3721.46	-1134.87	3857.71	0.00			
	13900.00	91.22	0.00	8976.86	3821.43	-1134.87	3956.32	0.00			
	14000.00	91.22	0.00	8974.74	3921.41	-1134.87	4054.93	0.00			
	14100.00	91.22	0.00	8972.61	4021.39	-1134.87	4153.53	0.00			
	14200.00	91.22	0.00	8970.49	4121.37	-1134.87	4252.14	0.00			
	14300.00	91.22	0.00	8968.37	4221.34	-1134.87	4350.75	0.00			
	14400.00	91.22	0.00	8966.25	4321.32	-1134.87	4449.35	0.00			
	14500.00	91.22	0.00	8964.13	4421.30	-1134.87	4547.96	0.00			
	14600.00	91.22	0.00	8962.01	4521.28	-1134.87	4646.57	0.00			
	14700.00	91.22	0.00	8959.88	4621.25	-1134.87	4745.17	0.00			
	14800.00	91.22	0.00	8957.76	4721.23	-1134.87	4843.78	0.00			
	14900.00	91.22	0.00	8955.64	4821.21	-1134.87	4942.39	0.00			
	15000.00	91.22	0.00	8953.52	4921.19	-1134.87	5041.00	0.00			
	15100.00	91.22	0.00	8951.40	5021.16	-1134.87	5139.60	0.00			
	15200.00	91.22	0.00	8949.28	5121.14	-1134.87	5238.21	0.00			
	15300.00	91.22	0.00	8947.15	5221.12	-1134.87	5336.82	0.00			
	15400.00	91.22	0.00	8945.03	5321.10	-1134.87	5435.42	0.00			
	15500.00	91.22	0.00	8942.91	5421.07	-1134.87	5534.03	0.00			
	15600.00	91.22	0.00	8940.79	5521.05	-1134.87	5632.64	0.00			
	15700.00	91.22	0.00	8938.67	5621.03	-1134.87	5731.24	0.00			
	15800.00	91.22	0.00	8936.54	5721.01	-1134.87	5829.85	0.00			
	15900.00	91.22	0.00	8934.42	5820.98	-1134.87	5928.46	0.00			
	16000.00	91.22	0.00	8932.30	5920.96	-1134.87	6027.06	0.00			
	16100.00	91.22	0.00	8930.18	6020.94	-1134.87	6125.67	0.00			
	16200.00	91.22	0.00	8928.06	6120.92	-1134.87	6224.28	0.00			
	16300.00	91.22	0.00	8925.94	6220.89	-1134.87	6322.88	0.00			
	16400.00	91.22	0.00	8923.81	6320.87	-1134.87	6421.49	0.00			
	16500.00	91.22	0.00	8921.69	6420.85	-1134.87	6520.10	0.00			
	16600.00	91.22	0.00	8919.57	6520.83	-1134.87	6618.70	0.00			
	16700.00	91.22	0.00	8917.45	6620.80	-1134.87	6717.31	0.00	<b>F</b> 11		
	16782.08	91.22	0.00	8915.71	6702.87	-1134.87	6798.25	0.00	Exit		
	16800.00 16862.08	91.22 91.22	0.00 0.00	8915.33 8914.00	6720.78 6782.85	-1134.87 -1134.87	6815.92 6877.13	0.00 0.00	BHL		

•

devon		County: Wellbore:	Eddy		COM 231H				Geodetic System: US State Plane 1983 Datum: North American Datum 1927 Ellipsoid: Clarke 1866 Zone: 3001 - NM East (NAD83)
_	MD (ft)	<b>INC</b> (°)	<b>AZI</b> (°)	TVD (ft)	NS (ft)	EW (ft)	<b>VS</b> (ft)	<b>DLS</b> (°/100ft)	Comment

.

## PECOS DISTRICT DRILLING CONDITIONS OF APPROVAL

<b>OPERATOR'S NAME:</b>	Devon Energy Production Company LP
LEASE NO.:	NMNM105213
LOCATION:	Section 12, T.24 S., R.29 E., NMPM
COUNTY:	Eddy County, New Mexico
WELL NAME & NO.:	Fully Loaded 12-1 Fed Com 231H
SURFACE HOLE FOOTAGE:	1516'/N & 1405'/W
<b>BOTTOM HOLE FOOTAGE</b>	20'/N & 330'/W
WELL NAME & NO.:	Fully Loaded 12-1 Fed Com 232H
SURFACE HOLE FOOTAGE:	1516'/N & 1435'/W
<b>BOTTOM HOLE FOOTAGE</b>	20'/N & 1320'/W
	-
WELL NAME & NO.:	Fully Loaded 12-1 Fed Com 233H
SURFACE HOLE FOOTAGE:	1516'/N & 1465'/W
<b>BOTTOM HOLE FOOTAGE</b>	20'/N & 2310'/W
WELL NAME & NO.:	Fully Loaded 12-13 Fed Com 231H
SURFACE HOLE FOOTAGE:	2397'/N & 982'/W
<b>BOTTOM HOLE FOOTAGE</b>	20'/S & 330'/W
WELL NAME & NO.:	Fully Loaded 12-13 Fed Com 232H
SURFACE HOLE FOOTAGE:	2397'/N & 1012'/W
<b>BOTTOM HOLE FOOTAGE</b>	20'/S & 1320'/W
WELL NAME & NO.:	Fully Loaded 12-13 Fed Com 233H
SURFACE HOLE FOOTAGE:	2397'/N & 1042'/W
<b>BOTTOM HOLE FOOTAGE</b>	20'/S & 2310'/W

## COA

H2S	C Yes	🖸 No	
Potash	🖸 None	Secretary	<b>C</b> R-111-P
Cave/Karst Potential	🖸 Low	C Medium	🕻 High
Cave/Karst Potential	Critical		
Variance	C None	🖸 Flex Hose	C Other
Wellhead	Conventional	🖸 Multibowl	C Both
Other	□4 String Area	Capitan Reef	□ WIPP
Other	Fluid Filled	Cement Squeeze	Pilot Hole
Special Requirements	Water Disposal	COM	🗖 Unit

**Approval Date: 03/23/2021** 

## A. HYDROGEN SULFIDE

Hydrogen Sulfide (H2S) monitors shall be installed prior to drilling out the surface shoe. If H2S is detected in concentrations greater than 100 ppm, the Hydrogen Sulfide area shall meet Onshore Order 6 requirements, which includes equipment and personnel/public protection items. If Hydrogen Sulfide is encountered, provide measured values and formations to the BLM.

## **B.** CASING

- 1. The **13-3/8** inch surface casing shall be set at approximately **383 feet** (a minimum of **70 feet (Eddy County)** into the Rustler Anhydrite and above the salt) and cemented to the surface.
  - a. If cement does not circulate to the surface, the appropriate BLM office shall be notified and a temperature survey utilizing an electronic type temperature survey with surface log readout will be used or a cement bond log shall be run to verify the top of the cement. Temperature survey will be run a minimum of six hours after pumping cement and ideally between 8-10 hours after completing the cement job.
  - b. Wait on cement (WOC) time for a primary cement job will be a minimum of <u>8</u> <u>hours</u> or 500 pounds compressive strength, whichever is greater. (This is to include the lead cement)
  - c. Wait on cement (WOC) time for a remedial job will be a minimum of 4 hours after bringing cement to surface or 500 pounds compressive strength, whichever is greater.
  - d. If cement falls back, remedial cementing will be done prior to drilling out that string.
- 2. The minimum required fill of cement behind the **9-5/8** inch intermediate casing shall be set at approximately **3193 feet** is:
  - Cement to surface. If cement does not circulate see B.1.a, c-d above.

# Operator has proposed to pump down 13-3/8" X 9-5/8" annulus. <u>Operator must run</u> a CBL from TD of the 9-5/8" casing to surface. Submit results to BLM.

- 3. The minimum required fill of cement behind the 5-1/2 inch production casing is:
  - Cement should tie-back at least 200 feet into previous casing string. Operator shall provide method of verification.
     Cement excess is less than 25%, more cement might be required.

## C. PRESSURE CONTROL

- 1. Variance approved to use flex line from BOP to choke manifold. Manufacturer's specification to be readily available. No external damage to flex line. Flex line to be installed as straight as possible (no hard bends).'
- 2. Operator has proposed a multi-bowl wellhead assembly. This assembly will only be tested when installed on the surface casing. Minimum working pressure of the blowout preventer (BOP) and related equipment (BOPE) required for drilling below the surface casing shoe shall be **5000 (5M)** psi.
  - a. Wellhead shall be installed by manufacturer's representatives, submit documentation with subsequent sundry.
  - b. If the welding is performed by a third party, the manufacturer's representative shall monitor the temperature to verify that it does not exceed the maximum temperature of the seal.
  - c. Manufacturer representative shall install the test plug for the initial BOP test.
  - d. If the cement does not circulate and one inch operations would have been possible with a standard wellhead, the well head shall be cut off, cementing operations performed and another wellhead installed.
  - e. Whenever any seal subject to test pressure is broken, all the tests in OOGO2.III.A.2.i must be followed.

## D. SPECIAL REQUIREMENT (S)

## **Communitization Agreement**

- The operator will submit a Communitization Agreement to the Santa Fe Office, 301 Dinosaur Trail Santa Fe, New Mexico 87508, at least 90 days before the anticipated date of first production from a well subject to a spacing order issued by the New Mexico Oil Conservation Division. The Communitization Agreement will include the signatures of all working interest owners in all Federal and Indian leases subject to the Communitization Agreement (i.e., operating rights owners and lessees of record), or certification that the operator has obtained the written signatures of all such owners and will make those signatures available to the BLM immediately upon request.
- If the operator does not comply with this condition of approval, the BLM may take enforcement actions that include, but are not limited to, those specified in 43 CFR 3163.1.
- In addition, the well sign shall include the surface and bottom hole lease numbers. <u>When the Communitization Agreement number is known, it shall also be on the sign.</u>

**Approval Date: 03/23/2021** 

## **GENERAL REQUIREMENTS**

The BLM is to be notified in advance for a representative to witness:

- a. Spudding well (minimum of 24 hours)
- b. Setting and/or Cementing of all casing strings (minimum of 4 hours)
- c. BOPE tests (minimum of 4 hours)
  - Eddy County Call the Carlsbad Field Office, 620 East Greene St., Carlsbad, NM 88220, (575) 361-2822
  - Lea County Call the Hobbs Field Station, 414 West Taylor, Hobbs NM 88240, (575) 393-3612
- 1. Unless the production casing has been run and cemented or the well has been properly plugged, the drilling rig shall not be removed from over the hole without prior approval.
  - a. In the event the operator has proposed to drill multiple wells utilizing a skid/walking rig. Operator shall secure the wellbore on the current well, after installing and testing the wellhead, by installing a blind flange of like pressure rating to the wellhead and a pressure gauge that can be monitored while drilling is performed on the other well(s).
  - b. When the operator proposes to set surface casing with Spudder Rig
    - Notify the BLM when moving in and removing the Spudder Rig.
    - Notify the BLM when moving in the 2<sup>nd</sup> Rig. Rig to be moved in within 90 days of notification that Spudder Rig has left the location.
    - BOP/BOPE test to be conducted per Onshore Oil and Gas Order No. 2 as soon as 2nd Rig is rigged up on well.
- 2. Floor controls are required for 3M or Greater systems. These controls will be on the rig floor, unobstructed, readily accessible to the driller and will be operational at all times during drilling and/or completion activities. Rig floor is defined as the area immediately around the rotary table; the area immediately above the substructure on which the draw works are located, this does not include the dog house or stairway area.
- 3. The record of the drilling rate along with the GR/N well log run from TD to surface (horizontal well vertical portion of hole) shall be submitted to the BLM office as well as all other logs run on the borehole 30 days from completion. If available, a digital copy of the logs is to be submitted in addition to the paper copies. The Rustler top and top and bottom of Salt are to be recorded on the Completion Report.

#### 021

## A. CASING

- 1. Changes to the approved APD casing program need prior approval if the items substituted are of lesser grade or different casing size or are Non-API. The Operator can exchange the components of the proposal with that of superior strength (i.e. changing from J-55 to N-80, or from 36# to 40#). Changes to the approved cement program need prior approval if the altered cement plan has less volume or strength or if the changes are substantial (i.e. Multistage tool, ECP, etc.). The initial wellhead installed on the well will remain on the well with spools used as needed.
- <u>Wait on cement (WOC) for Potash Areas:</u> After cementing but before commencing any tests, the casing string shall stand cemented under pressure until both of the following conditions have been met: 1) cement reaches a minimum compressive strength of 500 psi for all cement blends, 2) until cement has been in place at least <u>24</u> <u>hours</u>. WOC time will be recorded in the driller's log. The casing intergrity test can be done (prior to the cement setting up) immediately after bumping the plug.
- 3. <u>Wait on cement (WOC) for Water Basin:</u> After cementing but before commencing any tests, the casing string shall stand cemented under pressure until both of the following conditions have been met: 1) cement reaches a minimum compressive strength of 500 psi at the shoe, 2) until cement has been in place at least <u>8 hours</u>. WOC time will be recorded in the driller's log. See individual casing strings for details regarding lead cement slurry requirements. The casing intergrity test can be done (prior to the cement setting up) immediately after bumping the plug.
- 4. Provide compressive strengths including hours to reach required 500 pounds compressive strength prior to cementing each casing string. Have well specific cement details onsite prior to pumping the cement for each casing string.
- 5. No pea gravel permitted for remedial or fall back remedial without prior authorization from the BLM engineer.
- 6. On that portion of any well approved for a 5M BOPE system or greater, a pressure integrity test of each casing shoe shall be performed. Formation at the shoe shall be tested to a minimum of the mud weight equivalent anticipated to control the formation pressure to the next casing depth or at total depth of the well. This test shall be performed before drilling more than 20 feet of new hole.
- 7. If hardband drill pipe is rotated inside casing, returns will be monitored for metal. If metal is found in samples, drill pipe will be pulled and rubber protectors which have a larger diameter than the tool joints of the drill pipe will be installed prior to continuing drilling operations.
- 8. Whenever a casing string is cemented in the R-111-P potash area, the NMOCD requirements shall be followed.
- B. PRESSURE CONTROL

- 1. All blowout preventer (BOP) and related equipment (BOPE) shall comply with well control requirements as described in Onshore Oil and Gas Order No. 2 and API RP 53 Sec. 17.
- 2. If a variance is approved for a flexible hose to be installed from the BOP to the choke manifold, the following requirements apply: The flex line must meet the requirements of API 16C. Check condition of flexible line from BOP to choke manifold, replace if exterior is damaged or if line fails test. Line to be as straight as possible with no hard bends and is to be anchored according to Manufacturer's requirements. The flexible hose can be exchanged with a hose of equal size and equal or greater pressure rating. Anchor requirements, specification sheet and hydrostatic pressure test certification matching the hose in service, to be onsite for review. These documents shall be posted in the company man's trailer and on the rig floor.
- 3. 5M or higher system requires an HCR valve, remote kill line and annular to match. The remote kill line is to be installed prior to testing the system and tested to stack pressure.
- 4. If the operator has proposed a multi-bowl wellhead assembly in the APD. The following requirements must be met:
  - a. Wellhead shall be installed by manufacturer's representatives, submit documentation with subsequent sundry.
  - b. If the welding is performed by a third party, the manufacturer's representative shall monitor the temperature to verify that it does not exceed the maximum temperature of the seal.
  - c. Manufacturer representative shall install the test plug for the initial BOP test.
  - d. Whenever any seal subject to test pressure is broken, all the tests in OOGO2.III.A.2.i must be followed.
  - e. If the cement does not circulate and one inch operations would have been possible with a standard wellhead, the well head shall be cut off, cementing operations performed and another wellhead installed.
- 5. The appropriate BLM office shall be notified a minimum of 4 hours in advance for a representative to witness the tests.
  - a. In a water basin, for all casing strings utilizing slips, these are to be set as soon as the crew and rig are ready and any fallback cement remediation has been done. The casing cut-off and BOP installation can be initiated four hours after installing the slips, which will be approximately six hours after bumping the plug. For those casing strings not using slips, the minimum wait time before cut-off is eight hours after bumping the plug. BOP/BOPE testing can begin after cut-off or once cement reaches 500 psi compressive strength (including lead when specified), whichever is greater. However, if the float does not

hold, cut-off cannot be initiated until cement reaches 500 psi compressive strength (including lead when specified).

- b. In potash areas, for all casing strings utilizing slips, these are to be set as soon as the crew and rig are ready and any fallback cement remediation has been done. For all casing strings, casing cut-off and BOP installation can be initiated at twelve hours after bumping the plug. However, **no tests** shall commence until the cement has had a minimum of 24 hours setup time, except the casing pressure test can be initiated immediately after bumping the plug (only applies to single stage cement jobs).
- c. The tests shall be done by an independent service company utilizing a test plug not a cup or J-packer. The operator also has the option of utilizing an independent tester to test without a plug (i.e. against the casing) pursuant to Onshore Order 2 with the pressure not to exceed 70% of the burst rating for the casing. Any test against the casing must meet the WOC time for water basin (8 hours) or potash (24 hours) or 500 pounds compressive strength, whichever is greater, prior to initiating the test (see casing segment as lead cement may be critical item).
- d. The test shall be run on a 5000 psi chart for a 2-3M BOP/BOP, on a 10000 psi chart for a 5M BOP/BOPE and on a 15000 psi chart for a 10M BOP/BOPE. If a linear chart is used, it shall be a one hour chart. A circular chart shall have a maximum 2 hour clock. If a twelve hour or twenty-four hour chart is used, tester shall make a notation that it is run with a two hour clock.
- e. The results of the test shall be reported to the appropriate BLM office.
- f. All tests are required to be recorded on a calibrated test chart. A copy of the BOP/BOPE test chart and a copy of independent service company test will be submitted to the appropriate BLM office.
- g. The BOP/BOPE test shall include a low pressure test from 250 to 300 psi. The test will be held for a minimum of 10 minutes if test is done with a test plug and 30 minutes without a test plug. This test shall be performed prior to the test at full stack pressure.
- h. BOP/BOPE must be tested by an independent service company within 500 feet of the top of the Wolfcamp formation if the time between the setting of the intermediate casing and reaching this depth exceeds 20 days. This test does not exclude the test prior to drilling out the casing shoe as per Onshore Order No. 2.
- C. DRILLING MUD

**Approval Date: 03/23/2021** 

Mud system monitoring equipment, with derrick floor indicators and visual and audio alarms, shall be operating before drilling into the Wolfcamp formation, and shall be used until production casing is run and cemented.

## D. WASTE MATERIAL AND FLUIDS

All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of drilling operations and completion operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area.

Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.



Devon Energy Center 333 West Sheridan Avenue Oklahoma City, Oklahoma 73102-5015


# Hydrogen Sulfide (H<sub>2</sub>S) Contingency Plan

For

# Fully Loaded 12-1 Fed Com 231H

Sec-12 T-24S R-29E 1516' FNL & 1405' FWL LAT. = 32.235255' N (NAD83) LONG = 103.942074' W

**Eddy County NM** 



## Escape

Crews shall escape upwind of escaping gas in the event of an emergency release of gas. Escape can be facilitated from the location entrance road. Crews should then block the entrance to the location from the lease road so as not to allow anyone traversing into a hazardous area. The blockade should be at a safe distance outside of the ROE. <u>There are no homes or buildings in or near the ROE</u>.

## Assumed 100 ppm ROE = 3000'

## **100** ppm H<sub>2</sub>S concentration shall trigger activation of this plan.

## Emergency Procedures

In the event of a release of gas containing H<sub>2</sub>S, the first responder(s) must

- Isolate the area and prevent entry by other persons into the 100 ppm ROE.
- Evacuate any public places encompassed by the 100 ppm ROE.
- Be equipped with H<sub>2</sub>S monitors and air packs in order to control the release.
- Use the "buddy system" to ensure no injuries occur during the response
- Take precautions to avoid personal injury during this operation.
- Contact operator and/or local officials to aid in operation. See list of phone numbers attached.
- Have received training in the
  - $\circ$  Detection of H<sub>2</sub>S, and
  - Measures for protection against the gas,
  - Equipment used for protection and emergency response.

## Ignition of Gas Source

Should control of the well be considered lost and ignition considered, take care to protect against exposure to Sulfur Dioxide (SO<sub>2</sub>). Intentional ignition must be coordinated with the NMOCD and local officials. Additionally the NM State Police may become involved. NM State Police shall be the Incident Command on scene of any major release. Take care to protect downwind whenever there is an ignition of the gas

011414010110									
Common	Chemical	Specific	Specific Threshold		Lethal				
Name	Formula	Gravity	Limit	Hazardous Limit	Concentration				
Hydrogen Sulfide	H₂S	1.189 Air = 1	10 ppm	100 ppm/hr	600 ppm				
Sulfur	50-	2.21	2	N/A	1000				
Dioxide	SO2	Air = 1	2 ppm		1000 ppm				

## Characteristics of H<sub>2</sub>S and SO<sub>2</sub>

## **Contacting Authorities**

Devon Energy Corp. personnel must liaison with local and state agencies to ensure a proper response to a major release. Additionally, the OCD must be notified of the release as soon as possible but no later than 4 hours. Agencies will ask for information such as type and volume of release, wind direction, location of release, etc. Be prepared with all information available. The following call list of essential and potential responders has been prepared for use during a release. Devon Energy Corp. Company response must be in coordination with the State of New Mexico's 'Hazardous Materials Emergency Response Plan' (HMER)

## Hydrogen Sulfide Drilling Operation Plan

## I. HYDROGEN SULFIDE (H<sub>2</sub>S) TRAINING

All personnel, whether regularly assigned, contracted, or employed on an unscheduled basis, will receive training from a qualified instructor in the following areas prior to commencing drilling operations on this well:

- 1. The hazards and characteristics of hydrogen sulfide (H<sub>2</sub>S)
- 2. The proper use and maintenance of personal protective equipment and life support systems.
- 3. The proper use of H<sub>2</sub>S detectors, alarms, warning systems, briefing areas, evacuation procedures, and prevailing winds.
- 4. The proper techniques for first aid and rescue procedures.

In addition, supervisory personnel will be trained in the following areas:

- 1. The effects of H<sub>2</sub>S metal components. If high tensile tubulars are to be used, personnel will be trained in their special maintenance requirements.
- 2. Corrective action and shut-in procedures when drilling or reworking a well and blowout prevention and well control procedures.
- 3. The contents and requirements of the H<sub>2</sub>S Drilling Operations Plan and Public Protection Plan.

There will be an initial training session just prior to encountering a known or probable  $H_2S$  zone (within 3 days or 500 feet) and weekly  $H_2S$  and well control drills for all personnel in each crew. The initial training session shall include a review of the site specific  $H_2S$  Drilling Operations Plan and the Public Protection Plan.

## II. HYDROGEN SULFIDE TRAINING

Note: All  $H_2S$  safety equipment and systems will be installed, tested, and operational when drilling reaches a depth of 500 feet above, or three days prior to penetrating the first zone containing or reasonably expected to contain  $H_2S$ .

## 1. Well Control Equipment

- A. Flare line
- B. Choke manifold Remotely Operated
- C. Blind rams and pipe rams to accommodate all pipe sizes with properly sized closing unit
- D. Auxiliary equipment may include if applicable: annular preventer and rotating head.
- E. Mud/Gas Separator

## 2. Protective equipment for essential personnel:

30-minute SCBA units located at briefing areas, as indicated on well site diagram, with escape units available in the top doghouse. As it may be difficult to communicate audibly while wearing these units, hand signals shall be utilized.

## 3. H<sub>2</sub>S detection and monitoring equipment:

Portable H<sub>2</sub>S monitors positioned on location for best coverage and response. These units have warning lights which activate when H<sub>2</sub>S levels reach 10 ppm and audible sirens which activate at 15 ppm. Sensor locations:

- Bell nipple
   Possum Belly/Shale shaker
- Rig floor
   Choke manifold
- Cellar

## Visual warning systems:

- A. Wind direction indicators as shown on well site diagram
- B. Caution/ Danger signs shall be posted on roads providing direct access to locations. Signs will be painted a high visibility yellow with black lettering of sufficient size to be reasonable distance from the immediate location. Bilingual signs will be used when appropriate.

## 4. Mud program:

The mud program has been designed to minimize the volume of H<sub>2</sub>S circulated to surface. Proper mud weight, safe drilling practices and the use of H<sub>2</sub>S scavengers will minimize hazards when penetrating H<sub>2</sub>S bearing zones.

## 5. Metallurgy:

- A. All drill strings, casings, tubing, wellhead, blowout preventer, drilling spool, kill lines, choke manifold lines, and valves shall be H<sub>2</sub>S trim.
- B. All elastomers used for packing and seals shall be H<sub>2</sub>S trim.

## 6. Communication:

- A. Company personnel have/use cellular telephones in the field.
- B. Land line (telephone) communications at Office

## 7. Well testing:


- A. Drill stem testing will be performed with a minimum number of personnel in the immediate vicinity, which are necessary to safety and adequately conduct the test. The drill stem testing will be conducted during daylight hours and formation fluids will not be flowed to the surface. All drill-stem-testing operations conducted in an H<sub>2</sub>S environment will use the closed chamber method of testing.
- B. There will be no drill stem testing.


Devon Energy Corp. Company Call List						
Drilling Su	405-823-4796					
EHS Profe	essional – Laura Wright	405-439-8129				
Agency	<u>Call List</u>					
Lea County	Hobbs Lea County Communication Authority	393-3981				
<u>(575)</u>	State Police City Police Sheriff's Office	392-5588 397-9265 393-2515				
	Ambulance Fire Department	<b>911</b> 397-9308				
	LEPC (Local Emergency Planning Committee) NMOCD	<u>393-2870</u> <u>393-6161</u>				
Eddy	US Bureau of Land Management Carlsbad	393-3612				
<u>County</u> (575)	State Police City Police Sheriff's Office	885-3137 885-2111 887-7551				
	Ambulance Fire Department LEPC (Local Emergency Planning Committee)	<b>911</b> 885-3125 887-3798				
	US Bureau of Land Management NM Emergency Response Commission (Santa Fe)	887-6544 (505) 476-9600				
	24 HR National Emergency Response Center	(505) 827-9126 (800) 424-8802				
	National Pollution Control Center: Direct For Oil Spills Emergency Services	(703) 872-6000 (800) 280-7118				
	Wild Well ControlCudd Pressure Control(915) 699-0139Halliburton	(281) 784-4700 (915) 563-3356 (575) 746-2757				
Give	B. J. Services Native Air – Emergency Helicopter – Hobbs (TX & NM)	(575) 746-3569 (800) 642-7828				
GPS position:	Flight For Life - Lubbock, TX Aerocare - Lubbock, TX Med Flight Air Amb - Albuquerque, NM	(806) 743-9911 (806) 747-8923 (575) 842-4433 (800) 222-1222				
	Lifeguard Air Med Svc. Albuquerque, NM Poison Control (24/7) Oil & Gas Pipeline 24 Hour Service NOAA – Website - www.nhc.noaa.gov	(800) 222-1222 (575) 272-3115 (800) 364-4366				

Prepared in conjunction with Dave Small



.





District I 1625 N. French Dr., Hobbs, NM 88240

District II

District IV

Phone:(575) 393-6161 Fax:(575) 393-0720

811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720

Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

District III 1000 Rio Brazos Rd., Aztec, NM 87410 COMMENTS

Action 28309

## State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

COMMENTS								
Operator:					OGRID:	Action Number:	Action Type:	
	DEVON ENERGY PRODUCTIO	ON COMPAN	333 West Sheridan Ave.	Oklahoma City, OK73102	6137	28309	FORM 3160-3	
Created B	у	Comment			Comment	Date		
kpickford	pickford KP GEO Review 5/17/2021			05/17/202	1			

District I 1625 N. French Dr., Hobbs, NM 88240

District II

District IV

Phone:(575) 393-6161 Fax:(575) 393-0720

811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720

Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

District III 1000 Rio Brazos Rd., Aztec, NM 87410 CONDITIONS

Action 28309

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

#### CONDITIONS OF APPROVAL

Operator:				OGRID:	Action Number:	Action Type:	
	DEVON ENERGY PRODUCTION COMPAN	333 West Sheridan Ave.	Oklahoma City, OK73102	6137	28309	FORM 3160-3	
OCD	Condition						
Reviewer							
kpickford	Notify OCD 24 hours prior to casing & cement						
kpickford	Will require a File As Drilled C-102 and a Directional Survey with the C-104						
kpickford	Once the well is spud, to prevent ground water contamination through whole or partial conduits from the surface, the operator shall drill without interruption through the fresh water zone or zones and shall immediately set in cement the water protection string						
kpickford	Cement is required to circulate on both surface and in	termediate1 strings of casing					
kpickford	Oil base muds are not to be used until fresh water zones are cased and cemented providing isolation from the oil or diesel. This includes synthetic oils. Oil based mud, drilling fluids and solids must be contained in a steel closed loop system						