U.S. Department of the Interior BUREAU OF LAND MANAGEMENT		Sundry Print Report 09/02/2021
Well Name: DOMINATOR 25 FEDERAL COM	Well Location: T25S / R33E / SEC 25 / SWSW / 32.095022 / -103.531812	County or Parish/State: LEA /
Well Number: 714H	Type of Well: OIL WELL	Allottee or Tribe Name:
Lease Number: NMNM121958	Unit or CA Name: DOMINATOR 25 FED COM WELLS-WLF	Unit or CA Number: NMNM138694
US Well Number: 3002544748	Well Status: Producing Oil Well	Operator: COG OPERATING LLC

## **Notice of Intent**

Type of Submission: Notice of Intent

Date Sundry Submitted: 08/31/2021

Date proposed operation will begin: 11/15/2021

**Procedure Description:** COG Operating LLC respectfully requests temporary abandonment of the Dominator 25 Federal Com #714H. Three additional wells will be drilled on the same pad as the Dominator 25 Federal Com #714H so it will need to have production tubing pulled and the wellhead reduced to ground level in order to safely execute the drilling and completion of the new wells on this pad. Temporary abandonment operations are expected to begin November 15th, 2021. This well is expected to be put back on production in the fourth quarter of 2022. 1.) MIRU pulling unit, ND tree, NU BOP. 2.) POOH w/ production tubing. 3.) RIH w/ CIBP and set +/-75ft above top perforation at 12,860ft. 4.) Spot 25 sacks of Class H cement on top of CIBP. 5.) Tag top of cement and displace wellbore with corrosion inhibited fluid. 6.) Test casing to 500psi for 30min and document with test pressure recording device. 7.) ND BOP and install TA cap. 8.) RDMO. See attachments for current wellbore diagram, proposed wellbore diagram, and perforation depths.

Type of Action Temporary Abandonment

Time Sundry Submitted: 12:55

**Surface Disturbance** 

Is any additional surface disturbance proposed?: No

## **NOI Attachments**

#### **Procedure Description**

Dominator\_25\_Fed\_714H\_Proposed\_TA\_WBD\_20210831125426.pdf

Dominator\_25\_Fed\_714H\_Perf\_Summary\_20210831125416.pdf

Dominator\_25\_Fed\_714H\_Current\_WBD\_20210831125408.pdf

Dominator\_25\_Federal\_Com\_714H\_TA\_Justification\_and\_Procedure\_20210831125357.pdf

Accepted for Record Only



NMOCD 10/8/21

Received by OCD: 9/20/2021 11:21:41 AM Well Name: DOMINATOR 25 FEDERAL COM	Well Location: T25S / R33E / SEC 25 / SWSW / 32.095022 / -103.531812	County or Parish/State: LEA
Well Number: 714H	Type of Well: OIL WELL	Allottee or Tribe Name:
Lease Number: NMNM121958	Unit or CA Name: DOMINATOR 25 FED COM WELLS-WLF	Unit or CA Number: NMNM138694
<b>US Well Number:</b> 3002544748	Well Status: Producing Oil Well	<b>Operator:</b> COG OPERATING LLC

# **Conditions of Approval**

## **Specialist Review**

REVISED\_TA\_PROCEDURE\_20210902092543.pdf

## **Operator Certification**

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a submission of Form 3160-5 or a Sundry Notice.

**Operator Electronic Signature: MAYTE REYES** 

Name: COG OPERATING LLC

Title: Regulatory Analyst

Street Address: 925 N ELDRIDGE PARKWAY

City: HOUSTON

Phone: (281) 293-1000

Email address: MAYTE.X.REYES@CONOCOPHILLIPS.COM

State: TX

State: NM

## **Field Representative**

Representative Name: Gerald Herrera

Street Address: 2208 West Main Street

City: Artesia

Phone: (575)748-6940

Email address: gerald.a.herrera@conocophillips.com

# **BLM Point of Contact**

BLM POC Name: ZOTA M STEVENS BLM POC Phone: 5752345998 Disposition: Approved Signature: Zota Stevens

BLM POC Title: Petroleum Engineer BLM POC Email Address: ZSTEVENS@BLM.GOV Disposition Date: 09/02/2021

**Zip:** 88210

Signed on: AUG 31, 2021 12:54 PM

**Released to Imaging: 10/8/2021 1:14:27 PM** 

- 1.) MIRU pulling unit, ND tree, NU BOP.
- 2.) POOH w/ production tubing.
- 3.) RIH w/ CIBP and set +/-50 ft above top perforation at 12,860ft.
- 4.) Spot 25 sacks of Class H cement on top of CIBP. WOC AND TAG
- 5.) Tag top of cement and displace wellbore with corrosion inhibited fluid.
- 6.) Test casing to 500psi for 30min and document with test pressure recording device.
- 7.) ND BOP and install TA cap.
- 8.) RDMO.

## Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.

a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging. CIBP must be capped with minimum 25 sacks cement, **placed with tubing**.

b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leak-off will be evaluated.

c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.

d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.

e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.

3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned. 43 CFR 3162.3-4 (a) The operator shall promptly plug and abandon...wells in which oil or gas is not encountered in paying quantities...

Wells that successfully pass the casing integrity test **may** be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with well bore diagram with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.


If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

Well Name: <u>DOMINATOR 25 FED COM 714H</u> Submit Subsequent Report and well bore diagram with all Perforations and CIBP with tops of cement. Well may be approved to be TA for a period of <u>6 months or until 06/30/2022</u> after successful MIT and subsequent report is submitted. If well is not brought into production by 06/30/2022, operator shall P&A the well.

<b>Received by OCD: 9/20/2021 11:21:41</b> AM	Current WBD			Page 5 of 39
API: 30-025-44748 SPUD: 8/1/2018 FRR: 10/2/2018 RIG: McVay 8	Dominator 25 Federal #714H         Sec         25         T/B         25-S         R/Svy         33-E           Wildcat/Wolfcamp         BHL:         215'         FNL & 862'         FNL           Lea County         Sec         25         T/B         25-S         R/Svy         33-E           GL:         3,341'         KB:         3,367'         25-S         R/Svy         33-E	HOLE SIZE	(bdd) MW	BHST (F) Evaluation
	Surface Casing @ 1,152' 10.75 45.5 ppf L-80HC BTC	14.75"	8.4	No Logs
	Circulated 324 sx cement	9.875"	9.1	No Logs
5.5"x5" Casing Crossover at 11,302ft	DV Tool @ 5,142'         stg 1: 0 sx circulated         stg 2: 0 sx circulated         COC @ 12,399'         EOC @ 13,044'         EOL @ 17,380'         Average TVD in Lateral 12,795'         Production Casing @ 17,360'         5.5/5 23/18 ppf P-110 RYCC/RY CDC-HTQ         FC (PBTD) 17,333'         Notes: Planned Wet Shoe         Circulated: 327 sx cement         5.5'r X5'r X0: 11,302'         MJ: 12,183'	6.75"	12.5	172°F Mud Logs

	Cluster 1	Cluster 2	Cluster 3	Cluster 4	Cluster 5	Cluster 6	Cluster 7	Cluster 8
Stage 1	17,285	17263	17241	17219	17198	17176	17154	17132
Stage 2	17110	17088	17066	17045	17023	17001	16979	16957
2 mg - 2	1,110	1,000	1,000	17010	1,020	1,001	10313	10507
Stage 3	16935	16913	16892	16870	16848	16826	16804	16782
Stage 4	16760	16739	16717	16695	16673	16651	16629	16607
8								
Stage 5	16586	16564	16542	16520	16498	16476	16454	16432
Stage 6	16411	16389	16367	16345	16323	16301	16279	16258
						1		1
Stage 7	16236	16214	16192	16170	16148	16126	16105	16083
Stage 8	16061	16039	16017	15995	15973	15952	15930	15908
							1	
Stage 9	15886	15864	15842	15820	15799	15777	15755	15733
Stage 10	15711	15689	15667	15646	15624	15602	15580	15558
		· ·						
Stage 11	15536	15514	15493	15471	15449	15427	15405	15383
Stage 12	15361	15340	15318	15296	15274	15252	15230	15208
					- L			
Stage 13	15187	15165	15143	15121	15099	15077	15055	15034
Stage 14	15012	14990	14968	14946	14924	14902	14881	14859
		<u>.</u>			<u>.</u>			
Stage 15	14837	14815	14793	14771	14749	14727	14706	14684
Stage 16	14662	14640	14618	14596	14574	14553	14531	14509
							1	
Stage 17	14487	14465	14443	14421	14400	14378	14356	14334
Stage 18	14312	14290	14268	14247	14225	14203	14181	14159
~ 10								
Stage 19	14137	14115	14094	14072	14050	14028	14006	13984
Stage 20	13962	13941	13919	13897	13875	13853	13831	13809
Ct 21	12700	127((	12744	12722	12700	12(70	12(5)	12(25
Stage 21	13788	13766	13744	13722	13700	13678	13656	13635
Stage 22	13613	13591	13569	13547	13525	13503	13482	13460
Star 22	12420	12416	12204	12272	12250	12220	12207	12295
Stage 23	13438	13416	13394	13372	13350	13329	13307	13285
Stage 24	13263	13241	13219	13197	13176	13154	13132	13110
	10000	10055		10000	10001			10005
Stage 25	13088	13066	13044	13022	13001	12979	12957	12935



COG Operating LLC respectfully requests temporary abandonment of the Dominator 25 Federal Com #714H. Three additional wells will be drilled on the same pad as the Dominator 25 Federal Com #714H so it will need to have production tubing pulled and the wellhead reduced to ground level in order to safely execute the drilling and completion of the new wells on this pad. Temporary abandonment operations are expected to begin November 15<sup>th</sup>, 2021. This well is expected to be put back on production in the fourth quarter of 2022.

- 1.) MIRU pulling unit, ND tree, NU BOP.
- 2.) POOH w/ production tubing.
- 3.) RIH w/ CIBP and set +/-75ft above top perforation at 12,860ft.
- 4.) Spot 25 sacks of Class H cement on top of CIBP.
- 5.) Tag top of cement and displace wellbore with corrosion inhibited fluid.
- 6.) Test casing to 500psi for 30min and document with test pressure recording device.
- 7.) ND BOP and install TA cap.
- 8.) RDMO.

- 1.) MIRU pulling unit, ND tree, NU BOP.
- 2.) POOH w/ production tubing.
- 3.) RIH w/ CIBP and set +/-50 ft above top perforation at 12,860ft.
- 4.) Spot 25 sacks of Class H cement on top of CIBP. WOC AND TAG
- 5.) Tag top of cement and displace wellbore with corrosion inhibited fluid.
- 6.) Test casing to 500psi for 30min and document with test pressure recording device.
- 7.) ND BOP and install TA cap.
- 8.) RDMO.

## Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.

a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging. CIBP must be capped with minimum 25 sacks cement, **placed with tubing**.

b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leak-off will be evaluated.

c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.

d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.

e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.

3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned. 43 CFR 3162.3-4 (a) The operator shall promptly plug and abandon...wells in which oil or gas is not encountered in paying quantities...

Wells that successfully pass the casing integrity test **may** be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with well bore diagram with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.


If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

Well Name: <u>DOMINATOR 25 FED COM 714H</u> Submit Subsequent Report and well bore diagram with all Perforations and CIBP with tops of cement. Well may be approved to be TA for a period of <u>6 months or until 06/30/2022</u> after successful MIT and subsequent report is submitted. If well is not brought into production by 06/30/2022, operator shall P&A the well.

<b>Received by OCD: 9/20/2021 11:21:41 AM</b>	Current WBD			Page	11 of 39
API: 30-025-44748 SPUD: 8/1/2018 FRR: 10/2/2018 RIG: McVay 8	Dominator 25 Federal #714H         Sec         25         T/B         25-S         R/Svy         33-E           Wildcat/Wolfcamp         SHL:         280'         FSL & 862'         FNL           BHL:         215'         FNL & 789'         FWL (est.)           Sec         25         T/B         25-S         R/Svy         33-E           GL:         3,341'         KB:         3,367'         25-S         R/Svy         33-E	HOLE SIZE	(bdd) MM	BHST (F)	Evaluation
	Surface Casing         @ 1,152'           10.75         45.5 ppf         L-80HC         BTC	14.75"	8.4		No Logs
	Circulated 324 sx cement Intermediate Casing @ 11,813' 7.625 29.7 ppf L-80HP BTC	9.875"	9.1		No Logs
5.5"x5" Casing Crossover at 11,302ft	DV Tool @ 5,142'         stg 1: 0 sx circulated         stg 2: 0 sx circulated         Stg 2: 0 sx circulated         COC @ 13,044'         EOC @ 17,380'         Average TVD in Lateral       12,795'         Image: Style of the system of the s	6.75"	12.5	172°F	Mud Logs

	Cluster 1	Cluster 2	Cluster 3	Cluster 4	Cluster 5	Cluster 6	Cluster 7	Cluster 8
Stage 1	17,285	17263	17241	17219	17198	17176	17154	17132
Stage 2	17110	17088	17066	17045	17023	17001	16979	16957
			·	1	• •	• •		
Stage 3	16935	16913	16892	16870	16848	16826	16804	16782
Stage 4	16760	16739	16717	16695	16673	16651	16629	16607
Stage 5	16586	16564	16542	16520	16498	16476	16454	16432
Stage 6	16411	16389	16367	16345	16323	16301	16279	16258
a. 7	1(00)	16014	1(102	1(170	16140	1(12)	16105	1.0002
Stage 7	16236	16214	16192	16170	16148	16126	16105	16083
Stage 8	16061	16039	16017	15995	15973	15952	15930	15908
Stage 9	15886	15864	15842	15820	15799	15777	15755	15733
Stage 9	13880	13804	13842	13820	13799	13///	13733	13/33
Stage 10	15711	15689	15667	15646	15624	15602	15580	15558
Stage 11	15536	15514	15493	15471	15449	15427	15405	15383
Stage 11	15550	15514	13493	134/1	13449	13427	13403	15565
Stage 12	15361	15340	15318	15296	15274	15252	15230	15208
Stage 13	15187	15165	15143	15121	15099	15077	15055	15034
Suge 10	10107	10100	10110	10121	10077	100,7	10000	10001
Stage 14	15012	14990	14968	14946	14924	14902	14881	14859
Stage 15	14837	14815	14793	14771	14749	14727	14706	14684
		· · · · · · · · · · · · · · · · · · ·	·	-1	·	·	·	·
Stage 16	14662	14640	14618	14596	14574	14553	14531	14509
Stage 17	14487	14465	14443	14421	14400	14378	14356	14334
Stage 18	14312	14290	14268	14247	14225	14203	14181	14159
Stage 19	14137	14115	14094	14072	14050	14028	14006	13984
G( 20	120/2	12041	12010	12007	12075	12052	12021	12900
Stage 20	13962	13941	13919	13897	13875	13853	13831	13809
Stage 21	13788	13766	13744	13722	13700	13678	13656	13635
Stage 22	13613	13591	13569	13547	13525	13503	13482	13460
Stage 22	13013	13391	13309	13347	13323	13303	13482	13400
Stage 23	13438	13416	13394	13372	13350	13329	13307	13285
Stage 24	13263	13241	13219	13197	13176	13154	13132	13110
Stage 24	13203	13241	13219	1317/	131/0	1 13134	13132	15110
Stage 25	13088	13066	13044	13022	13001	12979	12957	12935



COG Operating LLC respectfully requests temporary abandonment of the Dominator 25 Federal Com #714H. Three additional wells will be drilled on the same pad as the Dominator 25 Federal Com #714H so it will need to have production tubing pulled and the wellhead reduced to ground level in order to safely execute the drilling and completion of the new wells on this pad. Temporary abandonment operations are expected to begin November 15<sup>th</sup>, 2021. This well is expected to be put back on production in the fourth quarter of 2022.

- 1.) MIRU pulling unit, ND tree, NU BOP.
- 2.) POOH w/ production tubing.
- 3.) RIH w/ CIBP and set +/-75ft above top perforation at 12,860ft.
- 4.) Spot 25 sacks of Class H cement on top of CIBP.
- 5.) Tag top of cement and displace wellbore with corrosion inhibited fluid.
- 6.) Test casing to 500psi for 30min and document with test pressure recording device.
- 7.) ND BOP and install TA cap.
- 8.) RDMO.

- 1.) MIRU pulling unit, ND tree, NU BOP.
- 2.) POOH w/ production tubing.
- 3.) RIH w/ CIBP and set +/-50 ft above top perforation at 12,860ft.
- 4.) Spot 25 sacks of Class H cement on top of CIBP. WOC AND TAG
- 5.) Tag top of cement and displace wellbore with corrosion inhibited fluid.
- 6.) Test casing to 500psi for 30min and document with test pressure recording device.
- 7.) ND BOP and install TA cap.
- 8.) RDMO.

## Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.

a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging. CIBP must be capped with minimum 25 sacks cement, **placed with tubing**.

b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leak-off will be evaluated.

c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.

d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.

e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.

3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned. 43 CFR 3162.3-4 (a) The operator shall promptly plug and abandon...wells in which oil or gas is not encountered in paying quantities...

Wells that successfully pass the casing integrity test **may** be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with well bore diagram with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.


If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

Well Name: <u>DOMINATOR 25 FED COM 714H</u> Submit Subsequent Report and well bore diagram with all Perforations and CIBP with tops of cement. Well may be approved to be TA for a period of <u>6 months or until 06/30/2022</u> after successful MIT and subsequent report is submitted. If well is not brought into production by 06/30/2022, operator shall P&A the well.

<b>Received by OCD: 9/20/2021 11:21:41 AM</b>	Current WBD			Page	17 of 39
API: 30-025-44748 SPUD: 8/1/2018 FRR: 10/2/2018 RIG: McVay 8	Dominator 25 Federal #714H         Sec         25         T/B         25-S         R/Svy         33-E           Wildcat/Wolfcamp         SHL:         280'         FSL & 862'         FNL           Lea County         Sec         25         T/B         25-S         R/Svy         33-E           GL:         3,341'         Sec         25         T/B         25-S         R/Svy         33-E           ZERO:         26'         ZERO:         26'         ZERO:         26'         ZERO:         26'	HOLE SIZE	MW (ppg)	BHST (F)	Evaluation
	Surface Casing @ 1,152' 10.75 45.5 ppf L-80HC BTC	14.75"	8.4		No Logs
	Circulated 324 sx cement          Intermediate Casing       @ 11,813'         7.625       29.7 ppf       L-80HP       BTC	9.875"	9.1		No Logs
5.5"x5" Casing Crossover at 11,302ft	DV Tool @ 5,142'       stg 1: 0 sx circulated         stg 2: 0 sx circulated         Stg 2: 0 sx circulated         EOC @ 12,399'         EOC @ 13,044'         EOL @ 17,380'         Average TVD in Lateral       12,795'         Image: T	6.75"	12.5	172°F	sgot bud

	Cluster 1	Cluster 2	Cluster 3	Cluster 4	Cluster 5	Cluster 6	Cluster 7	Cluster 8
Stage 1	17,285	17263	17241	17219	17198	17176	17154	17132
Stage 2	17110	17088	17066	17045	17023	17001	16979	16957
			·	1	• •	• •		
Stage 3	16935	16913	16892	16870	16848	16826	16804	16782
Stage 4	16760	16739	16717	16695	16673	16651	16629	16607
Stage 5	16586	16564	16542	16520	16498	16476	16454	16432
Stage 6	16411	16389	16367	16345	16323	16301	16279	16258
G. 7	1(00)	16014	1(102	1(170	16140	1(12)	16105	1.0002
Stage 7	16236	16214	16192	16170	16148	16126	16105	16083
Stage 8	16061	16039	16017	15995	15973	15952	15930	15908
Stage 9	15886	15864	15842	15820	15799	15777	15755	15733
Stage 9	13880	13804	13842	13820	13799	13///	13733	13/33
Stage 10	15711	15689	15667	15646	15624	15602	15580	15558
Stage 11	15536	15514	15493	15471	15449	15427	15405	15383
Stage 11	15550	15514	13493	134/1	13449	13427	13403	15565
Stage 12	15361	15340	15318	15296	15274	15252	15230	15208
Stage 13	15187	15165	15143	15121	15099	15077	15055	15034
Singe It	10107	10100	10110	10121	10077	100,7	10000	10001
Stage 14	15012	14990	14968	14946	14924	14902	14881	14859
Stage 15	14837	14815	14793	14771	14749	14727	14706	14684
		· · · · · · · · · · · · · · · · · · ·	·	1	·	·	·	·
Stage 16	14662	14640	14618	14596	14574	14553	14531	14509
Stage 17	14487	14465	14443	14421	14400	14378	14356	14334
Stage 18	14312	14290	14268	14247	14225	14203	14181	14159
Stage 19	14137	14115	14094	14072	14050	14028	14006	13984
G( 20	120/2	12041	12010	12007	12075	12052	12021	12900
Stage 20	13962	13941	13919	13897	13875	13853	13831	13809
Stage 21	13788	13766	13744	13722	13700	13678	13656	13635
Stage 22	13613	13591	13569	13547	13525	13503	13482	13460
Stage 22	13013	13391	13309	13347	13323	13303	13482	13400
Stage 23	13438	13416	13394	13372	13350	13329	13307	13285
Stage 24	13263	13241	13219	13197	13176	13154	13132	13110
Stage 24	13203	13241	13219	1317/	131/0	1 13134	13132	15110
Stage 25	13088	13066	13044	13022	13001	12979	12957	12935



COG Operating LLC respectfully requests temporary abandonment of the Dominator 25 Federal Com #714H. Three additional wells will be drilled on the same pad as the Dominator 25 Federal Com #714H so it will need to have production tubing pulled and the wellhead reduced to ground level in order to safely execute the drilling and completion of the new wells on this pad. Temporary abandonment operations are expected to begin November 15<sup>th</sup>, 2021. This well is expected to be put back on production in the fourth quarter of 2022.

- 1.) MIRU pulling unit, ND tree, NU BOP.
- 2.) POOH w/ production tubing.
- 3.) RIH w/ CIBP and set +/-75ft above top perforation at 12,860ft.
- 4.) Spot 25 sacks of Class H cement on top of CIBP.
- 5.) Tag top of cement and displace wellbore with corrosion inhibited fluid.
- 6.) Test casing to 500psi for 30min and document with test pressure recording device.
- 7.) ND BOP and install TA cap.
- 8.) RDMO.

- 1.) MIRU pulling unit, ND tree, NU BOP.
- 2.) POOH w/ production tubing.
- 3.) RIH w/ CIBP and set +/-50 ft above top perforation at 12,860ft.
- 4.) Spot 25 sacks of Class H cement on top of CIBP. WOC AND TAG
- 5.) Tag top of cement and displace wellbore with corrosion inhibited fluid.
- 6.) Test casing to 500psi for 30min and document with test pressure recording device.
- 7.) ND BOP and install TA cap.
- 8.) RDMO.

## Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.

a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging. CIBP must be capped with minimum 25 sacks cement, **placed with tubing**.

b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leak-off will be evaluated.

c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.

d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.

e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.

3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned. 43 CFR 3162.3-4 (a) The operator shall promptly plug and abandon...wells in which oil or gas is not encountered in paying quantities...

Wells that successfully pass the casing integrity test **may** be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with well bore diagram with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.


If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

Well Name: <u>DOMINATOR 25 FED COM 714H</u> Submit Subsequent Report and well bore diagram with all Perforations and CIBP with tops of cement. Well may be approved to be TA for a period of <u>6 months or until 06/30/2022</u> after successful MIT and subsequent report is submitted. If well is not brought into production by 06/30/2022, operator shall P&A the well.

<b>Received by OCD: 9/20/2021 11:21:41 AM</b>	Current WBD			Page	23 of 39
API: 30-025-44748 SPUD: 8/1/2018 FRR: 10/2/2018 RIG: McVay 8	Dominator 25 Federal #714H         Sec         25         T/B         25-S         R/Svy         33-E           Wildcat/Wolfcamp         BHL:         215'         FNL & 862'         FNL           BHL:         215'         FNL & 789'         FWL (est.)           Sec         25         T/B         25-S           R/Svy         33-E           GL:         3,341'           KB:         3,367'           ZERO:         26'	HOLE SIZE	(bdd) MM	BHST (F)	Evaluation
	Surface Casing         @ 1,152'           10.75         45.5 ppf         L-80HC         BTC	14.75"	8.4		No Logs
	Circulated 324 sx cement          Intermediate Casing       @       11,813'         7.625       29.7 ppf       L-80HP       BTC	9.875"	9.1		No Logs
5.5"x5" Casing Crossover at 11,302ft	DV Tool @ 5,142'         stg 1: 0 sx circulated         stg 2: 0 sx circulated         EOC @ 12,399'         EOC @ 13,044'         EOL @ 17,380'         Average TVD in Lateral       12,795'         Production Casing @ 17,360'         S.5/5 23/18 ppf P-110 RYCC/RY CDC-HTQ         FC (PBTD)       17,333'         Notes: Planned Wet Shoe         Circulated:       327 sx cement         5.5'' x 5'' XO: 11,302'         My: 12,183'	6.75"	12.5	172°F	sgot bud

	Cluster 1	Cluster 2	Cluster 3	Cluster 4	Cluster 5	Cluster 6	Cluster 7	Cluster 8
Stage 1	17,285	17263	17241	17219	17198	17176	17154	17132
Stage 2	17110	17088	17066	17045	17023	17001	16979	16957
Stage 3	16935	16913	16892	16870	16848	16826	16804	16782
Stage 4	16760	16739	16717	16695	16673	16651	16629	16607
Stage 5	16586	16564	16542	16520	16498	16476	16454	16432
Stage 6	16411	16389	16367	16345	16323	16301	16279	16258
Stage 7	16236	16214	16192	16170	16148	16126	16105	16083
Stage 8	16061	16039	16017	15995	15973	15952	15930	15908
Stage 9	15886	15864	15842	15820	15799	15777	15755	15733
Stage 10	15711	15689	15667	15646	15624	15602	15580	15558
Stage 11	15536	15514	15493	15471	15449	15427	15405	15383
Stage 12	15361	15340	15318	15296	15274	15252	15230	15208
Stage 13	15187	15165	15143	15121	15099	15077	15055	15034
Stage 14	15012	14990	14968	14946	14924	14902	14881	14859
Stage 15	14837	14815	14793	14771	14749	14727	14706	14684
Stage 16	14662	14640	14618	14596	14574	14553	14531	14509
Stage 17	14487	14465	14443	14421	14400	14378	14356	14334
Stage 18	14312	14290	14268	14247	14225	14203	14181	14159
Stage 19	14137	14115	14094	14072	14050	14028	14006	13984
Stage 20	13962	13941	13919	13897	13875	13853	13831	13809
Stage 21	13788	13766	13744	13722	13700	13678	13656	13635
Stage 22	13613	13591	13569	13547	13525	13503	13482	13460
Stage 23	13438	13416	13394	13372	13350	13329	13307	13285
Stage 24	13263	13241	13219	13197	13176	13154	13132	13110
Stage 25	13088	13066	13044	13022	13001	12979	12957	12935



COG Operating LLC respectfully requests temporary abandonment of the Dominator 25 Federal Com #714H. Three additional wells will be drilled on the same pad as the Dominator 25 Federal Com #714H so it will need to have production tubing pulled and the wellhead reduced to ground level in order to safely execute the drilling and completion of the new wells on this pad. Temporary abandonment operations are expected to begin November 15<sup>th</sup>, 2021. This well is expected to be put back on production in the fourth quarter of 2022.

- 1.) MIRU pulling unit, ND tree, NU BOP.
- 2.) POOH w/ production tubing.
- 3.) RIH w/ CIBP and set +/-75ft above top perforation at 12,860ft.
- 4.) Spot 25 sacks of Class H cement on top of CIBP.
- 5.) Tag top of cement and displace wellbore with corrosion inhibited fluid.
- 6.) Test casing to 500psi for 30min and document with test pressure recording device.
- 7.) ND BOP and install TA cap.
- 8.) RDMO.

- 1.) MIRU pulling unit, ND tree, NU BOP.
- 2.) POOH w/ production tubing.
- 3.) RIH w/ CIBP and set +/-50 ft above top perforation at 12,860ft.
- 4.) Spot 25 sacks of Class H cement on top of CIBP. WOC AND TAG
- 5.) Tag top of cement and displace wellbore with corrosion inhibited fluid.
- 6.) Test casing to 500psi for 30min and document with test pressure recording device.
- 7.) ND BOP and install TA cap.
- 8.) RDMO.

## Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.

a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging. CIBP must be capped with minimum 25 sacks cement, **placed with tubing**.

b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leak-off will be evaluated.

c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.

d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.

e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.

3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned. 43 CFR 3162.3-4 (a) The operator shall promptly plug and abandon...wells in which oil or gas is not encountered in paying quantities...

Wells that successfully pass the casing integrity test **may** be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with well bore diagram with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.


If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

Well Name: <u>DOMINATOR 25 FED COM 714H</u> Submit Subsequent Report and well bore diagram with all Perforations and CIBP with tops of cement. Well may be approved to be TA for a period of <u>6 months or until 06/30/2022</u> after successful MIT and subsequent report is submitted. If well is not brought into production by 06/30/2022, operator shall P&A the well.

<b>Received by OCD: 9/20/2021 11:21:41 AM</b>	Current WBD		Pag	e 29 of 39
API: 30-025-44748 SPUD: 8/1/2018 FRR: 10/2/2018 RIG: McVay 8	Dominator 25 Federal #714H         Sec         25         T/B         25-S         R/Svy         33-E           Wildcat/Wolfcamp         BHL:         215'         FNL & 789'         FWL (est.)           Lea County         Sec         25         T/B         25-S         R/Svy         33-E           GL:         3,341'         KB:         3,367'         ZERO:         26'	HOLE SIZE	BHST (F)	Evaluation
	10.75 45.5 ppf L-80HC BTC	14.75" 8.4	5	No Logs
	Intermediate Casing @ 11,813' 7.625 29.7 ppf L-80HP BTC	9.875" 9.4	;	No Logs
5.5"x5" Casing Crossover at 11,302ft	DV Tool @ 5,142' stg 1: 0 sx circulated stg 2: 0 sx circulated KOP @ 12,399' EOC @ 13,044'	6.75" 12 F	 172°F	Wud Logs

	Cluster 1	Cluster 2	Cluster 3	Cluster 4	Cluster 5	Cluster 6	Cluster 7	Cluster 8
Stage 1	17,285	17263	17241	17219	17198	17176	17154	17132
Stage 2	17110	17088	17066	17045	17023	17001	16979	16957
Stage 3	16935	16913	16892	16870	16848	16826	16804	16782
Stage 5	10755	10913	10892	10870	10040	10820	10804	10/82
Stage 4	16760	16739	16717	16695	16673	16651	16629	16607
Stage 5	16586	16564	16542	16520	16498	16476	16454	16432
Stage 6	16411	16389	16367	16345	16323	16301	16279	16258
Stage 7	16236	16214	16192	16170	16148	16126	16105	16083
Stage 8	16061	16039	16017	15995	15973	15952	15930	15908
Stage 9	15886	15864	15842	15820	15799	15777	15755	15733
Stage 10	15711	15689	15667	15646	15624	15602	15580	15558
Stage 11	15536	15514	15493	15471	15449	15427	15405	15383
Stage 12	15361	15340	15318	15296	15274	15252	15230	15208
Stage 13	15187	15165	15143	15121	15099	15077	15055	15034
Stage 14	15012	14990	14968	14946	14924	14902	14881	14859
Stage 15	14837	14815	14793	14771	14749	14727	14706	14684
Stage 16	14662	14640	14618	14596	14574	14553	14531	14509
Stage 17	14487	14465	14443	14421	14400	14378	14356	14334
Stage 18	14312	14290	14268	14247	14225	14203	14181	14159
Stage 19	14137	14115	14094	14072	14050	14028	14006	13984
Stage 20	13962	13941	13919	13897	13875	13853	13831	13809
Stage 21	13788	13766	13744	13722	13700	13678	13656	13635
Stage 22	13613	13591	13569	13547	13525	13503	13482	13460
Stage 23	13438	13416	13394	13372	13350	13329	13307	13285
Stage 24	13263	13241	13219	13197	13176	13154	13132	13110
Stage 25	13088	13066	13044	13022	13001	12979	12957	12935



COG Operating LLC respectfully requests temporary abandonment of the Dominator 25 Federal Com #714H. Three additional wells will be drilled on the same pad as the Dominator 25 Federal Com #714H so it will need to have production tubing pulled and the wellhead reduced to ground level in order to safely execute the drilling and completion of the new wells on this pad. Temporary abandonment operations are expected to begin November 15<sup>th</sup>, 2021. This well is expected to be put back on production in the fourth quarter of 2022.

- 1.) MIRU pulling unit, ND tree, NU BOP.
- 2.) POOH w/ production tubing.
- 3.) RIH w/ CIBP and set +/-75ft above top perforation at 12,860ft.
- 4.) Spot 25 sacks of Class H cement on top of CIBP.
- 5.) Tag top of cement and displace wellbore with corrosion inhibited fluid.
- 6.) Test casing to 500psi for 30min and document with test pressure recording device.
- 7.) ND BOP and install TA cap.
- 8.) RDMO.

- 1.) MIRU pulling unit, ND tree, NU BOP.
- 2.) POOH w/ production tubing.
- 3.) RIH w/ CIBP and set +/-50 ft above top perforation at 12,860ft.
- 4.) Spot 25 sacks of Class H cement on top of CIBP. WOC AND TAG
- 5.) Tag top of cement and displace wellbore with corrosion inhibited fluid.
- 6.) Test casing to 500psi for 30min and document with test pressure recording device.
- 7.) ND BOP and install TA cap.
- 8.) RDMO.

## Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.

a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging. CIBP must be capped with minimum 25 sacks cement, **placed with tubing**.

b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leak-off will be evaluated.

c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.

d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.

e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.

3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned. 43 CFR 3162.3-4 (a) The operator shall promptly plug and abandon...wells in which oil or gas is not encountered in paying quantities...

Wells that successfully pass the casing integrity test **may** be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with well bore diagram with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.


If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

Well Name: <u>DOMINATOR 25 FED COM 714H</u> Submit Subsequent Report and well bore diagram with all Perforations and CIBP with tops of cement. Well may be approved to be TA for a period of <u>6 months or until 06/30/2022</u> after successful MIT and subsequent report is submitted. If well is not brought into production by 06/30/2022, operator shall P&A the well.

<b>Received by OCD: 9/20/2021 11:21:41 AM</b>	Current WBD			Page	35 of 39
API: 30-025-44748 SPUD: 8/1/2018 FRR: 10/2/2018 RIG: McVay 8	Dominator 25 Federal #714H         Sec         25         T/B         25-S         R/Svy         33-E           Wildcat/Wolfcamp         BHL:         215'         FNL & 862'         FNL           Lea County         Sec         25         T/B         25-S         R/Svy         33-E           GL:         3,341'         KB:         3,367'         ZERO:         26'         26'	HOLE SIZE	MW (ppg)	BHST (F)	Evaluation
	Surface Casing         @ 1,152'           10.75         45.5 ppf         L-80HC         BTC	14.75"	8.4		No Logs
	Circulated 324 sx cement  Intermediate Casing @ 11,813'  7.625 29.7 ppf L-80HP BTC	9.875"	9.1		No Logs
5.5"x5" Casing Crossover at 11,302ft	DV Tool @ 5,142'       stg 1: 0 sx circulated         stg 1: 0 sx circulated         stg 2: 0 sx circulated         EOC @ 13,044'         EOL @ 17,380'         Average TVD in Lateral       12,795'         Production Casing @ 17,360'	6.75"	12.5	172°F	Sgod Logs

	Cluster 1	Cluster 2	Cluster 3	Cluster 4	Cluster 5	Cluster 6	Cluster 7	Cluster 8
Stage 1	17,285	17263	17241	17219	17198	17176	17154	17132
Stage 2	17110	17088	17066	17045	17023	17001	16979	16957
				1		1	1	
Stage 3	16935	16913	16892	16870	16848	16826	16804	16782
Stage 4	16760	16739	16717	16695	16673	16651	16629	16607
		<u>.</u>		'	<u>.</u>	-	-	·
Stage 5	16586	16564	16542	16520	16498	16476	16454	16432
Stage 6	16411	16389	16367	16345	16323	16301	16279	16258
a	1.622.6	1 (01.4	1 (100	1 (1 5 0	1.61.40	1.612.6	1.610.5	1.000
Stage 7	16236	16214	16192	16170	16148	16126	16105	16083
Stage 8	16061	16039	16017	15995	15973	15952	15930	15908
Stars 0	1500(	15964	15942	15920	15700	15777	15755	15722
Stage 9	15886	15864	15842	15820	15799	15777	15755	15733
Stage 10	15711	15689	15667	15646	15624	15602	15580	15558
Stage 11	15536	15514	15493	15471	15449	15427	15405	15383
Stage 11	15550	15514	15495	134/1	13449	13427	15405	15585
Stage 12	15361	15340	15318	15296	15274	15252	15230	15208
Stage 13	15187	15165	15143	15121	15099	15077	15055	15034
Stage 15	15167	15105	15145	13121	15077	15077	15055	15054
Stage 14	15012	14990	14968	14946	14924	14902	14881	14859
Stage 15	14837	14815	14793	14771	14749	14727	14706	14684
Stage 16	14662	14640	14618	14596	14574	14553	14531	14509
Stage 17	14487	14465	14443	14421	14400	14378	14356	14334
		<u>.</u>			·	-		·
Stage 18	14312	14290	14268	14247	14225	14203	14181	14159
Stage 19	14137	14115	14094	14072	14050	14028	14006	13984
~ ~ ~								
Stage 20	13962	13941	13919	13897	13875	13853	13831	13809
Stage 21	13788	13766	13744	13722	13700	13678	13656	13635
Store 22	12(12	12501	125(0	12547	12525	12502	12492	12460
Stage 22	13613	13591	13569	13547	13525	13503	13482	13460
Stage 23	13438	13416	13394	13372	13350	13329	13307	13285
Store 24	12262	12241	12210	12107	13176	12154	12122	12110
Stage 24	13263	13241	13219	13197	131/0	13154	13132	13110
Stage 25	13088	13066	13044	13022	13001	12979	12957	12935



COG Operating LLC respectfully requests temporary abandonment of the Dominator 25 Federal Com #714H. Three additional wells will be drilled on the same pad as the Dominator 25 Federal Com #714H so it will need to have production tubing pulled and the wellhead reduced to ground level in order to safely execute the drilling and completion of the new wells on this pad. Temporary abandonment operations are expected to begin November 15<sup>th</sup>, 2021. This well is expected to be put back on production in the fourth quarter of 2022.

- 1.) MIRU pulling unit, ND tree, NU BOP.
- 2.) POOH w/ production tubing.
- 3.) RIH w/ CIBP and set +/-75ft above top perforation at 12,860ft.
- 4.) Spot 25 sacks of Class H cement on top of CIBP.
- 5.) Tag top of cement and displace wellbore with corrosion inhibited fluid.
- 6.) Test casing to 500psi for 30min and document with test pressure recording device.
- 7.) ND BOP and install TA cap.
- 8.) RDMO.

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

# **State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
COG OPERATING LLC	229137
600 W Illinois Ave	Action Number:
Midland, TX 79701	50165
	Action Type:
	[C-103] NOI Temporary Abandonment (C-103I)

#### CONDITIONS

Created By	Condition	Condition Date
kfortner	BLM approval required	10/8/2021

CONDITIONS

Page 39 of 39

.

Action 50165