Sundry Print Report

U.S. Department of the Interior BUREAU OF LAND MANAGEMENT

Well Name: GARRETT COM Well Location: T29N / R11W / SEC 12 / County or Parish/State: SAN

SENE / 36.741755 / -107.937064 JUAN / NM

Well Number: 100S Type of Well: OTHER Allottee or Tribe Name:

Lease Number: NMNM03717B Unit or CA Name: GARRETT COM Unit or CA Number:

NMNM96707

US Well Number: 3004534835 Well Status: Temporarily Abandoned Operator: HILCORP ENERGY

COMPANY

Notice of Intent

Sundry ID: 2635188

Type of Submission: Notice of Intent

Type of Action: Plug and Abandonment

Date Sundry Submitted: 09/21/2021 Time Sundry Submitted: 08:50

Date proposed operation will begin: 10/03/2021

Procedure Description: Hilcorp Energy Company requests permission to P&A the subject well per the attached procedure, current and proposed wellbore schematic. The Pre-Disturbance Site Visit was held on 9/20/2021 with Bob Switzer/BLM. The re-vegetation plan is attached. A closed loop system will be used.

Surface Disturbance

Is any additional surface disturbance proposed?: No

NOI Attachments

Procedure Description

 $P_A_Procedure___Garrett_Com_100S_20210921084939.pdf$

Page 1 of 2

Well Location: T29N / R11W / SEC 12 /

SENE / 36.741755 / -107.937064

County or Parish/State: SAN

JUAN / NM

Well Number: 100S Type of Well: OTHER Allottee or Tribe Name:

Lease Number: NMNM03717B Unit or CA Name: GARRETT COM **Unit or CA Number:**

NMNM96707

US Well Number: 3004534835 Well Status: Temporarily Abandoned Operator: HILCORP ENERGY

COMPANY

Conditions of Approval

Additional Reviews

2635188_NOIA_100S_30045234835_KR_10212021_20211021172339.pdf 29N11W12HKkf_Garrett_Com_100S_20211021151037.pdf

Operator Certification

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a submission of Form 3160-5 or a Sundry Notice.

Operator Electronic Signature: AMANDA WALKER Signed on: SEP 21, 2021 08:50 AM

Name: HILCORP ENERGY COMPANY Title: Operations/Regulatory Technician

Street Address: 1111 TRAVIS ST.

City: HOUSTON State: TX

Phone: (346) 237-2177

Email address: mwalker@hilcorp.com

Field Representative

Representative Name:

Street Address:

City: State: Zip:

Phone:

Email address:

BLM Point of Contact

Signature: Kenneth Rennick

BLM POC Name: KENNETH G RENNICK BLM POC Title: Petroleum Engineer

BLM POC Phone: 5055647742 BLM POC Email Address: krennick@blm.gov

Disposition: Approved Disposition Date: 10/21/2021

Plug and Abandonment - NOI Garrett Com 100S API # - 3004534835

Procedure:

Hold PJSM prior to beginning any and all operations. Properly document all operations via the JSA process. Ensure that all personnel onsite abide by HEC safety protocol, including PPE, housekeeping, and standard guidelines.

Verify cathodic protection is off and wellhead instrumentation is properly disconnected from the wellhead. Comply with all NMOCD, BLM, and HEC safety and environmental regulations.


Verify there is no H2S present prior to beginning operations. If any H2S is present, take the necessary actions to ensure that the location is safe prior to beginning operations.


Observe and record pressures across all string daily, prior to beginning operations. Remember to notify NMOCD 24 hours prior to starting operations on location.

NOTE: **This procedure is contingent upon P&A sundry approval by NMOCD**. All cement volumes use 100% excess outside pipe and 50' excess inside (unless otherwise stated). All cement will be Class G, mixed at 15.8 ppg w/ a 1.15 cf/sx yield. The stabilizing wellbore fluid will be an 8.3 ppg fluid, sufficient to balance all exposed formation pressures.

- 1. This project will use a steel tank to handle waste fluids circulated from the well and cement wash up.
- 2. Test anchors if not using a base beam. Comply with all NMOCD, BLM, and HEC safety regulations. MIRU and conduct safety meeting for all personnel on location.
- 3. Record casing, tubing, and bradenhead pressures. NU relief line and blow down well. Kill well with water as necessary. Ensure well is dead or on a vacuum.
- 4. ND wellhead and NU BOP, rig up 1.5" coil unit
- 5. Plug #1, 1908' 1858' (Fruitland Top:1608') EXISTING CIBP AT 1908'. RIH with coil and tag top of CIBP.
- 6. Establish circulation and spot 0.75bbls of cement on CIBP
- 7. Circulate 25bbl. of plug mud above cement
- 8. POOH to 950'
- 9. Plug #2, 950' 850' (Kirtland Top: 1000' Ojo Alamo Top:926') Spot 1.6 bbls of cement. POOH to 140'
- 10. Plug #3, 175' Surface (Surface Shoe: 139') Circulate cement (~2.8 bbl.) to surface.

11. ND BOP and cut off wellhead below surface casing flange per regulation. Top off w/cement if needed. Install P&A marker with cement to comply with regulations. RD, MOL and cut off anchors. Restore location.





Hilcorp Energy
P&A Final Reclamation Plan
Garrett Com 100S
API: 30-045-34835
T29N-R011W-Sec. 12-Unit H
LAT: 36.74176 LONG: -107.93642 NAD 27

Footage: 2069' FNL & 898' FEL San Juan County, NM

1. PRE- RECLAMATION SITE INSPECTION

A pre-reclamation site inspection was completed with Bob Switzer from the BLM and Eufracio Trujillo, Hilcorp Energy SJ South Construction Foreman on September 20, 2021.

2. LOCATION RECLAMATION PROCEDURE

- 1. Reclamation work will begin in summer/fall time period.
- 2. Removal of all equipment, anchors, cathodic protection, T-blocks, and flowlines.
- 3. Spray entire location for Halogeton.
- 4. All trash and debris will be removed within a 50' buffer outside of the location disturbance during reclamation.
- 5. Rip compacted soil and walk down entire well pad.
- 6. Remove pipe and debris off of side of location.
- 7. Push in fill side on the Southeastern and South edges and push into cut side on North side of location to recontour close to natural surroundings.
- 8. Remove all gravel from berms, pads, and meter run.
- 9. Enterprise needs to remove line from location to dogleg.
- 10. P&A cathodic well.

3. ACCESS ROAD RECLAMATION PROCEDURE

- 1. The well access road will be blocked at the main lease road with a berm.
- 2. Reclaim road by ripping and broadcast seeding.
- 3. Remove culvert from road.
- 4. Insert small water bars for erosion control down road to help with runoff.

4. SEEDING PROCEDURE

- 1. A Pinion/Juniper seed mix mixed with some sage will be used for all reclaimed and disturbed areas of the well pad and lease road.
- 2. Drill seed will be done where applicable, and all other disturbed areas will be broadcast seeded and harrowed. Broadcast seeding will be applied at a double the rate of seed.
- 3. Timing of the seeding will be when the ground is not frozen or saturated.

5. WEED MANAGEMENT

1. Halogeton was identified during this onsite. We will spray entire location before we rip and push location.

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon

Re: Permanent Abandonment Well: Garrett Com 100S

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.
- 3. The following modifications to your plugging program are to be made:
 - a) Plug 1: Add a plug, or extend plug 1, to cover the Fruitland formation top at 1608 feet.
 - b) Plug 2: Adjust plug to cover the interval from 1055 to 876 feet the Kirtland and Ojo Alamo formation tops.
 - c) Plug 3: Confirm the location of the surface casing shoe. The procedure has 139 feet depth, while the schematic and other wellbore data has the shoe has 125 feet. If indeed 125 feet, no modifications. If 139 feet, the plug will need to be adjusted to be 50 feet below surface casing depth.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.

K. Rennick 10/21/2021

BLM FLUID MINERALS P&A Geologic Report

Date Completed: 10/21/2021

Well No. Garrett Com #100S (API# 30-045-34835)			Location	2069	FNL	&	898	FEL
Lease No. NMNM03717B			Sec. 12	T29N			R11W	
Operator Hilcorp Energy Company		County	San Juan		State	New Mexico		
Total Depth	2346'	PBTD 2288'	Formation	Fruitland	l			
Elevation (GL) 5802'			Elevation (KI	Elevation (KB) 5813'				

Geologic Formations	Est. Top	Est. Bottom	Log Top	Log Bottom	Remarks
San Jose Fm					
Nacimiento Fm			Surface	926	Fresh water sands
Ojo Alamo Ss			926	1005	Aquifer (fresh water)
Kirtland Shale			1005	1608	
Fruitland Fm			1608	2127	Coal/Gas/Possible water
Pictured Cliffs Ss			2127	PBTD	Gas
Lewis Shale					
Chacra (La Ventana)					
Cliff House Ss					Water/Possible gas
Menefee Fm					Coal/Ss/Water/Possible O&G
Point Lookout Ss					Probable water/Possible O&G
Mancos Shale					
Gallup					O&G/Water
Greenhorn					
Graneros Shale					
Dakota Ss					O&G/Water

Remarks:

P & A

- BLM pick for the Kirtland formation top varies slightly from operator pick.

- No CBL on file.
- Add a plug, or extend Plug #1, to cover the Fruitland formation top @ 1608'.
- Adjust Plug #2 to cover the interval from 1055' 876' to cover the Kirtland and Ojo Alamo formation tops.
- Bring the bottom of Plug #3 (surface shoe) down to 189' to cover 50' below the shoe @ 139'.
- The plugs proposed in the P&A procedure, with adjustments recommended above, will adequately protect any freshwater sands in this well bore.
- Fruitland coal perfs @ 1964' 2104'. CIBP @ 1908'.

Reference Well:

1) Formation Tops

Same

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

COMMENTS

Action 57975

COMMENTS

Operator:	OGRID:
HILCORP ENERGY COMPANY	372171
1111 Travis Street	Action Number:
Houston, TX 77002	57975
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

COMMENTS

Created By	Comment	Comment Date		
kpickford	KP GEO Review 11/4/2021	11/4/2021		

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 57975

CONDITIONS

On another:	OGRID:
Operator:	
HILCORP ENERGY COMPANY	372171
1111 Travis Street	Action Number:
Houston, TX 77002	57975
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

CONDITIONS

Created By	Condition	Condition Date	
kpickford	Notify NMOCD 24 Hours Prior to beginning operations	11/4/2021	
kpickford	Adhere to BLM approved plugs	11/4/2021	