U.S. Department of the Interior BUREAU OF LAND MANAGEMENT

Well Number: 4

Sundry Print Rego

Well Name: LOCO HILLS SWD 33 Well Location: T17S / R30E / SEC 33 / County or Parish/State: EDDY /

SESE /

Allottee or Tribe Name:

Unit or CA Number:

Type of Well: OTHER

Unit or CA Name:

US Well Number: 3001537269 Well Status: Water Disposal Well **Operator: SPUR ENERGY**

PARTNERS LLC

Notice of Intent

Lease Number: NMLC028936D

Sundry ID: 2678531

Type of Submission: Notice of Intent Type of Action: Workover Operations

Date Sundry Submitted: 06/23/2022 Time Sundry Submitted: 01:51

Date proposed operation will begin: 07/01/2022

Procedure Description: This well has a suspected hole in tubing or packer leak due to equalized pressure of 1,700 lbs on the casing and tubing. It is proposed to pull and hydrotest tubing and replace any leaking joints. It is also proposed to run a new packer if a leak is detected. The well was last pulled in 2021 for a hole in tubing; 1 bad joint was found. Packer was not pulled. Please find procedure and WBDs attached for your use.

Surface Disturbance

Is any additional surface disturbance proposed?: No

NOI Attachments

Procedure Description

Loco_Hills_33__4_SWD___HIT_Packer_Leak_Procedure_20220623135105.pdf

Loco_Hills_33__4_WBD_20220623135105.pdf

eceived by OCD: 7/6/2022 7:24:20 AM Well Name: LOCO HILLS SWD 33

Well Location: T17S / R30E / SEC 33 /

SESE /

County or Parish/State: EDD 2 20

NM

Well Number: 4

Type of Well: OTHER

Allottee or Tribe Name:

Lease Number: NMLC028936D

Unit or CA Name:

Unit or CA Number:

US Well Number: 3001537269

Well Status: Water Disposal Well

Operator: SPUR ENERGY PARTNERS LLC

Conditions of Approval

Specialist Review

Workover_or_Vertical_Deepen_COA_20220705155440.pdf

Operator

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a

Operator Electronic Signature: SARAH CHAPMAN Signed on: JUN 23, 2022 01:51 PM

Name: SPUR ENERGY PARTNERS LLC

Title: Regulatory Directory

Street Address: 9655 KATY FREEWAY, SUITE 500

City: Houston State: TX

Phone: (832) 930-8613

Email address: SCHAPMAN@SPUREPLLC.COM

Field

Representative Name:

Street Address:

City:

State:

Zip:

Phone:

Email address:

BLM Point of Contact

BLM POC Name: Jonathon W Shepard

BLM POC Phone: 5752345972

Disposition: Approved

Signature: Jonathon Shepard

BLM POC Title: Petroleum Engineer

 $\textbf{BLM POC Email Address:} \ jshepard@blm.gov$

Disposition Date: 07/05/2022

Accepted for Record

PRG

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Conditions of Approval for Workover/Deepening of a Well

- 1. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any operations. For wells in Eddy County, call 575-361-2822. For wells in Lea County, call 575-689-5981
- 2. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,100 feet, a 3M system for a well not deeper than 13,600 feet, or a 5M system for a well not deeper than 22,700 feet (all depths are for measured well depth).
- 3. Cement: Notify BLM if cement fails to circulate.
- 4. <u>Subsequent Reporting:</u> Within 30 days after work is completed, file a Subsequent Report (Form 3160-5) to BLM. The report should give in detail the manner in which the work was carried out. <u>Show date work was completed</u>. If producing a new zone, submit a Completion Report (Form 3160-4) with the Subsequent Report.
- 5. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.
- 6. If well location is within the Timing Limitation Stipulation Area for Lesser Prairie-Chicken: From March 1st through June 15th annually, activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted.

LOCO HILLS SWD #4

API# 30-015-37269 Laurel Marsh 832-646-8568

Hole in Tubing / Packer Leak Procedure

Objective

This well has a suspected hole in tubing or packer leak due to equalized pressure of 1,700 lbs on the casing and tubing. It is proposed to pull and hydrotest tubing and replace any leaking joints. It is also proposed to run a new packer if a leak is detected. The well was last pulled in 2021 for a hole in tubing; 1 bad joint was found. Packer was not pulled.

Summary


- RIH w/ plug on slickline and test tbg to 1,000 psi
- If tubing does not test, get off O/O tool and POOH
- If tubing does test, POOH with tubing and packer
- RBIH while hydrotesting tubing to 5,000 lbs below slips
- Set packer, get off O/O tool, circulate packer fluid and test backside to 500 psi for 15 minutes


Procedure

- 1. <u>Notification</u>: Contact the appropriate BLM and OCD office at least 24 hours prior to the commencing of any operations.
- 2. MIRU SLU
- 3. RIH w gauge ring. POOH.
- 4. RIH w/ 2.31" R plug and set in profile nipple @ +/- 8,466'. POOH.
- 5. RDMO SLU
- 6. Test tubing to 1,000 psi. If pressure on tubing and casing equalize, pull just tubing. If tubing pressure holds, pull tubing and packer.
- 7. Move in rig up pulling unit
- 8. Nipple up BOP.
 - →If tubing failed, Release O/O Tool Overshot & POOH w/ 3-1/2" L-80 tubing.
 - →If Packer failed POOH w/ 3-1/2" L-80 tubing and packer.

	Description uction Tubing	Set Depth (ftKB) 8,481.0			Run Date 3/31/2010							
Tul	Tubing Components											
Jts	Item Des	OD (in)	ID (in)	Wt (lb/ft)	Grade	Top Thread	Top Connection Type	Len (ft)	Cum Len (ft)	Top (ftKB)	Btm (ftKB)	Incl Max
								12.96	8,481.00	0.0	13.0	
269	TUBING	3 1/2	2.99	9.30	L-80	8RND		8,451.90	8,468.04	13.0	8,464.9	
	ON/OFF TOOL	2 7/8						1.50	16.14	8,464.9	8,466.4	0.62
	NO-GO NIPPLE	2 7/8						1.00	14.64	8,466.4	8,467.4	0.62
	PRODUCTION PACKER	7						6.10	13.64	8,467.4	8,473.5	0.62
	PUP JOINT	2 7/8						6.00	7.54	8,473.5	8,479.5	0.62
	NO-GO NIPPLE	2 7/8						1.00	1.54	8,479.5	8,480.5	0.62
	WIRELINE RE-ENTRY GUIDE	2 7/8						0.54	0.54	8,480.5	8,481.0	0.62

- 9. RBIH hydrotesting to 5k below the slips. Replace any failed joints w new. If packer was leaking, replace with new 2-7/8 10K Arrowset packer.
- 10. Engage on/off tool and pressure test casing to 1,000 psi for 15 min
- 11. Get off on/off tool. Circulate packer fluid
- 12. Nipple up wellhead. Pressure up on tubing and pump out plug.
- 13. Rig down pulling unit.
- 14. Notify BLM & NMOCD to witness MIT.
 - a) Loco Hills Sr Foreman: JP Hermes 575.703.6218
 - b) BKU SWD Tech: Brian Thompson 575.703.4565
 - c) SWD Foreman: Hilario Jimenez 575.703.4925





District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 122936

CONDITIONS

Operator:	OGRID:
Spur Energy Partners LLC	328947
9655 Katy Freeway Houston, TX 77024	Action Number: 122936
	Action Type: [C-103] NOI Workover (C-103G)

CONDITIONS

Created By	Condition	Condition Date
pgoetze	Operator shall provide notice to the OCD 48 hours in advance of conducting the required MIT for the opportunity to witness the test	7/13/2022