eceined by Och: Appropriate Daile: 59 I	Blate of flew ivi		Form C-1831 of
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Nat	ural Resources	Revised July 18, 2013 WELL API NO. 30-025-30565
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210 District III – (505) 334-6178	OIL CONSERVATION 1220 South St. Fra		5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460	Santa Fe, NM 8		STATE FEE X 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			326998
SUNDRY NOTION (DO NOT USE THIS FORM FOR PROPOS.	CES AND REPORTS ON WELL ALS TO DRILL OR TO DEEPEN OR PI		7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION PROPOSALS.)	ATION FOR PERMIT" (FORM C-101) F	FOR SUCH	Maxwell Trust 26
2. Name of Operator	Gas Well X Other		8. Well Number 1 9. OGRID Number
- Catena R	esources Operating, LLC		6137
3. Address of Operator 1001 Fannin S	Street, STE 2200, Housto	n TX 77002	10. Pool name or Wildcat 76360 Eidson Morrow, North (G)
4. Well Location Unit Letter E:	1980 feet from the Nor	th 6	660 feet from the West line
Unit Letter <u> </u>		un line and 6 lange 34E	NMPM Lea County NM
Section 20	11. Elevation (Show whether DI	U	y 1 1111
	4068' GL - 4085' KB		
12. Check A	ppropriate Box to Indicate N	Nature of Notice,	Report or Other Data
NOTICE OF IN	ΓΕΝΤΙΟΝ ΤΟ:	l l	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK TEMPORARILY ABANDON	PLUG AND ABANDON CHANGE PLANS □	REMEDIAL WORK	_
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	
DOWNHOLE COMMINGLE			
CLOSED-LOOP SYSTEM OTHER:		OTHER:	
			d give pertinent dates, including estimated date
of starting any proposed wor proposed completion or reco		.C. For Multiple Cor	mpletions: Attach wellbore diagram of
(1) MIRU WOR. POOH w/ tubing. MIR	ong: 32.939991 / -103.459625 (NAD83) RU WL. RIH and set CIBP ~ 11,850'. D	ump bail ~35' class 'H' c	
(2) Spot 26 sxs class 'H' cement from	of first plug ~11,850'. RU pump and cir 9,840' to 9,640'. (Top of Wolfcamp ~9,	840') Plug #2.	
(4) Attempt to freepoint and cut 5-1/2"	8,097' to 7,897'. (Top of Abo ~7,997') casing and recover as much as possil	ole. Estimate cut around	
(5) Spot 65 sxs class 'C' cement from	will perf and squeeeze 5-1/2" casing f 6,100' to 5,895'. WOC 4 hrs. Tag and	spot more cement as ne	eeded. Plug #4
(7) Spot 65 sxs class 'C' cement from	4,880' to 4,680'. WOC 4 hrs. Tag and	spot more cement as ne	eeded. (Top of Glorieta ~5,696') Plug #5 eeded. (8-5/8" shoe at 4,780') Plug #6.
(9) Spot 65 sxs class 'C' cement from		spot more cement as ne	eeded. (Top of Yates ~2,910') Plug #7 eeded. (Top of Salado ~1,790') Plug #8
(11) Cut off casings 3' below ground le	om 517' to 0'. (13-3/8" shoe at 492') Plu evel. Visually verify cement top. Top of		
(12) Set dry hole marker per requirem		attached	conditions of approval
Spud Date: 03/21/1989	Rig Release D		
4" Diameter 4' tall above	e ground marker		
I hereby certify that the information a	bove is true and complete to the b	est of my knowledge	e and belief.
SIGNATURE Karen Zor	nsstitle_Re	gulatory Consulta	ant DATE 08/12/2022
Type or print name <u>Karen Zorne</u>		ss: <u>kzornes@ntg</u> l	lobal.com PHONE: 281-872-9300
For State Use Only	-		s
APPROVED BY: Yeary for Conditions of Approv	unerTITLE_ Co	mpliance Office	in ADATE_9/15/22

CONDITIONS OF APPROVAL FOR PLUGGING AND ABANDONMENT OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office I (Hobbs) at (575)-263-6633 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down.

Company representative will be on location during plugging procedures.

- **1.** A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.
- **2.** Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- **3.** Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private- shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- **5.** A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can +be released.
- **6.** If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
- 7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- **8.** Produced water will not be used during any part of the plugging operation.
- 9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
- **10.** All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 11. Class 'C' cement will be used above 7500 feet.
- 12. Class 'H' cement will be used below 7500 feet.
- **13.** A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- **14.** All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.
- **16.** When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
- 17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
- **18.** A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).

- 19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
- 20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
- A) Fusselman
- B) Devonian
- C) Morrow
- D) Wolfcamp
- E) Bone Springs
- F) Delaware
- G) Any salt sections
- H) Abo
- I) Glorieta
- J) Yates.
- K) Potash---(In the R-111-P Area (Potash Mine Area),

A solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.

21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing.

DRY HOLE MARKER REQ.UIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

- 1. Operator name
- 2. Lease and Well Number
- 3. API Number
- 4. Unit letter
- 5. Quarter Section (feet from the North, South, East or West)
- 6. Section, Township and Range
- 7. Plugging Date
- 8. County

SPECIAL CASES ----AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION

BIT SZ.

17-1/2"

BIT SZ.

12-1/4"

BIT SZ.

7-7/8"

SX CMT.

545

SX CMT.

1,655

SX CMT.

1,190

BH TEMP:

KB ELEVATION:

GL ELEVATION:

TOP CMT.

TOP CMT

0'

TOP CMT

SURFACE LAT/LONG:

TD:

TVD:

PBTD:

~205

12,467'

12,467'

12,214'

4,085.0'

4,068.0'

COMMENT

COMMENT

COMMENT

MD (KB)

TVD (KB)

MD (KB)

* Circ 147 sxs to surf, 545 sxs Class 'C'

* Circ 184 sxs to surf, 1,455 sxs 'C', 200 sxs 'C'

Cmt: 350 sxs 'H', 840 sxs 'H' *Reported TOC per CBL

NOTES

(17.0' KB)

32.939991 / -103.459625 (NAD83)



WELL: MAXWELL TRUST 26 1 FORMATION: MORROW, CHESTER 20" @ 60' (MD) **OPERATOR:** Catena Resources Operating, LLC **SPUD DATE**: 1/13/2001 COUNTY: Lea STATE: New Mexico 13-3/8" @ 492' (MD) **API**: 30-025-30565 **LEASE**: 326998 **LOCATION:** U/L: G, Section: 06, Township: 16S, Range: 35E (G-06-16S-35E) FIELD: SHOE BAR; ATOKA, NORTH (GAS) CASING RECORD SURFACE CASING WT./FT. GRADE THD TOP втм O.D. 20" 60' 13-3/8" H-40 STC 492' 48# INTERMEDIATE CASING GRADE THD TOP BTM LTC 8-5/8" K-55 4,780' 32# 0' **PRODUCTION CASING / LINER** GRADE O.D. WT./FT. THD TOP BTM 5-1/2" 17# P-110, S-95 LTC 12,466' PERFORATION & PLUGBACK RECORD BOTTOM INTERVAL ZONE - Stage DATE COMMENTS 8-5/8" @ 4,780' (MD) TOP Perfs: 11,910'-11,932' (TCP, 6 SPF) **ATOKA** 11,910 11,932 22' 5/1/2001 Stimulation: Frac: 49,700 gals 70Q Binary Foam, 46,500 lbs 20/40 Interprop CIBP w/ 36' cmt 12,214 12,250 CIBP w/ 36' cmt cap: CIBP at 12,250', TOC at 12,214' 36' 3/21/2001 Perfs: 4" guns, 4 SPF **LWR AUSTIN** 12,312 12,324 12' 3/14/2001 **Stimulation:** Acidize with 1,500 gals 15% NEFE acid. No Pressure BU or fluid entry. TUBING DETAIL 5-1/2" TOC @ 6,920' **Tubing Detail** Top Depth **Bottom Depth** KB Adjustment (used for WOR tally) (Jnt Count) 15.00' 15.0' 2-3/8" 4.7# N-80 8rd EUE tbg 32.15' 15.0' 47.2' 2-3/8" 4.7# N-80 sub 4.10' 47.2' 51.3' 2-3/8" 4.7# N-80 8rd EUE tbg 12,856.97' 51.3' 12,908.2' 1.71' On-Off Tool (w/ 1.781 'F' profile) 12,908.2' 12,909.9' 5-1/2" x 2-3/8" AS-1X Pkr 5.49' 12,909.9' 12,915.4' 2-3/8" 4.7# N-80 sub 10.28 12,915.4 12,925.7' F' Profile Nipple (2-3/8", 1.781" ID) 0.90' 12,925.7' 12,926.6' WLREG - 2-3/8" 0.41' 12,926.6' 12,927.0' DATE INSTALLED: 05-08-2002 Well was on Plunger Lift in the past, not sure of current PL equipment status 2-7/8" Tbg Lengths based at: **ACTUALS** EOT: 2-3/8" Tbg Lengths based at: Tubing Totals Footage Joints Avg Jnt 2-7/8" 6.5# L-80 8rd EUE tbg 2-3/8" 4.7# N-80 8rd EUE tbg 12,889.1 31.75' 406.0 12,889.1' 406.0 31.75' Atoka Perfs: Lwr TCP Assembly Top at ~12,050' (Spacer of 1 jnt 2-3/8" tbg, Mech. Firing Head, TCP Gun Assembly) CIBP w/ 36' cmt cap: CIBP at 12,250', TOC at 12,214' Lower Austin Perfs: 12,312'- 12,324' 5-1/2" @ 12,466' (MD) TD @ 12,467' (MD) PBTD @ 12,214' (MD) (12,467' TVD) **Updated:** 5/2/2022 SCB

CURRENT

Released to Imaging: 9/16/2022 7:15:22 AM



Plug #8

Plug #7

Plug #6

Plug #5

Plug #4


Plug #3

Plug #2

* '8-5/8" @ 4,780' (MD)

20" @ 60' (MD)

13-3/8" @ 492' (MD)



CASING RECORD
OADING KEDOKE

URFACE	CASING

O.D.	WT./FT.	GRADE	THD	TOP	BTM	BIT SZ.	SX CMT.	TOP CMT.	COMMENT
20"	=	-	=	0'	60'	=	=	-	
13-3/8"	48#	H-40	STC	0'	492'	17-1/2"	545	0'	* Circ 147 sxs to surf, 545 sxs Class 'C'

INTERMEDIATE CASING

O.D.	WT./FT.	GRADE	THD	TOP	BTM	BIT SZ.	SX CMT.	TOP CMT	COMMENT
8-5/8"	32#	K-55	LTC	0'	4,780'	12-1/4"	1,655	0'	* Circ 184 sxs to surf, 1,455 sxs 'C', 200 sxs 'C'

PRODUCTION CASING / LINER

O.D.	WT./FT.	GRADE	THD	TOP	втм	BIT SZ.	SX CMT.	TOP CMT	COMMENT
5-1/2"	17#	P-110, S-95	LTC	0'	12,466'	7-7/8"	1,190	6,920'	Cmt: 350 sxs 'H', 840 sxs 'H' *Reported TOC per CBL

	PERFORATION & PLUGBACK RECORD									
ZONE - Stage	TOP	воттом	INTERVAL	DATE	COMMENTS	NOTES				
		1	1	I	T					
ATOKA	11,910	11,932	22'	5/1/2001	Perfs: 11,910'-11,932' (TCP, 6 SPF) Stimulation: Frac: 49,700 gals 70Q Binary Foam, 46,500 lbs 20/40 Interprop					
CIBP w/ 36' cmt	12,214	12,250	36'	3/21/2001	CIBP w/ 36' cmt cap: CIBP at 12,250', TOC at 12,214'					
LWR AUSTIN	12,312	12,324	12'	3/14/2001	Perfs: 4" guns, 4 SPF Stimulation: Acidize with 1,500 gals 15% NEFE acid. No Pressure BU or fluid entry.					

	TUBIN	G DETAIL		
Tubing Detail		<u>Length</u>	Top Depth	Bottom Depth
				1
2.7/0 They I amouth a hoose ! - !		ACTUALS	FOT	
2-7/8" Tbg Lengths based at:		ACTUALS	EOT:	
2-3/8" Tbg Lengths based at:		ACTUALS		
Tubing Totals	Footage	Joints	Avg Jnt	
2-7/8" 6.5# L-80 8rd EUE tbg				
2-3/8" 4.7# N-80 8rd EUE tbg				
	0.0'	0.0		

Atoka Perfs: 11,910'- 11,932'

Lwr TCP Assembly Top at ~12,050' (Spacer of 1 jnt 2-3/8" tbg, Mech. Firing Head, TCP Gun Assembly)

CIBP w/ 36' cmt cap: CIBP at 12,250', TOC at 12,214'

Lower Austin Perfs: 12,312'- 12,324'

5.5" at 12,466' MD

PBTD @ 12,214' (MD) (12,467' TVD)

Updated: 8/7/2022 HDS

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

COMMENTS

Action 133654

COMMENTS

Operator:	OGRID:
Catena Resources Operating, LLC	328449
1001 Fannin Street	Action Number:
Houston, TX 77002	133654
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

COMMENTS

(Created By	Comment	Comment Date
	plmartinez	DATA ENTRY PM	9/16/2022

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 133654

CONDITIONS

Operator:	OGRID:
Catena Resources Operating, LLC	328449
1001 Fannin Street	Action Number:
Houston, TX 77002	133654
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

CONDITIONS

Created By		Condition Date
kfortner	See attached COA	9/15/2022