

U.S. Department of the Interior BUREAU OF LAND MANAGEMENT

Sundry Print Report

Well Name: NATANI Well Location: T21N / R6W / SEC 14 /

NENW / 36.055025 / -107.442238

County or Parish/State:

SANDOVAL / NM

Well Number: 10 Type of Well: CONVENTIONAL GAS

WELL

Allottee or Tribe Name:

Unit or CA Name:

Unit or CA Number:

US Well Number: 3004320613

Lease Number: NMNM17007

Well Status: Producing Gas Well

Operator: M & M PRODUCTION

& OPERATION

Notice of Intent

Sundry ID: 2699958

Type of Submission: Notice of Intent

Type of Action: Plug and Abandonment

Date Sundry Submitted: 10/27/2022 Time Sundry Submitted: 10:25

Date proposed operation will begin: 08/01/2023

Procedure Description: See attached. DJR Operating, LLC/ DJR Nominee Corporation is submitting the NOI to Abandon as the Record Title Owner of Lease NMNM17007.

Surface Disturbance

Is any additional surface disturbance proposed?: No

Oral Submission

Oral Notification Date: Sep 23, 2022

Oral Notification Time:

12:00 AM

Contacted By:

Shaw-Marie Ford

Contact's Email:

sford@djrllc.com

Comments:

Submitted paper copy because DJR Operating, LLC is not the operator in AFMSS 2. Only

the record title owner of the lease.

NOI Attachments

Procedure Description

NMNM17007_Natani_010_3004320613_NOIA_09232022_20221027102500.pdf

FINAL SURVEYS - CIMAREX ARMACOST 6-33H GYRO + MWD TO 17707FT.PDF

ARMACOST 6-33H 1002A.PDF

CEMENT REPORTS.PDF

Well Location: T21N / R6W / SEC 14 / County or Parish/State: Page 2 of

NENW / 36.055025 / -107.442238 SANDOVAL / NM

Well Number: 10 Type of Well: CONVENTIONAL GAS Allottee or Tribe Name:

MELL

Lease Number: NMNM17007 Unit or CA Name: Unit or CA Number:

US Well Number: 3004320613 Well Status: Producing Gas Well Operator: M & M PRODUCTION

& OPERATION

Conditions of Approval

Additional

21N06W14CKmv_Natani_010_20221108135618.pdf

Authorized

2699958_NOIA_10_3004320613_KR_11092022_20221109122448.pdf NMNM17007_NOIA_10_NOIA_APPROVED_11092022_20221109122442.pdf

General_Requirement_PxA_20221109122435.pdf

BLM Point of Contact

BLM POC Name: KENNETH G RENNICK

BLM POC Title: Petroleum Engineer

BLM POC Phone: 5055647742 BLM POC Email Address: krennick@blm.gov

Disposition: Approved **Disposition Date:** 11/09/2022

Signature: Kenneth Rennick

Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED OMB No. 1004-0137 Expires: January 31, 2018

5. Lease Serial No. NMNM17007	
6. If Indian, Allottee or Tribe Name	

Do not use this f		ORTS ON WELLS o drill or to re-enter an PD) for such proposals.		6. If Indian, Allottee or	Tribe Name
SUBMIT IN 1	TRIPLICATE - Other instru	uctions on page 2		7. If Unit of CA/Agreen	nent, Name and/or No.
1. Type of Well Oil Well Gas W	/ell Other			8. Well Name and No.	
2. Name of Operator DJR OPERATIN	IG, LLC			9. API Well No. 30-043	3-20613
3a. Address 1 ROAD 3263 AZTEC, NM 87410	1000	3b. Phone No. (include area code) (505) 632-3476		10. Field and Pool or Ex Rusty Chacra	xploratory Area
4. Location of Well (Footage, Sec., T., F 800' FNL x 1800' FWL / C-14-21N				11. Country or Parish, S Sandoval County, N	
12. CHE	CK THE APPROPRIATE B	OX(ES) TO INDICATE NATURE O	F NOTI	CE, REPORT OR OTHI	ER DATA
TYPE OF SUBMISSION		ТҮРЕ	OF AC	ΓΙΟΝ	
✓ Notice of Intent	Acidize Alter Casing	Deepen Hydraulic Fracturing	=	uction (Start/Resume) amation	Water Shut-Off Well Integrity
Subsequent Report	Casing Repair Change Plans	New Construction ✓ Plug and Abandon		omplete porarily Abandon	Other
Final Abandonment Notice	Convert to Injection			er Disposal	
the Bond under which the work will	ally or recomplete horizontal ill be perfonned or provide the ons. If the operation results in	ly, give subsurface locations and means to Bond No. on file with BLM/BIA. It is a multiple completion or recomplet	asured ar Required tion in a	nd true vertical depths of subsequent reports mus new interval, a Form 31	all pertinent markers and zones. Attaci

This request is being submitted for engineering & geological review prior to on site inspection as approved by Dave M. of the BLM. DJR Operating, LLC requests permission to Plug & Abandon the subject well according to the attached Procedure, Current & Proposed Wellbore Diagram.

Received

SEP 2 3 2022

Farmington Field Office Bureau of Land Management

. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) haw-Marie Ford Regulatory Specialist Title				
Signature Shaw-Maria Ford	Date		09/21/2022	
THE SPACE FOR FEDE	RAL OR	STATE OFICE USE		
Approved by Hensett Kensull Conditions of approval, if any, are attached. Approval of this notice does not warrant of	Title	ETROLE UM EUGINEER FARMINGTON	Date FIELD	09 2022
certify that the applicant holds legal or equitable title to those rights in the subject leas which would entitle the applicant to conduct operations thereon.	e Office	OFFICE		C.1. V. 1. 10

Title 18 U.S.C Section 1001 and Title 43 U.S.C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

Plug and Abandonment Procedure

for

DJR Operating, LLC

Natani #010

API # 30-043-20613

NW/NE, Unit C, Sec. 14, T21N, R6W

Sandoval County, NM

- 1. Hold pre-job meeting, comply with all NMOCD, BLM and environmental regulations.
- 2. Check and record tubing, casing and bradenhead pressures.
- 3. Remove existing piping from casing valve, RU blow lines from casing valves and blow down casing pressure. Kill well as necessary. Ensure that well is dead or on a vacuum.
- 4. ND WH, NU BOP, function test BOP.
- 5. Trip out of hole with 2 3/8" tubing. LD tubing to be sent in for storage/salvage.
- 6. PU workstring, TIH with bit and scraper, make sure that the bit and scraper will go below 1450'. TOOH.
- 7. PU and TIH with 4-1/2" CR and set near 1450'. Pressure test tubing to 1000 psi. Sting out of CR. Roll hole Pressure test casing to 600 psi. TOOH.
- 8. Plug 1: Chacra: Sting back into CR and attempt to squeeze below with 10 sx. Sting out and spot plug on top of CR to bring TOC to 1400'. Pump water to ensure tubing is clear. TOOH.
- 9. Plug 2: Pictured Cliffs, Fruitland, Kirtland, and Ojo Alamo: Spot balanced plug from 1111-510'. Pump water to ensure tubing is clear. TOOH.
- 10. Plug 3. Nacimiento, surface casing shoe and surface: Spot balanced plug from 286' to surface.
- 11. RD cementing equipment. Cut off wellhead, fill annuli with cement, as necessary.

 Install SURFACE P&A marker as per BLM/OCD requirements. Record GPS coordinates for P&A marker and the final P&A report. Photograph the P&A marker and attach to the report.


- 12. RD and MO all rig and cement equipment. Assure that location is free of trash before moving off.
- 13. Send all reports and attachments to DJR Aztec office for regulatory filings.

Note: All cement is to be Class G mixed at 15.8 ppg yield 1.15 cu. Ft./sk. Cement volumes are based on inside capacities +50' and outside capacities + 100% excess.

DJR Operating, LLC Current Wellbore Diagram Natani 10

API # 30-043-20613 NW/NE, Unit C, Sec 14, T21N, R6W Sandoval County, NM

GL 6918' KB 6928' Spud Date 6/22/1982




Production Tubing Detail

2-3/8" tubing landed at 1521'

DJR Operating, LLC Proposed Wellbore Diagram Natani 10

API # 30-043-20613 NW/NE, Unit C, Sec 14, T21N, R6W Sandoval County, NM

GL 6918' KB 6928' Spud Date 6/22/1982



UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

AFMSS 2 Sundry ID 2699958

Attachment to notice of Intention to Abandon

Well: Natani 10

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence at (505) 564-7750.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.

K. Rennick 11/9/2022

GENERAL REQUIREMENTS FOR PERMANENT ABANDONMENT OF WELLS ON FEDERAL AND INDIAN LEASES FARMINGTON FIELD OFFICE

- 1.0 The approved plugging plans may contain variances from the following <u>minimum general</u> requirements.
 - 1.1 Modification of the approved plugging procedure is allowed only with the prior approval of the Authorized Officer, Farmington Field Office.
 - 1.2 Requirements may be added to address specific well conditions.
- 2.0 Materials used must be accurately measured. (densometer/scales)
- 3.0 A tank or lined pit must be used for containment of any fluids from the wellbore during plugging operations and all pits are to be fenced with woven wire. These pits will be fenced on three sides and once the rig leaves location, the fourth side will be fenced.
 - 3.1 Pits are not to be used for disposal of any hydrocarbons. If hydrocarbons are present in the pit, the fluids must be removed prior to filling in.
- 4.0 All cement plugs are to be placed through a work string. Cement may be bull-headed down the casing with prior approval. Cement caps on top of bridge plugs or cement retainers may be placed by dump bailer.
 - 4.1 The cement shall be as specified in the approved plugging plan.
 - 4.2 All cement plugs placed inside casing shall have sufficient volume to fill a minimum of 100' of the casing, or annular void(s) between casings, plus an excess volume sufficient to provide for 50 linear feet of fill above the plug.
 - 4.3 Surface plugs may be no less than 50' in length.
 - 4.4 All cement plugs placed to fill annular void(s) between casing and the formation shall be of sufficient volume to fill a minimum of 100' of the annular space plus 100% excess, calculated using the bit size, or 100' of annular capacity, determined from a caliper log, plus an excess volume sufficient to provide for 50 linear feet of fill above the plug.
 - 4.5 All cement plugs placed to fill an open hole shall be of sufficient volume to fill a minimum of 100' of hole, as calculated from a caliper log, plus an excess volume sufficient to provide for 50 linear feet of fill above the plug. In the absence of a caliper log, an excess of 100% shall be required.
 - 4.6 A cement bond log or other accepted cement evaluation tool is required to be run if one had not been previously ran or cement did not circulate to surface during the original casing cementing job or subsequent cementing jobs.

2

- 5.0 All cement plugs spotted across, or above, any exposed zone(s), when; the wellbore is not full of fluid or the fluid level will not remain static, and in the case of lost circulation or partial returns during cement placement, shall be tested by tagging with the work string.
 - 5.1 The top of any cement plug verified by tagging must be at or above the depth specified in the approved plan, without regard to any excess.
 - 5.2 Testing will not be required for any cement plug that is mechanically contained by use of a bridge plug and/or cement retainer, if casing integrity has been established.
 - 5.3 Any cement plug which is the only isolating medium, for a fresh water interval or a zone containing a prospectively valuable deposit of minerals, shall be tested by tagging.
 - 5.4 If perforations are required below the surface casing shoe, a 30 minute minimum wait time will be required to determine if gas and/or water flows are present. If flow is present, the well will be shut-in for a minimum of one hour and the pressure recorded. Short or long term venting may be necessary to evacuate trapped gas. If only a water flow occurs with no associated gas, shut well in and record the pressures. Contact the Engineer as it may be necessary to change the cement weight and additives.
- 6.0 Before setting any cement plugs the hole needs to be rolled. All wells are to be controlled by means of a fluid that is to be of a weight and consistency necessary to stabilize the wellbore. This fluid shall be left in place as filler between all plugs.
 - 6.1 Drilling mud may be used as the wellbore fluid in open hole plugging operations.
 - 6.2 The wellbore fluid used in cased holes shall be of sufficient weight to balance known pore pressures in all exposed formations.
- 7.0 A blowout preventer and related equipment (BOPE) shall be installed and tested prior to working in a wellbore with any exposed zone(s); (1) that are over pressured, (2) where the pressures are unknown, or (3) known to contain H_2S .
- 8.0 Within 30 days after plugging work is completed, file a Sundry Notice, Subsequent Report of Abandonment (Form 3160-5), five copies, with the Field Manager, Bureau of Land Management, 6251 College Blvd., Suite A, Farmington, NM 87402. The report should show the manner in which the plugging work was carried out, the extent, by depth(s), of cement plugs placed, and the size and location, by depth(s), of casing left in the well. Show date well was plugged.
- 9.0 All permanently abandoned wells are to be marked with a permanent monument as specified in 43 CFR 3162.6(d). Unless otherwise approved.
- 10.0 If this well is located in a Specially Designated Area (SDA), compliance with the appropriate seasonal closure requirements will be necessary.

All of the above are minimum requirements. Failure to comply with the above conditions of approval may result in an assessment for noncompliance and/or a Shut-in Order being issued pursuant to 43 CFR 3163.1. You are further advised that any instructions, orders or decisions issued by the Bureau of Land Management are subject to administrative review pursuant to 43 CFR 3165.3 and appeal pursuant to 43 CFR 3165.4 and 43 CFR 4.700.

(October 2012 Revision)

BLM FLUID MINERALS P&A Geologic Report

Date Completed: 11/08/2022

Well No. Natani #010 (API# 30-04	Location	800	FNL	&	1800	FWL		
Lease No. NMNM17007		Sec. 14	T21N			R06W		
Operator M & M Production & Operation		County	Sandoval		State	New Mexico		
Total Depth 1788'	PBTD 1752'	Formation	Formation Chacra					
Elevation (GL)	Elevation (KE	3) 6928'						

Geologic Formations	Est. Top	Est. Bottom	Log Top	Log Bottom	Remarks
San Jose			Surface	236	Surface/freshwater sands
Nacimiento			236	560	Freshwater sands
Ojo Alamo Ss			560	798	Aquifer (possible freshwater)
Kirtland Shale			798	984	Possible gas
Fruitland			984	1061	Coal/Gas/Water
Pictured Cliffs Ss			1061	1107	Probable Gas
Lewis Shale			1107	1472	
Chacra			1472	PBTD	Gas
Cliff House Ss					
Menefee					
Point Lookout Ss					
Mancos Shale					
Gallup					
Greenhorn					
Graneros Shale					
Dakota Ss					
Morrison					

Remarks:

P & A

- Note: DJR Operating, LLC is plugging this well as record title owner of the lease.

- Chacra perfs 1477' – 1571'.

Reference Well:
1) Formation Tops

Same

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 157454

CONDITIONS

Operator:	OGRID:
DJR OPERATING, LLC	371838
1 Road 3263	Action Number:
Aztec, NM 87410	157454
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

CONDITIONS

Created By	Condition	Condition Date
kpickford	Notify NMOCD 24 Hours Prior to beginning operations	11/10/2022
kpickford	Adhere to BLM approved COAs and plugs. See BLM COAs and GEO report.	11/10/2022