	Po Appropriate Bistrici 10:49	State	of New Mex	tico		Form C-1831			
<u> 215111011</u> (575) 575 5151			nerals and Natural Resources		Revised July 18, 2013				
1625 N. French District II – (57	Dr., Hobbs, NM 88240 5) 748-1283				WELL API NO.	025-44267			
811 S. First St., Artesia, NM 88210 OIL CON			ERVATION		5. Indicate Type of				
<u>District III</u> – (50 1000 Rio Brazo	05) 334-6178 s Rd., Aztec, NM 87410		outh St. Francis Dr.		STATE X	FEE			
<u>District IV</u> – (5	05) 476-3460	Santa	a Fe, NM 87:	505	6. State Oil & Gas	Lease No.			
87505	ncis Dr., Santa Fe, NM								
(DO NOT LIGE		ES AND REPORTS		C D A CW TO A		Jnit Agreement Name			
	THIS FORM FOR PROPOSA ESERVOIR. USE "APPLICA	GEM 36 S	TATE COM						
PROPOSALS.) 1. Type of V	Well: Oil Well 🛛 G	8. Well Number	709H						
1. Type of Well: Oil Well					9. OGRID Number	7377			
3. Address of Operator					10. Pool name or W	Vildcat			
4 777 11 7		2267 MIDLAND, T.	X 79702		WC025 G09 S253236	6A; UPPER WOLFCAMP			
4. Well Loc		220' feet from	the SOUTH	line and11	193' feet from	the WEST line			
Sec		reet from				County LEA			
Section 36 Township 25S Range 32E NMPM County LEA 11. Elevation (Show whether DR, RKB, RT, GR, etc.)									
3347' GR									
	12 Chook An	proprieto Poy to	Indianta Na	ture of Notice	Report or Other D	loto			
	•		indicate ina		•				
DEDEOD44	NOTICE OF INT		🗆		SEQUENT REP				
		PLUG AND ABAND CHANGE PLANS	OON	REMEDIAL WOR COMMENCE DRI		LTERING CASING AND A			
		MULTIPLE COMPL	_	CASING/CEMEN					
	COMMINGLE			0,10,110,102,112,11					
	OOP SYSTEM								
OTHER:	riba proposad or complat	end aparations (Cla	orly state all p	OTHER:	d give pertinent detec	including estimated date			
of sta	arting any proposed work osed completion or recon	a). SEE RULE 19.1							
۸۱۱ ۵	RODUCTION CEASE		I DILITOI	DULL TUDING		IT			
	SE REFERENCE ATT			POLL TOBING,	COULD NOT PULL	- 11,			
THIS	WELL WILL BE PLUC	GED AND ABAI	NDONED AS	SOON AS THE	NOI TO P&A IS A	PPROVED.			
						7			
Spud Date:	01/21/2018	R	tig Release Dat	e: 04/09	/2018				
I hamahar aamtid	Sy that the information of	ove is two and som	unlata to the ha	ot of my lmoviledo	a and haliaf				
I nereby certii	Ty that the information ab	ove is true and com	iplete to the bes	st of my knowledg	e and belief.				
CICNIATUDE	Kay Maddox		erer e Redu	latory Analyst	DAT	E 11/17/2022			
SIGNATURE	, Ray Maduox		IIILE NOGU	.a.o., / maryot	DAT	E			
	name Kay Maddox	I	E-mail address: kay_maddox@eogresources.com PHONE: 432-638-8475						
For State Use									
APPROVED	вч: <u>Хели 7</u>	vitree T	TTLE Com	pliance Officer	ADATI	<u> 1/6/23</u>			
APPROVED BY: Young Formula Conditions of Approval (if any)			575-263-6633						

GEM 36 STATE COM #709H WELLWORK

ALL PRODUCTION CEASED ON THIS WELL – RIH ATTEMPTED TO CLEAN OUT THE WELLBORE, FINALLY DETERMINED THAT DRILLING MUD AND CEMENT FROM AN OFFSET WELLBORE INVADED THE WELLBORE THROUGH THE FRACTURE NETWORK AND PERFORATIONS. ATTEMPTED TO FISH TUBING FOR 3 MONTHS – DETAILS BELOW.

07/06/2021

- A workover rig attempted to pull the tubing, but it was stuck in place by the cement.
- Attempted to log free point with wireline but tools tagged at 9,288.

07/09/2021

- Slickline bailer recovered small piece of scale or cement
- Pumped 5000 gals of 15% HCL acid
- Ran free point, free at 9,310'
- Backed off pipe with string shot at 9,228' and pulled tubing out of hole.
- Screwed into fish with workstring, bumper sub, jars, intensifier, no movement, backed off, no recovery.
- Ran back in with L-80 to engage fish and prep for Coil Tubing
- Cleaned out tubing to 11,800' with 1-1/4" coil
- Ran another freepoint, 100% stuck below 9700'

07/17/2021

- Jet cut pipe at 11,176' and 10,290' but no movement
- Jet cut pipe at 9,595' and recovered 3 joints, 1 gas lift valve, and 8 joints below
- Cleanout run with bit and scraper to top of fish
- Set RBP and tested casing, casing held to 500 PSI
- Retrieved RBP and ran in hole with wash pipe

08/29/2021

- Washed over tubing from 9608'-10,052', recovering heavy cement, quit making hole
- Tripped for new shoe, continue wash/drill over tubing fish to 10,252' (next gas lift valve)
- Attempt to latch fish, no bite, ran in to dress off fish, ran back in with overshot

09/08/2021

RIH w/jet cutter, cut tubing @ 11,575',

09/09/2021

- Latch onto collar at 9598, pulled 106,000 lbs above string weight, no movement
- Ran CCL and string shot. Saw previous jet cut just below gas lift valve.
- String shot back of 10,253' at top of the gas lift valve
- Recovered 20 joints with tubing coupling
- Screwed back into fish at 10,253' with workstring
- Jet cut 11,575', perforated 11,145-11,150, cut 10,716' and perforated 10,253-10,258'
- Worked pipe, no movement
- Circulated small amount of casing to surface

- Pumped 38 bbls 15% double inhibited HCL, let sit, then flushed
- Worked pipe, no movement
- Jet cut 2' below gas lift valve @ 10,254', worked free, recovered gas lift valve and small piece of tubing
- Washed over top of fish at 10,260' to 10,294' and hit hard stop with light cement and metal shavings in returns
- POOH to inspect BHA, cracks and heavy ID gouging
- RBIH with new shoe, washed over down to 10,306' making 12 feet in 3 days
- POOH, more heavy gouging on shoe
- RIH with workstring and packer to 10,150' to test casing, casing tested good
- Made cleanout run with shoe to recover missing packer elements
- Ran in with packer to pump acid squeeze 27 bbls 10% double inhibited
- Swabbed down, no inflow
- POOH LD packer


09/21/2021

- Trip in hole with tubing and shoe to top of fish and hang tubing off to return to gas lift 10/23/2021
 - Ran in hole with GR and CCL, tagged solid at 10,288'
- Rigged up 1-1/4" coiled tubing with 2.17" bit and cleaned out to 12,000' no solids in returns 10/24/2021

RDMO, WO approved NOI to P&A

Worked on pulling tubing for 3 months, pulled as much tubing as possible, some tubing and gas lift valves were left in hole, top of fish @ 10,260'. Put well back on production, no inflow due to cement below the fish which could not be accessed.

To put the well back on production EOG would have to mill up the fish that is cemented in hole which would be extremely time consuming and costly, and then cleanout the wellbore, but even then would still not produce much oil if the perforations and fracture network is cemented up as well. The reserves remaining and probability of success are not economically justifiable.



District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 159755

CONDITIONS

Operator:	OGRID:
EOG RESOURCES INC	7377
P.O. Box 2267	Action Number:
Midland, TX 79702	159755
	Action Type:
	[C-103] Sub. Workover (C-103R)

CONDITIONS

Created By	Condition	Condition Date
kfortner	None	1/6/2023