Received by Och: Appropriate District:	17 AM State of Ne	ew Mexico		Form C-103 of
Office District I – (575) 393-6161	Energy, Minerals an			Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240	87)		WELL API NO.	
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVA	TION DIVISION	30-025	
<u>District III</u> – (505) 334-6178	1220 South S	t. Francis Dr.	5. Indicate Type of Leas	FEE 🛛
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	Santa Fe, l	6. State Oil & Gas Leas		
1220 S. St. Francis Dr., Santa Fe, NM 87505				
SUNDRY NO	TICES AND REPORTS ON V		7. Lease Name or Unit	
(DO NOT USE THIS FORM FOR PROD DIFFERENT RESERVOIR. USE "APP			Langlie Mattix Penrose	Sand Unit
PROPOSALS.)	<u></u>	,	8. Well Number	
 Type of Well: Oil Well Name of Operator 	Gas Well Other		9. OGRID Number	
	GACY RESERVES OPERATI	NG LP	240974	
3. Address of Operator			10. Pool name or Wildo	
	MITH ROAD, SUITE 3000, N	AIDLAND, TX 79705	Langlie Mattix; 7 Rvrs-0	Q-Grayburg
4. Well Location	. 1000	COUTH 1:1	((() f4 f 41	EACT 1:
Unit Letter <u>I</u> Section 21	: <u>1980</u> feet from the	SOUTH line and South	660 feet from the NMPM	EAST line County LEA
Section 21		2S Range 37E her DR, RKB, RT, GR, etc.		County LEA
	,	1' GR	,	
12. Check	Appropriate Box to Indie	cate Nature of Notice,	Report or Other Data	
NOTICE OF	INTENTION TO:	l eun	SEQUENT REPOR	T ()E.
PERFORM REMEDIAL WORK		REMEDIAL WOR		TOF. RING CASING □
TEMPORARILY ABANDON [COMMENCE DRI		
PULL OR ALTER CASING [MULTIPLE COMPL [CASING/CEMEN	T JOB 🔲	
]			
CLOSED-LOOP SYSTEM [OTHER:		OTHER:		
	npleted operations. (Clearly st		d give pertinent dates, incl	uding estimated date
of starting any proposed	work). SEE RULE 19.15.7.14			
proposed completion or i	recompletion.			
1. MIRU. Pull Injection string and	l AD-1 packer from 3195'.			
2. PUMU 6.625" AW scraper. RII	H to 3320'.			
3. PUMU 6.625" CIBP. RIH and s		G 0 TT 11 1		
4. MIRU cementers. RIH with tub 5. Circ hole with MLF and P/T ca				
6. Spot 25 sx cmt @2658'-2558'.		юсь тер.		
7. Spot 71 sx cmt @ 2488-2098'.	WOC & Tag (Transil (B-salt)/			
8. Perf & Sqz 59 sx cmt @ 1273'-			z holes)	
9. Perf & Sqz 30 sx cmt @ 300'-2 10. Spot 25 sx cmt @ 100'. (Surfa		noe)		
11. Cut off well head, verify cmt a		rker		
4" diameter 4' tall Above G	•			
		CEE ATTA	CHED CONDITIONS	
Spud Date:	Rig Rel	ease Date: OF APPRO	CHED CONDITIONS	
		0171171	5 7 7 1 1	
I hereby certify that the information	on above is true and complete t	o the best of my knowledg	e and belief.	
SIGNATURE <u>Melan</u>	<u>iis Reyes </u>	Regulatory Tech	DATE <u>0</u> 1	/23/2023
Type or print name MELAN	IE DEVES E	Idraes measure @lace	racarwas com DHONE.	122 221 6250
Type or print name <u>MELAN</u> For State Use Only	IE REYES E-mail ad	ldress: <u>mreyes@legacy</u> ı	reserves.com PHONE:	432-221-0338
	1 4			
APPROVED BY:	Tollne Title	Compliance Officer A	DATE_ 2/	/15/23
Conditions of Approval (if any):		575-263-6633		

CONDITIONS OF APPROVAL FOR PLUGGING AND ABANDONMENT OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office I (Hobbs) at (575)-263-6633 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down.

Company representative will be on location during plugging procedures.

- 1. A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.
- **2.** Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- **3.** Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private- shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- **5.** A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can +be released.
- **6.** If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
- 7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- **8.** Produced water will not be used during any part of the plugging operation.
- 9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
- **10.** All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 11. Class 'C' cement will be used above 7500 feet.
- 12. Class 'H' cement will be used below 7500 feet.
- **13.** A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- **14.** All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.
- **16.** When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
- 17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
- **18.** A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).

- 19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
- 20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
- A) Fusselman
- B) Devonian
- C) Morrow
- D) Wolfcamp
- E) Bone Springs
- F) Delaware
- G) Any salt sections
- H) Abo
- I) Glorieta
- J) Yates.
- K) Potash---(In the R-111-P Area (Potash Mine Area),

A solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.

21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing.

DRY HOLE MARKER REQ.UIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

- 1. Operator name
- 2. Lease and Well Number
- 3. API Number
- 4. Unit letter
- 5. Quarter Section (feet from the North, South, East or West)
- 6. Section, Township and Range
- 7. Plugging Date
- 8. County

SPECIAL CASES ----AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION

Page 1

Wellbore Schematic

Printed: 1/18/2023

LMPSU # 101	BOLO I	BOLO ID: 300029.10.01 AP					
LMPSU # 101, 1/18/2023	2310 FNL & 660 FEL	GL Elev. 3,361.00	KOP:				
	Section 21, Township 22S, Range	37E	EOC:				
	County, State: Lea, NM		Fill Depth:				
	Aux ID: 39520		PBTD:	3,550.00			
	'KB' correction: ; All Depths Corr	То:	TD:	3,550.00			
			BOP:				

1.000 2,000 3,000 4,000

Hole Size		
Diameter	Top At	Btm At
9.8750	0.00	1,350.00

8.2500 1,350.00 3,350.00 6.0000 3,350.00 3,636.00 Open hole. Bore size estimated.

Date Ran: 10/30/2008 Surface Casing Diameter W eight Grade Btm At Description # Length Top At 8.6250 1,350.00 Casing 1,350.00 0.00

Date Drilled

 Production Casing
 Date Ran:
 10/30/2008

 Description
 # Diameter
 W eight
 Grade
 Length
 Top At
 Btm At

 Casing
 7.0000
 3,350.00
 0.00
 3,350.00

Date Ran: 10/30/2008 **Production Liner** Diameter Description W eight Grade Length Top At Btm At 4.5000 3,308.00 3,308.00 Casing 10.50 0.00

Cement

Top At	Btm At	ID	OD	TOC Per	#-Type	#Sx	Class	Wt.
0.00	1,350.00	8.625	9.875	Circ	10	300		
0.00	3,350.00	7.000	8.250	Circ	20	200		
0.00	3,308.00	4.500	7.000	Circ	30	250		

Zone and Perfs

SEVEN RIVERS

Comments / Completion Summary

6/28/36: Shot from 3490 - 3548 with Nitro. 5/11/1938: drilled to 3636 and shot with Nitro.

11/15/1955: Frac treatment. 5/21/1971: Frac treatment.

Perforations

L	Тор	Bottom	Formation	Status	Opened	Closed	#/Ft	Ttl#
ľ	3,350.00	3,636.00	Penrose Sand					

Tubing						Date Ran:	11/26/2013
Description	#	Diameter	W eight	Grade	Length	Top At	Btm At
Tubing	98	2.3750			3,133.00	0.00	3,133.00
Tubing Anchor	1	4.5000			3.00	3,133.00	3,136.00
Tubing	5	2.3750			161.00	3,136.00	3,297.00
Tubing	2	2.3750			64.00	3,297.00	3,361.00
Seat Nipple	1	2.3750			1.00	3.361.00	3.362.00

Rods	Rods Date Ran:						
Description	#	Diameter	Rod Box	Grade	Length	Top At	Btm At
Polish Rod	1	1.2500	SH SM		26.00	0.00	26.00
Polish Rod Liner	1	1.5000			16.00	10.00	26.00
Pony Rods	2	0.8750	SH SM		8.00	26.00	34.00
Rods	31	1.0000	SH SM	FG	1,162.50	34.00	1,196.50
Rods	77	0.8750	SH SM	N90	1,925.00	1,196.50	3,121.50
Rods	8	0.7500	Full SM	N90	200.00	3,121.50	3,321.50
Rods	1	0.8750	SH SM	N90	25.00	3,321.50	3,346.50
Rods	1	0.7500	Full SM		2.00	3,346.50	3,348.50

5,000

Page 2


Wellbore Schematic

Printed: 1/18/2023

LMPSU # 101		ВО	LO ID: 300	029.10.01	API i	# 300251	0383
	Pump	1	1.5000		20.00	3,348.50	3,368.50
	2 x 1 1/2 x 20 -	- 4					



Langlie-Mattix Po	Langlie-Mattix Penrose Sand Unit #101		30-02	5-10383		
Field/Pool:	Langlie-Mattix; 7Rvrs- Queen-Grayburg	Section:	21			
County:	Lea	Township:	22S	Range:	37E	
State:	New Mexico	Location:	19	980' FSL x 66	0' FEL	Author:
Spud Date:	5/3/1936	GL:	3361'	PBTD:	3550'	J. Valdez



Description	O.D.	Weight	Тор	Depth	Hole	Cmt Sx	TOC
Surface	8.25	29	0	1350	9.875	300	Unknown- Est 0'
Production	7	20	0	3350	7.875	200 sx	0' calc
Production Inner-string	4.5	10.5	0	3308	7	350 sx	Circ'd
Open Hole	3.875" est		3350	3636	5.75/3.875	0	Open Hole

7. Cut off well head, verify cmt at surface, weld on dry hole marker.

6. Spot 25 sx cmt @ 100'. (Surface Plug)

Forma	ntion Tops:
Rustler (T-Salt)	1225'*
Transil (B-Salt)	2456'*
Yates	2624'*
7Rivers	2830'*
Queen	3394'*

* Used offset well LMPSU #522



5. Perf & Sqz 31 sx cmt @ 1400'-1175'. WOC & Tag (Rustler T-salt/ Surf Casing Shoe)

- 4. Spot 25 sx cmt @2674'-2406'. WOC & Tag (Yates/ Transil (B-salt))
- 3. Circ hole with MLF and P/T casing to 500 # witnessed by NMOCD rep.
- 2. MIRU cementers. RIH with tubing, tag CIBP, spot 25 sx. WOC & Tag-record depth.
- 1. PUMU 4.5" CIBP. RIH and set @ 3280'.

4.5" Production Inner-String @3308' (1993) 7" Production Casing @ 3350'

2.375" Tubing to 3360' with 1.5" Insert Pump

5.75"/3.875" (est) Open Hole 3350'-3636'

PBTD: 3550' TD =3636'

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

COMMENTS

Action 178360

COMMENTS

Operator:	OGRID:
LEGACY RESERVES OPERATING, LP	240974
15 Smith Road	Action Number:
Midland, TX 79705	178360
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

COMMENTS

Ī	Created By		Comment Date
	plmartinez	DATA ENTRY PM	2/16/2023

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410

Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 178360

CONDITIONS

Operator:	OGRID:
LEGACY RESERVES OPERATING, LP	240974
15 Smith Road	Action Number:
Midland, TX 79705	178360
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

CONDITIONS

Created By		Condition Date
kfortner	See attached COA	2/15/2023